

THERMITE BRAZE

NOTES:

1. CLEAN PIPE TO BRIGHT METAL.
2. THERMITE BRAZE TO BE CADWELL BY ERICO PRODUCTS OR EQUAL.
3. USE PROPER BRAZE ALLOY FOR STEEL.
4. TEST BRAZE BY PULLING ON WIRE & STRIKING BRAZE.
5. COAT BRAZE WITH ROYSTON PRIMER AND "HANDY CAP."

SPECIAL NOTE:
THERMITE BRAZE KIT
SUPPLIED BY:
FARWEST CORROSION CONTROL
GARDENA, CA.
(214) 770-6425

REGISTERED PROFESSIONAL ENGINEER
JOHN P. SULLIVAN
No. 24079
Exp. 12-31-07
CIVIL
STATE OF CALIFORNIA

APPROVED BY:				
JOHN P. SULLIVAN CITY ENGINEER			24079 RCE	08/15/06 DATE
RECOMMENDED:				
ASST. UTIL. DIRECTOR/ENG.			57875 RCE	08/14/06 DATE
REV	DESCRIPTION	BY	APP'D	DATE

CITY OF ONTARIO

THERMITE BRAZE DETAIL

STANDARD DRAWING NUMBER

4009