

NFIRS-1 Basic

Α							
36170	CA	03	16	2021	Station 2 (132)	OF2104486	0
FDID	State	Month	Day	Year	Station	Number	Exposure
^B Location Type							Census tract:
Street Address Intersection In Front Of Rear Of Adjacent To Directions US National Grid	428 Number	W-West Prefix	FRANCI Street o	IS r Highway			T-Street Suffix
			ONTARIO)		CA	91762
	Apt./Suite/R	toom	City			State	Zip Code
	ĭ						T.
	Cross Street	:					
С				E1 Dates ar	nd Times		E2 Shifts and Alarms
Incident Type 1111-Building fire				Alarm	03 16 2021	12:29	B 3 0-10
TTT-Building file				Arrival	03 16 2021	12:34	Shift or Alarms District Platoon
D				Controlled	03 17 2021	07:03	
Aid Given Or Recei	ved			Last Unit	03 20 2021	15:31	E3 Special Studies
1 Mutual Aid Rec 2 Auto. Aid Recei 3 Mutual Aid Give 4 Auto. Aid Given 5 Other Aid Given	ved Their	FDID	California Their State	Cleared			ID# Value
None	Their	Incident Num	her				

Actions Taken 11-Extinguishment by fire service personnel Primary Action Taken		G1 Resources Apparatus or Personnel Apparatus Suppression 17 EMS 5 Other 5 Resource counts include resources.	Personnel 35 12 10	Losses: Required for all fires if known. Optional for all non-fires. Property: \$ 0 Contents: \$ 0 Pre-Incident Values: Optional Property: \$ 0 Contents: \$ 0		
Completed Modules 2 - Fire 3 - Structure Fire 4 - Civilian Fire Cas. 5 - Fire Service Cas. 6 - EMS 7 - HazMat 8 - Wildland Fire 9 - Apparatus 10 - Personnel 11 - Arson	Fire Service Civilian H2 Detector Required for Condition 1 - Detector A	None reaths Injuries 2	H3 Hazardous Ma 1 - Natural G 2 - Propane G 3 - Gasoline 4 - Kerosene 5 - Diesel Fur 6 - Househol 7 - Motor Oil 8 - Paint 0 - Other None	terials Release as as 10 10 11 12 13 14 14 15 15 15 15 16 16 16 16 16 16 16 16 16 16 16 16 16	ced Use Property ot Mixed 0 - Assembly Use 0 - Education Use 3 - Medical Use 1 - Row Of Stores 3 - Enclosed Mall 8 - Business and Residential 9 - Office Use 0 - Industrial Use 3 - Military Use 5 - Farm Use 0 - Other Mixed Use	
Property Use Non- Structures 131 Church, Place of 161 Restaurant or Ca 162 Bar/Tavern or Nie 213 Elementary Scho 215 High School, Jun 241 College, Adult Ed 311 Nursing Home Hospital	Worship Ifeteria ghtclub ool, Kindegarten ior High	341 Clinic, Clinic-Type 342 Doctor/Dentist Of 361 Prison or Jail, Not 419 1- or 2-Family Dwell 439 Rooming/Boardin 449 Commerical Hotel 459 Residential, Board 464 Dormitory/Barrac 519 Food and Beverag	fice Juvenile elling ing g House or Motel J and Care ks	539 Household Goods 571 Gas or Service Sta 579 Motor Vehicle/Bo 599 Business Office 615 Electric-Generati 629 Laboratory/Scien 700 Manufacturing Pl Livestock/Poultry 882 Non-Residential F 891 Warehouse	ation oat Sales/Repairs ng Plant ice Laboratory lant y Storage (Barn)	
Outside 124 Playground or Pa 655 Crops or Orchard 669 Forest (Timberla 807 Outdoor Storage 919 Dump or Sanitary 931 Open Land or Fie 936 Vacant Lot	d nd) e Area y Landfill	938 Graded/Cared for 946 Lake, River, Stream 951 Railroad Right-of- 960 Other Street 961 Highway/Divided 962 Residential Street 981 Construction Site 984 Industrial Plant Ya	n Way Highway :/Driveway	Property Use: Description Look up and enter a Proper description only if you have Property Use box.		

(1				
Person/Entity Involved	Employee		Environmental Protection Agency	
Local Option	Person/Entity Type	В	usiness Name (if applicable)	Phone Number
MR-Mr.	Robert		Wise	
Mr., Ms., Mrs.	First Name	MI	Last Name	Suffix
Number	Prefix	Street or Highw	ay Street Type	Suffix
		Ī		-
Post Office Box	Apt./Su	ite/Room	City	
State		Z	ip Code	

Owner	Ü			
Local Option	Person/Enti	ty Type Business	s Name (if applicable)	Phone Number
L				11
Mr., Ms., Mrs.	First Name	MI	Last Name	Suffix
L				
Number	Prefix	Street or Highway	Street Type	Suffix
			JL	
Post Office Box		Apt./Suite/Room	City	
State		Zip Code	2	

Remarks:

B 1815 was dispatched as part of the first alarm assignment to a potential structure fire at the documented address. Prior to going enroute B 1815 acknowledged Ontario Dispatch traffic stating that there were multiple explosions at the location. Due to this I immediately started EOD 131 and HM 133.

B 1815 then went responding. While enroute I observed a large column of smoke in the area of the dispatched address. I broadcast this traffic and continued in code 3.

B 1815 AOS and observed fire to the front yard and to the rear of house. The structure observed was a single story single family residence with significant exposure concern to the delta side. B 1815 established Francis Command. Immediately upon establishing Francis Command, B 1815 requested that OPD shut down Francis St west of Fern and east of San Antonio. B 1815 also requested a 300' perimeter be established around 428 W. Francis St.

ME 132 AOS and Francis Command assigned him as Division A. Objectives were perimeter control and victim accountability. They were advised to engage in fire attack operations only if they felt safe in doing so.

ME 131 AOS and was assigned as a rescue group. There were report of victims on the "D" side of 428 W. Francis. This information was relayed to ME 131 and they set up for potential rescue operations.

T 1820 arrived onscene and he was assigned as division D with primary objectives of perimeter control and victim accountability. ME 136 was almost immediately assigned to help ou...

Full primary narrative can be found in NFIRS 1S - Supplemental

Date
03/23/2021
_

NFIRS-2 Fire

Α										
36	170	CA	03	16	2021		Station 2 (132)	OF2104486	0	
FDII	D	State	Month	Day	Year		Station	Number	Exposure	
) Prope	erty Details					C On-	Site Materials	O	n-Site Materials	
B1	2	Not f	Residential				Products		orage Use	
4	Estimated number origin whether or	not all unit	s became inv	olved	ilding of					
B2			ings Not Inv	volved						
В3	Number of buildin 	None		an 1 acre						
	Acres burned (out		E LESS CI	iaii i acie						
	Acres burned (out	iside Hies/								
)				E1				E3		
lgniti	ion				of Ignition			Human Fact	ors Contributing to	
D1	90-Outside area,	other	1		itentional nintentional			Check all app	licable boxes	
	Area of Fire Origin D2 Undetermined		3 - Failure of Equipment or Heat Source 4 - Act of Nature			r Heat	None 1 - Asleep 2 - Possibly impaired by alcohol or drugs			
D2										
	Heat Source				ause Under II ause Undete			3 - Unatte	ended person	
D3	88-Pyrotechnics,	explosives		Investig	gation				ly Mentally Disabled ally Disabled	
	Item First Ignited	l		F2					le Persons Involved	
D4	37-Solid chemical explosives	l, included ar	e	Factors Contributing to Ignition 18-Improper container or storage procedure			nition	7 - Age Was A Factor Estimated Age of Person Involved		
D4		=					1			
	Type of Material I	First ignited	1					Male	Female	
				Factor	Contributing t	o ignicior	1			
1 Fauir	ment Involved	In Ignition	- 1	F2	ent Power Sc	MILCO			G Fire Suppression Fac	tors
No		iii igiiicioi	'	Equipme	inc rower se	, or ce			The Suppression rac	.013
I I				∐ .					327-Explosives hazard	
∟ Equip:	ment Involved			Equipmen	t Power Sourc	:e			Fire Suppression Factor	
		I		F3						
Bran	الــــا اه	l E		Equipme	nt Portabili	ty				
Mode	el L	Į)		1 - Poi	table					
Seria	l#			2 - Sta	tionary		نبالجريم			
Year				Portable of persons.	equipment noi	rmally car	be moved by on	e or two		

H1 Mobile Property Involved 1 - Not involved in ignition, but burned 2 - Involved in ignition, but did not burn	H2 Mobile Property Type and Make Mobile Property Type	Local Use Pre-Fire Plan Available Arson Report Attached
3 - Involved in ignition and burned None	Mobile Property Make	Police Report Attached Coroner Report Attached Other Reports Attached
Mobile Property Model	Year	
State License Plate Number	VIN	

NFIRS-3 Structure Fire

I1	12	13		14
Structure Type	Building Status	Building H	eiaht	Main Floor Size
1 - Enclosed Building 2 - Portable/Mobile Structure 3 - Open Structure 4 - Air-Supported Structure 5 - Tent 6 - Open Platform 7 - Underground Structure 8 - Connective Structure 0 - Other	1 - Under Construction 2 - In Normal Use 3 - Idle, Not Routinely Used 4 - Under Major Renovation 5 - Vacant and Secured 6 - Vacant and Unsecured 7 - Being Demolished 0 - Other U - Undetermined	Number of Stories At/Above Grade 0 Number of Stories Below Grade		Total Square Feet OR BY Length (ft) X Width (ft)
J1	J3		К	
Fire Origin 1 Below Grade Story of Fire Origin J2 Fire Spread Confined to Object of Origin 2 - Confined to Room of Origin 3 - Confined to Floor of Origin 4 - Confined to Building of Origin 5 - Beyond Building of Origin	Number of Stories W/Minor Da Number of Stories w/Minor Da Number of Stories w/Significal Number of Stories w/Heavy Da Number of Stories w/Extreme *Count the roof as part of the highest	mage (1-24%) nt Damage (25-49%) nmage (50-74%) Damage (75-100%)	K1 LI Iter to F K2 LI Typ	Material Contributing Flame Spread In Contributing Most Flame Spread The of Material Contributing St To Flame Spread
	T.	1		
L1 Presence of Detectors	L3 Detector Power Supply	L5 Detector Effect	ivonoss	
N - None Present 1 - Present U - Undetermined	1 - Battery Only 2 - Hardwire Only 3 - Plug-In 4 - Hardwire With Battery 5 - Plug-In With Battery 9 6 - Mechanical 7 - Multiple Detectors	1 - Alerted Oc	cupants, O cupants, O e No Occup lert Occupa	
L2	& Power Supplies	L6		
Detector Type	0 - Other U - Undetermined	Detector Failure	e Reason	
 1 - Smoke 2 - Heat 3 - Combination of Smoke and Heat 4 - Sprinkler, Water Flow Detection 5 - More Than One Type Present 0 - Other U - Undetermined 	L4 Detector Operation 1 - Fire Too Small To Activate 2 - Operated 3 - Failed To Operate U - Undetermined		nstallation intenance, ssing or Dis scharged o	sconnected

M1	M3	M5
Presence of Automatic Extinguishing System	Operation of Automatic Extinguishing System	Reason for Automatic Extinguishing System Failure
N - None Present 1 - Present 2 - Partial System Present U - Undetermined	1 - Operated/Effective 2 - Operated/Not Effective 3 - Fire Too Small To Activate 4 - Failed To Operate 10 - Other 1 - U - Undetermined Required if fire was within designed	1 - System Shut Off 2 - Not Enough Agent Discharged 3 - Agent Discharged But Did Not Reach Fire 4 - Wrong Type of System 5 - Fire Not In Area Protected 6 - System Components Damaged 7 - Lack of Maintenance 8 - Manual Intervention
Type of Automatic Extinguishing System 1 - Wet-Pipe Sprinkler	range	0 - Other U - Undetermined Required if system failed or not effective
2 - Dry-Pipe Sprinkler 3 - Other Sprinkler System 4 - Dry Chemical System 5 - Foam System 6 - Halogen-Type System 7 - Carbon Dioxide System 0 - Other U - Undetermined Required if fire was within designed range of AES	M4 Number of Sprinkler Heads Operating Required if system operated	

NFIRS-5 Fire Service Casualty (1 of 2)

	I INS STITE SCIVICE COS	2010) (1 01 L)
A 36170 CA FDID State	03 16 2021 State (13 Month Day Year State	
B Injured Person Male Fen First Name MI	nale Career Volunteer SSN:	C Casualty Number
Age or Date Of Birth OR Date of I	Date and Time of Injury 03	F Responses 15:05 Number of prior responses during past 24 hours
G Usual Assignment 1 - Suppression 2 - EMS 3 - Prevention 4 - Training 5 - Maintenance 6 - Communications 7 - Administration 8 - Fire Investigation 0 - Other	G2 Physical Condition Just Prior To Injury 1 - Rested 2 - Fatigued 4 - Ill or Injured 0 - Other U - Undetermined G3 Severity	G4 Taken To 1 - Hospital 4 - Doctor's Office 5 - Morgue/Funeral Home 6 - Residence 7 - Station or Quarters 0 - Other Not Transported
o- otilei	1 - Report only, including exposure 2 - First aid only 3 - Treated by physician (no lost time) 4 - Moderate (lost time) 5 - Severe (lost time) 6 - Life threatening (lost time) 7 - Death	G5 Activity At Time Of Injury 40-Suppression support, other Activity At Time Of Injury
H1 Primary Apparent Symptom 98-Pain only Primary Apparent Symptom	Cause of Firefighter Injury 1-Fall Cause of Injury	Object Involved In Injury Object Involved In Injury
H2 Primary Part of Body Injured 64-Wrist Primary Injured Body Part	Factor Contributing to Injury 50-Slippery or uneven surfaces, other Contributing Factor	

J1	J3	J4
Where injury Occurred	Specific Location Where Injury Occurred	Vehicle Type
1 - En route to FD location 2 - At FD location 3 - En route to incident scene 4 - En route to medical facility 5 - At scene in structure 6 - At scene outside 7 - At medical facility 8 - Returning from incident 9 - Returning from med facility 0 - Other U - Undetermined	65 - In Aircraft 64 - In boat, ship, or barge 63 - In rail vehicle 61 - In motor vehicle 54 - In sewer 53 - In tunnel 49 - In structure 45 - In attic 36 - In water 35 - In ravine 33 - In quarry or mine 32 - In ditch or trench	1 - Suppression Vehicle 2 - EMS Vehicle 3 - Other FD Vehicle 4 - Non-FD Vehicle None
J2 Story Where Injury Occurred 1 - 1 - Injury Occurred Inside or On Structure 2 - Injury Occurred Outside	31 - In dictn or trench 31 - In open pit 28 - On steep grade 27 - On fire escape/outside stairs 26 - On vertical surface or ledge 25 - On ground ladder 24 - On aerial ladder or in basket 23 - On roof 22 - Outside at grade 00 - Other UU - Undetermined	Remarks Left wrist pain due to a fall, no treatment required.

K1			
Did protective equipment fail and contribute to the injury?	Yes No		

NFIRS-5 Fire Service Casualty (2 of 2)

A 36170 CA	03 16 2021		04486
FDID State	Month Day Year	Station Numbe	er Exposure
B Injured Person Male Fem	nale Career Volunteer SS Last Name	sn: ∐ ∐ Suffix	C Casualty Number
D Age or Date Of Birth OR Age Date of E	E Date and Time of I 03 20 Month Day	Injury 2021 06:00 Year Time	F Responses Number of prior responses during past 24 hours
G Usual Assignment 1 - Suppression 2 - EMS 3 - Prevention 4 - Training 5 - Maintenance 6 - Communications 7 - Administration 8 - Fire Investigation 0 - Other	G2 Physical Condition Just Prior To 1 - Rested 2 - Fatigued 4 - Ill or Injured 0 - Other U - Undetermined G3 Severity 1 - Report only, including export 2 - First aid only 3 - Treated by physician (no lost 4 - Moderate (lost time) 5 - Severe (lost time) 6 - Life threatening (lost time) 7 - Death	osure G5 st time) A	aken To 1 - Hospital 4 - Doctor's Office 5 - Morgue/Funeral Home 6 - Residence 7 - Station or Quarters 0 - Other Not Transported
H1 Primary Apparent Symptom Primary Apparent Symptom H2 Primary Part of Body Injured Primary Injured Body Part	I1 Cause of Firefighter Cause of Injury I2 Factor Contributing Contributing Factor	[Object Involved In Injury Object Involved In Injury

J1 Where Injury Occurred	J3 Specific Location Where Injury Occurred	J4 Vehicle Type
1 - En route to FD location 2 - At FD location 3 - En route to incident scene 4 - En route to medical facility 5 - At scene in structure 6 - At scene outside 7 - At medical facility 8 - Returning from incident 9 - Returning from med facility 0 - Other U - Undetermined	65 - In Aircraft 64 - In boat, ship, or barge 63 - In rail vehicle 61 - In motor vehicle 54 - In sewer 53 - In tunnel 49 - In structure 45 - In attic 36 - In water 35 - In water 33 - In ravine 33 - In quarry or mine 32 - In ditch or trench 31 - In open pit 28 - On steep grade	1 - Suppression Vehicle 2 - EMS Vehicle 3 - Other FD Vehicle 4 - Non-FD Vehicle None
J2 Story Where Injury Occurred 1 - Injury Occurred Inside or On Structure 2 - Injury Occurred Outside	27 - On fire escape/outside stairs 26 - On vertical surface or ledge 25 - On ground ladder 24 - On aerial ladder or in basket 23 - On roof 22 - Outside at grade 00 - Other UU - Undetermined	

K1	
Did protective equipment fail and contribute to the injury?	Yes No

NFIRS-9 Apparatus or Resources

Α							
36170	CA	03	16	2021	Station 2 (132)	OF2104486	0
FDID	State	Month	Day	Year	Station	Number	Exposure

B Apparatus/Resource	Dates/Times		mber People Apparatus Use	Actions Taken
ID: B1806	Dispatch: 03/16/2021 12:42	Sent 1	Suppression	81-Incident command
Type: 92-Chief officer car	Arrival: 03/16/2021 12:54		Other	
,	Clear: 03/16/2021 15:23			
ID: B1807	Dispatch: 03/16/2021 13:02	Sent 1	Suppression	Ц
Type: 92-Chief officer car	Arrival:		Other	
	Clear: 03/18/2021 02:52			
ID: B1808	Dispatch: 03/16/2021 19:12	Sent 0	Suppression EMS	
Type: 92-Chief officer car	Arrival:		Other	
	Clear: 03/18/2021 02:51			
ID: B1811	Dispatch: 03/16/2021 19:36	Sent 0	Suppression EMS	
Type: 92-Chief officer car	Arrival:		Other	
	Clear: 03/17/2021 14:19			
ID: B1815	Dispatch: 03/16/2021 12:30	Sent 1	Suppression	
Type: 92-Chief officer car	Arrival: 03/16/2021 12:36		Other	
	Clear: 03/17/2021 01:41			
ID: B1825	Dispatch: 03/16/2021 12:32	Sent 1	Suppression EMS	П
Type: 92-Chief officer car	Arrival: 03/16/2021 12:40		Other	
	Clear: 03/16/2021 19:13			
ID: C1842	Dispatch: 03/16/2021 14:06	Sent 0	Suppression	Ш
Type: 60-Support apparatus, other	Arrival: 03/16/2021 14:06		Other	
	Clear: 03/16/2021 17:43			
ID; D1802	Dispatch: 03/16/2021 13:11	Sent 0	Suppression	Ц
Type: 92-Chief officer car	Arrival: 03/16/2021 13:11	_	EMS Other	
	Clear: 03/16/2021 14:26			
ID: D1803	Dispatch: 03/16/2021 12:44	Sent 0	Suppression	Ш
Type: 92-Chief officer car	Arrival:		EMS Other	
	Clear: 03/16/2021 14:26			
ID: ED131	Dispatch: 03/16/2021 12:31	Sent 8	Suppression	45-Remove hazard
Type: 00-Other apparatus/resource	Arrival: 03/19/2021 23:41		EMS Other	
, , , , , , , , , , , , , , , , , , ,	Clear: 03/20/2021 15:31			
ID: HM133	Dispatch: 03/16/2021 13:09	Sent 0	Suppression	
Type: 93-HazMat unit	Arrival:	_	Other	
	Clear:			

	03/20/2021	14:52		
Type: 60-Support apparatus, other	Dispatch: 03/16/2021 Arrival: 03/16/2021 Clear: 03/17/2021	12:30 Sent 1 1 12:36 17:58	Suppression EMS Other	86-Investigate
ID: ME131 Type: 11-Engine	Dispatch: 03/16/2021 Arrival: 03/16/2021 Clear: 03/16/2021	12:30 Sent 4 12:36 15:09	Suppression EMS Other	
ID: ME132 Type: 11-Engine	Dispatch: 03/16/2021 Arrival: 03/16/2021 Clear: 03/19/2021	12:30 Sent 4 12:34 15:43	Suppression EMS Other	
ID: ME134 Type: 11-Engine	Dispatch: 03/16/2021 Arrival: 03/16/2021 Clear: 03/16/2021	12:42 Sent 4 12:47 14:43	Suppression EMS Other	
ID: ME135 Type: 11-Engine	Dispatch: 03/16/2021 Arrival: 03/16/2021 Clear: 03/16/2021	12:42 Sent 4 12:53 14:47	Suppression EMS Other	
ID: ME136 Type: 11-Engine	Dispatch: 03/16/2021 Arrival: 03/16/2021 Clear: 03/17/2021	12:30 Sent 4 12:42 21:11	Suppression EMS Other	11-Extinguishment by fire service personne
ID: ME137 Type: 11-Engine	Dispatch: 03/16/2021 Arrival: 03/16/2021 Clear: 03/16/2021	13:09 Sent 4 13:20 14:15	Suppression EMS Other	
ID: ME138 Type: 11-Engine	Dispatch: 03/16/2021 Arrival: 03/16/2021 Clear: 03/16/2021	13:08 Sent 4 13:11 15:16	Suppression EMS Other	
ID: ME139 Type: 11-Engine	Dispatch: 03/16/2021 Arrival: 03/16/2021 Clear: 03/16/2021	12:42 Sent 4 12:54 22:13	Suppression EMS Other	
ID: ME141 Type: 11-Engine	Dispatch: 03/16/2021 Arrival:	22:31 Sent 0	Suppression EMS Other	
ID: ME67	Dispatch: 03/16/2021 Arrival: 03/16/2021	13:28 Sent 0	Suppression EMS Other	33-Provide advanced life support (ALS) 11-Extinguishment by fire service personne

	Clear: 03/16/2021 23:41	
ID: T131	Dispatch: 03/16/2021 12:30 Sent 4	Suppression L
Type: 12-Truck or aerial	Arrival: 03/16/2021 12:38	Other
	Clear: 03/16/2021 22:02	
ID: T138	Dispatch: 03/16/2021 12:42 Sent 4	Suppression L EMS
Type: 12-Truck or aerial	Arrival:	Other
	Clear: 03/16/2021 12:44	
ID: T139	Dispatch: 03/16/2021 12:43 Sent 4	Suppression L EMS
Type: 12-Truck or aerial	Arrival:	Other
	Clear: 03/16/2021 20:05	
ID: T1820	Dispatch: 03/16/2021 12:37 Sent 0	Suppression L EMS
Type: 60-Support apparatus, other	Arrival: 03/16/2021 12:37	Other
	Clear: 03/18/2021 13:36	
ID: T1822	Dispatch: 03/16/2021 12:51 Sent 0	Suppression L
Type: 60-Support apparatus, other	Arrival:	Other
	Clear: 03/16/2021 23:41	

NFIRS-10 Personnel

Α								
	36170	CA	03	16	2021	Station 2 (132)	OF2104486	0
	FDID	State	Month	Day	Year	Station	Number	Exposure

B Apparatus/Resource	Dates/Times	Sent	Number of People	Apparatus Use	Actions Taken
ID: B1806 Type: 92-Chief officer car	Dispatch: 03/16/2021 12:42 Arrival: 03/16/2021 12:54 Clear: 03/16/2021 15:23	Sent	1	Suppression EMS Other	81-Incident command
Personnel ID	Name	Rank	Role	Attend	Actions Taken
17111	Roeber, Scotland	Battalion Chief			81-Incident command
ID: B1807 Type: 92-Chief officer car	Dispatch: 03/16/2021 13:02 Arrival:	Sent	1	Suppression EMS Other	
Personnel ID	Name	Rank	Role	Attend	Actions Taken
16923	Lewis, Ryan	Battalion Chief			Ш
ID: B1808 Type: 92-Chief officer car	Dispatch: 03/16/2021 19:12 Arrival:	Sent	0	Suppression EMS Other	
Personnel ID	Name	Rank	Role	Attend	Actions Taken
ID: B1811 Type: 92-Chief officer car	Dispatch: 03/16/2021 19:36 Arrival:	Sent	0	Suppression EMS Other	
Personnel ID	Name	Rank	Role	Attend	Actions Taken
ID: B1815 Type: 92-Chief officer car	Dispatch: 03/16/2021 12:30 Arrival: 03/16/2021 12:36 Clear: 03/17/2021 01:41	Sent	1	Suppression EMS Other	
Personnel ID	Name	Rank	Role	Attend	Actions Taken
18726	Williams, Ryan	Battalion Chief		n	П
ID: B1825 Type: 92-Chief officer car	Dispatch: 03/16/2021 12:32 Arrival: 03/16/2021 12:40 Clear: 03/16/2021 19:13	Sent	1	Suppression EMS Other	
Personnel ID	Name	Rank	Role	Attend	Actions Taken
18006	Stepanian, Nicolas	Battalion Chief			Ш
ID: C1842 Type: 60-Support apparatus, other	Dispatch: 03/16/2021 14:06 Arrival: 03/16/2021 14:06 Clear: 03/16/2021 17:43	Sent	0	Suppression EMS Other	Ц
Descend ID	Name	Pank	Polo	Attand	Astions Taken

reisonnet in	Ranie	r.diik	KULE	Accend	ACTIONS (BREI)
Type: 92-Chief officer car	Dispatch: 03/16/2021 13:11 Arrival: 03/16/2021 13:11 Clear: 03/16/2021 14:26	Sent	0	Suppression EMS Other	
December 11D		Dank	Dala	Attand	Astions Taken
Personnel ID	Name	Rank	Role	Attend	Actions Taken
ID: D1803 Type: 92-Chief officer car	Dispatch: 03/16/2021 12:44 Arrival:	Sent	0	Suppression EMS Other	
Personnel ID	Name	Rank	Role	Attend	Actions Taken
ID: ED131 Type: 00-Other apparatus/resource	Dispatch: 03/16/2021 12:31 ce Arrival: 03/19/2021 23:41 Clear: 03/20/2021 15:31	Sent	8	Suppression EMS Other	45-Remove hazard
Personnel ID	Name	Rank	Role	Attend	Actions Taken
18343	Goyette, Matthew	Fire Captain			
19273	Lambert, Darrell	Fire Captain			
19228	Langevin, Steve	Fire Engineer		Ч	Ц
16923	Lewis, Ryan	Battalion Chief			Ц
19226	Ryan, Jacob	Fire Captain			
19425	Trapani, Geoffrey	Fire Investigation Supervisor			
18724	Verkaik, Eugene	Fire Captain			
18466	Wedell, Michael	Battalion Chief			
ID: HM133 Type: 93-HazMat unit	Dispatch: 03/16/2021 13:09 Arrival:	Sent	0	Suppression EMS Other	Ц
Personnel ID	Name	Rank	Role	Attend	Actions Taken
ID: [11850] Type: 60-Support apparatus, other	Dispatch: 03/16/2021 12:30 Arrival: 03/16/2021 12:36 Clear: 03/17/2021 17:58	Sent	1	_ Suppression EMS Other	86-Investigate
Personnel ID	Name	Rank	Role	Attend	Actions Taken
18721	Kloosterman, Daniel	Fire Investigation Supervisor			
ID: ME131 Type: 11-Engine	Dispatch: 03/16/2021 12:30 Arrival: 03/16/2021 12:36	Sent	4	Suppression EMS Other	Ц

•	Clear: 03/16/2021 15:09				
Personnel ID	Name	Rank	Role	Attend	Actions Taken
20025	Bandaruk, Jason	Firefighter			Ц
20192	Wilson, Duncan	Firefighter			
19140	Hafner, Ryan	Fire Captain		4	Ц
19344	Preston, Bryan	Fire Engineer			
ID: ME132 Type: 11-Engine	Dispatch: 03/16/2021 12:30 Arrival: 03/16/2021 12:34 Clear: 03/19/2021 15:43	Sent	4	Suppression EMS Other	
Personnel ID	Name	Rank	Role	Attend	Actions Taken
20183	Clements, Cody	Firefighter			
19687	Thompson, Matthew	Fire Engineer			
19223	Gilbert, Ryan	Fire Captain			
20190	Saunders, Kurt	Firefighter			
ID: ME134 Type: 11-Engine	Dispatch: 03/16/2021 12:42 Arrival: 03/16/2021 12:47 Clear: 03/16/2021 14:43	Sent	4	Suppression EMS Other	
Personnel ID	Name	Rank	Role	Attend	Actions Taken
20205	Okamura, Thomas	Firefighter	2		: <u> </u>
20201	Steele, Matthew	Firefighter			
19227	Willemse, Scott	Fire Captain			
19422	Cavanaugh, Sean	Fire Engineer			Ц
ID: ME135 Type: 11-Engine	Dispatch: 03/16/2021 12:42 Arrival: 03/16/2021 12:53 Clear: 03/16/2021 14:47	Sent	4	Suppression EMS Other	
Personnel ID	Name	Rank	Role	Attend	Actions Taken
19881	Ciszek, Brian				
20199	Hoover, Lucas	Firefighter		1	
17357	Bekins, Kurt	Fire Captain			
19857	Zaragoza, Eric				Ш
ID: ME136 Type: 11-Engine	Dispatch: 03/16/2021 12:30 Arrival: 03/16/2021 12:42 Clear: 03/17/2021 21:11	Sent	4	Suppression EMS Other	11-Extinguishment by fire service per
Personnel ID	Name	Rank	Role	Attend	Actions Taken
					1 1

19798	Mowad, Trevor				Ц
20327	Magrina, Joel	Firefighter		To the second	
20185	Medina, Jacob	Firefighter		П	-U
16864	Spellman, Ronald	Fire Captain			Ш
ID: ME137 Type: 11-Engine	Dispatch: 03/16/2021 13:09 Arrival: 03/16/2021 13:20 Clear: 03/16/2021 14:15	Sent	4	Suppression EMS Other	
Personnel ID	Name	Rank	Role	Attend	Actions Taken
20194	Esquivias, Jovanny	Firefighter			
19680	Garrett, Chad	Fire Engineer		Ш	Ш
17233	De Young, Daniel	Fire Captain			
20321	Armstrong, Joshua	Firefighter			
ID: ME138 Type: 11-Engine	Dispatch: 03/16/2021 13:08 Arrival: 03/16/2021 13:11 Clear: 03/16/2021 15:16	Sent	4	Suppression EMS Other	Ц
Personnel ID	Name	Rank	Role	Attend	Actions Taken
19807	Clarke, Christian				Ш
16895	Nelson, Tye	Fire Captain			Ц
20316	Hernandez, Michael	Firefighter			
20202	Powers, Brian	Firefighter			Ц
ID: ME139 Type: 11-Engine	Dispatch: 03/16/2021 12:42 Arrival: 03/16/2021 12:54 Clear: 03/16/2021 22:13	Sent	4	Suppression EMS Other	Ц
Personnel ID	Name	Rank	Role	Attend	Actions Taken
20334	Verral, Eric	Firefighter			
20184	Selk, Chase	Firefighter			
19686	Talley, Steven	Fire Engineer		4	Ц
18902	Bethel, Richard	Fire Captain		I	Ш
ID: ME141 Type: 11-Engine	Dispatch: 03/16/2021 22:31 Arrival:	Sent	0	i Suppression EMS Other	
Personnel ID	Name	Rank	Role	Attend	Actions Taken
ID: ME67 Type:	Dispatch: 03/16/2021 13:28 Arrival: 03/16/2021 13:28	Sent	0	Suppression EMS Other	33-Provide advanced life support (ALS) 11-Extinguishment by fire service pers

†	Cledi. (V3/10/2021) [23.41]				
Personnel ID	Name	Rank	Role	Attend	Actions Taken
Type: 12-Truck or aerial	Dispatch: 03/16/2021 12:30 Arrival: 03/16/2021 12:38 Clear: 03/16/2021 22:02	Sent	4	Suppression EMS Other	Ц
Personnel ID	Name	Rank	Role	 Attend	Actions Taken
20326	Jaquess, Tyler	Firefighter		L	
19228	Langevin, Steve	Fire Engineer		Ħ	Ц
18724	Verkaik, Eugene	Fire Captain		Ц	Ц
20032	Gamboa, Neil	Firefighter		F	
ID: T138 Type: 12-Truck or aerial	Dispatch: 03/16/2021 12:42 Arrival:	Sent Sent	4	Suppression EMS Other	Ц
Personnel ID	Name	Rank	Role	Attend	Actions Taken
19885	Morrison, Christopher				Ц
20029	Harper, Martin	Firefighter			Ш
18980	Van Fossen, Brian	Fire Captain			
19508	Bates, Logan	Fire Engineer			Ц
Type: 12-Truck or aerial	Dispatch: 03/16/2021 12:43 Arrival:	Sent	4	Suppression EMS Other	Ц
Personnel ID	Name	Rank	Role	Attend	Actions Taken
19880	DeMartino, Noah				
20214	Norbryhn, Scott	Firefighter			
19679	Charleston, David	Firefighter		Ц	
17102	Guapo, Louis	Fire Captain		Ш	Ц
Type: 60-Support apparatus, other	Dispatch: 03/16/2021 12:37 Arrival: 03/16/2021 12:37 Clear: 03/18/2021 13:36	Sent	0	Suppression EMS Other	Ц
Personnel ID	Name	Rank	Role	Attend	Actions Taken
ID: T1822 Type: 60-Support apparatus, other	Dispatch: 03/16/2021 12:51 Arrival:	Sent	0	Suppression EMS Other	Ц
Personnel ID	Name	Rank	Role	Attend	Actions Taken

NFIRS-1S Supplemental

Α								
	36170	CA	03	16	2021	Station 2 (132)	OF2104486	0
	FDID	State	Month	Day	Year	Station	Number	Exposure

Primary Narrative:

B 1815 was dispatched as part of the first alarm assignment to a potential structure fire at the documented address. Prior to going enroute B 1815 acknowledged Ontario Dispatch traffic stating that there were multiple explosions at the location. Due to this I immediately started EOD 131 and HM 133.

B 1815 then went responding. While enroute I observed a large column of smoke in the area of the dispatched address. I broadcast this traffic and continued in code 3.

B 1815 AOS and observed fire to the front yard and to the rear of house. The structure observed was a single story single family residence with significant exposure concern to the delta side. B 1815 established Francis Command. Immediately upon establishing Francis Command, B 1815 requested that OPD shut down Francis St west of Fern and east of San Antonio. B 1815 also requested a 300' perimeter be established around 428 W. Francis St.

ME 132 AOS and Francis Command assigned him as Division A. Objectives were perimeter control and victim accountability. They were advised to engage in fire attack operations only if they felt safe in doing so.

ME 131 AOS and was assigned as a rescue group. There were report of victims on the "D" side of 428 W. Francis. This information was relayed to ME 131 and they set up for potential rescue operations.

T 1820 arrived onscene and he was assigned as division D with primary objectives of perimeter control and victim accountability. ME 136 was almost immediately assigned to help out division D.

T 131 AOS and due to unit specialty their crew was split. Captain Verkaik and Engineer Langevin were assigned to the EOD group and FF Jaquess and FF Gamboa were assigned underneath division A to assist with their operation.

ME 134 was assigned as division B. Their objectives were to establish perimeter control and provide victim accountability.

ME 139 AOS and they were assigned as division D. Their objectives were to establish perimeter control and provide victim accountability.

During the course of assigning units to their divisional assignments a large explosion occurred. This explosion resulted in an operational retreat of all divisions. A PAR was performed and all firefighters were accounted for. No injuries were noted due to the explosion.

Fire suppression activities resumed after the explosion with safety measures applied. Large diameter hoselines were used from a safe distance and defensive operations were enacted.

The fire was extinguished at the documented time. Operations then transitioned into a multi day investigation operation led by Ontario FD EOD 131 and I 1850. Please reference their report for additional information in regards to their operations.

Multiple families were displaced as a result of this incident. Red Cross was used as the primary resource for sheltering measures.

Ultimately on Saturday March 20, 2021 late afternoon the Francis Incident was terminated and all Ontario Fire Department operations were complete.

R. Williams Fire Battalion Chief Battalion 1-B

Person/Entity Involved		Employee		South Coast Air Quality Management District	
Local Option		Person/Entity Type		Business Name (if applicable)	Phone Number
	Kamal			Brenner	
Mr., Ms., Mrs.	First Name		Mi	Last Name	Suffix
Number	Prefix	Street or Highway		Street Type	Suffix
Post Office Box		Apt./	Suite/Room	City	
State		Zip Code			

Additional Narrative (#1 of 18):

ME 138 was dispatched to the above address to assist units on scene of a structure/outdoor fire. We were assigned to Division "D" with our access point being off of Fern Avenue.

We made face-to-face contact with Division "D" and we were assigned to deploy a hose line and to attack the fire in the main house (defensively) and to extinguish other hotspots in the area.

We observed a deceased victim near the area that we were working in and notified Division "D".

Upon completion of our assignment we were released. ME 138 personnel deconned at our unit and left our hose bundle, gated wye, and nozzle at the scene as ordered by EOD 131 personnel.

ME 138 cleared the scene and returned to our first-in district without any injuries.

T. W. Nelson ME 138 "B"

Additional Narrative (#2 of 18):

ME135 responded as part of a Second Alarm to the documented location for a reported structure fire with multiple explosions at the location. ME135 arrived on scene and was assigned to Division D by Francis Command.

ME135 made contact with Division D was was assigned to Exposure Control on Division D. ME135 utilized multiple hose lines off of ME136 to protect exposures and extinguish any active fire found.

Once the scene was turned over to EOD for further investigation ME135 was released from the scene and returned.

There were no injuries or damaged equipment reported at the time of this report.

ΚB

Additional Narrative (#3 of 18):

ME 131 RESPONDED TO THE INCIDENT ON THE INITIAL ALARM. ME 131 WAS ASSIGNED RESCUE GROUP. AS RESCUE GROUP WE ASSISTED DIVISION A AND DIVISION B IN PRIMARY SEARCHES. PRIMARY SEARCHES WERE CONDUCTED AT THE FOLLOWING FRANCIS ADDRESSES: 432, 426, 428, 424 AND 416. AS RESCUE GROUP WE DISCOVERED 2 DECEASED VICTIMS IN DIVISION AT THE REAR OF 428 W FRANCIS.

RESCUE GROUP ALSO ASSISTED IN FREEING A TRAPPED HORSE TO THE REAR OF DIVISION A, AT 428 W FRANCIS.

ME 131 WAS RELEASED FROM THE INCIDENT AND RETURNED TO FULL SERVICE. HAFNER

Additional Narrative (#4 of 18):

ME134 was dispatched as part of the second alarm to a structure fire at reported address with multiple reported explosions. ME134 aos and was assigned to Division B by Francis Command with primary objective of exposure protection.

ME134 secured a 4" supply line and made access to the rear of 432 W. Francis with a 1 ¾" preconnect. While providing exposure protection we found severe damage to the residence and multiple small structures at 432 W. Francis. ME134 performed a Primary Search on all the structures on the property of 432 W. Francis which were all clear. ME134 was released from the incident without incidence.

Scott Willemse Fire Captain ME134-B

Additional Narrative (#5 of 18):

ME139 was assigned to the Francis incident. ME139 arrived on scene and did a face to face with Francis Operations. Operations assigned ME139 to DIV C.

ME139 moved to the north side of the incident on West Maple. ME139 pulled 500' of 1 3/4 to start our attack on DIV C. While we were pulling the hose we came across rescue group trying to free a horse that was trapped between a block wall and a tree. ME139 used our hose line to knock down the fire that was moving toward the horse. The horse was freed and ME139 continued to knock down spot fires.

DIV C was then assigned to assist the human society with retrieving the two horse that were near the fires. Both horse were taken by the human society and they cleared our DIV.

An operation retreat was given and DIV C fell back to ME139 that was on Maple. Operations then assigned DIV C to do a primary and secondary search on the following addresses; 415, 427, 431, 439, and 445 West Maple. ME67 was assigned to DIV C and assisted in searching the homes. DIV C gave a primary and secondary all clear on all of the homes. ME67 then cleared DIV C.

DIV C was then assigned to a medical aid at Fern and Maple, see attached EMS report.

DIV C staged at our engine for the next few hours while observing and updating fire activity to operations.

DIV C then walked over to DIV D to assisted with fire attack on DIV D. ME139 assisted DIV D with structure protection off of Fern. 50" of 1 3/4" off ME139 was left on DIV D.

At 2200hrs, DIV C gave Fire Branch and situation report for our DIV. DIV C advised Fire Branch that we were comfortable leaving the DIV unstaffed at night due to the lack of fire activity and being unable to reach anything in our DIV from the safety of our engine. ME139 loaded up our hose off the DIV and was released from the Francis Incident.

R. Bethel ME139B

Additional Narrative (#6 of 18):

ME 132 was dispatched to the incident and was initially given the location of the 400 block of Maple. ME 132 heard multiple explosions prior to departing the station. As ME 132 left the station, we saw a large column of smoke to the east.

Enroute, ME 132 notified 1815 best access was off Francis.

ME 132 was assigned to Division A with primary objectives rescue and fire attack. ME 132 utilized 1 ¾" handlines (2 lines) to fight the fire defensively from the Alpha/Bravo perimeter. ME 132 was attempting to protect the 2 homes located @ 426 W. Francis (Exposure #1). ME 132 was unable to make access to 428 W. Francis due to multiple explosions at the location.

EOD personnel arrived on scene and advised Division A to remain on Francis and not access the property. ME 132 continued the defensive firefighting operation by utilizing a master stream (defending Exposure #2).

At 2230 HRS, ME 141 relieved ME 132 as Division A. ME 132 returned to quarters in full service.

R. Gilbert ME 132-B

Additional Narrative (#7 of 18):

Truck 139 was assigned to this incident as part of the second alarm assignment. The call was for an explosion with fire and fire victims.

We arrived on scene from the North East and staged at Maple and Fern. We were assigned to Rapid Intervention and staged the truck on Fern between Francis and Maple. There were active explosions and fire activity at scene.

We assembled tools and equipment to effect the assignment given and transitioned on foot to the Alpha side of the incident. We were to Face to Face with Francis Operations.

We were given the objectives to evaluate the incident for needs as the RIC group and report back to OPS. After assessment the objectives determined were to support the incident with rapid medical support and evacuation if there were any injuries on the fire line. We established a cache of ALS medical gear, saws and a SKED on the Alpha side of the fire. No fire injuries occurred during this assignment.

We assisted and directed SoCal Edison to cut the power to the buildings in involved in the fire incident.

We were later reassigned to raised the aerial ladder of T139 to provide an elevated angle for photos for Investigation 1850. That never occurred. We provided support on the East side of the fire.

We were released from the incident at 1930 Hrs and relocated to station 133 for air bottle filling.

Fire Captain L.P. Guapo

Additional Narrative (#8 of 18):

ME136 responded as part of a commercial fire alarm in station#132's first in area. In route, there were reports of possible explosions.

ME136 was assigned to Div. Delta(Capt. Brown). ME136 on Fern St., North of Francis. ME136 personnel deployed a 2.5

inch line supplying two 1.75 hose bundles. A operational retreat was called and ME136 personnel returned to the unit. Operations were switched to a Defensive mode and several ground monitor operations were utilized form Fern St.

At approximately 19:00 hrs. I was put in charge of Div. Delta. Ground monitor operations continued intermittently for exposure protection. Several pets were found and turned over the Humane Society volunteers.

ME136 was released from the incident at 22:00 hrs.

R.D. Spellman Capt.

Additional Narrative (#9 of 18):

ME141 was assigned to assist bomb members with hose lines during the final stages of the operation. ME141 remained on scene until released by BC Lewis at 14:40. ME141 was returned to full operation at Station 2. Captain Tom Pacheco ME141

Additional Narrative (#10 of 18):

Bomb Squad/EOD 131

EOD 131 was requested by B1815 during the initial dispatch of this incident due to the call notes from Fire Dispatch.

Responding in from home/off-duty I requested a full recall of all EOD Team members. Within approximately two hours of the initial dispatch all EOD Team members arrived onscene.

EOD 131 coordinated efforts on scene to stabilize and render safe multiple hazards from the incident throughout the surrounding neighborhood. We remained onscene for the duration of the incident through Saturday 03/20/2021.

Battalion Chief Ryan Lewis/Bomb Squad

Additional Narrative (#11 of 18):

1842 was requested to respond to the location to assist with firefighter rehab. Upon arrival at approximately 14:15 on scene, Command advised that the divisions needed rehab measures. 1842 remained on scene providing rehab until approximately 16:30. 1842 released from incident and returned to service.

Tonya Loret 1842

Additional Narrative (#12 of 18):

T1822 responded as part of the first alarm response to the above address. Upon arrival T1822 donned PPE and SCBA and assisted ME 136 with firefighting efforts on Division D. T1822 assisted with obtaining primary surveys in surrounding structures with no remarkable findings. B1815 called for an operational retreat and met with all company officers. T1822 assigned to to safety officer for the incident.

Additional Narrative (#13 of 18):

ME141 was assigned to the Francis Incident for a 24 operational period on 3/18/2021 and was assigned to support and assist the EOD Operation on the incident. All pertinent operations were documented on Captain Bekins' ICS 214 and is attached to the main report.

KΒ

Additional Narrative (#14 of 18):

03/192021

ME141 was assigned to the Fire Branch for a 12 operational period. ME141 supported EOD operations during fireworks disposal. For further information reference IC#214.

R.D. Spellman Captain

Additional Narrative (#15 of 18):

Prior to the call, I was at station 131 at 425 east B street and I heard and felt a large explosion. Within 30 seconds, the tones sounded for a response to the documented location for a reported multiple explosions in the area of Francis and Fern Ave. While responding code 3 to the location, a large smoke header was observed.

Upon arrival, I parked my vehicle on the south side of the street in front of 424 west Francis.

Prior to first responders arrival, witness reports state hearing a loud explosion that caused windows to break near the area of origin. Smoke and flames were observed coming from the back yard of 428 west Francis. Within approximately 30 -60 seconds after the first explosion, a second very large explosion occurred which caused the most damage. This explosion also started many structure fires and spot fires on the property in question and surrounding properties. This explosion caused the gazebo along the north end of the property to be destroyed, the backhouse, the patio-cover to the north of the backhouse, and the van in the backyard all to catch on fire. A second vehicle was thrown on its side and ignited as well.

I 1850 and ME131 arrived on scene at the same time. I donned my turnouts and grabbed my camera. I then assisted ME 131 engineer Preston in pulling a 4-inch supply line to the fire hydrant at the corner of Fern and Francis. I then proceeded to 426 west Francis where I videoed and photographed the scene. Approximately 3 minutes after arriving on scene a large barrage of fireworks lit off with multiple explosions. ME 131 and ME 132 firefighters and I took shelter behind the back house at the location. A tactical retreat was called, and we exited the lot and allowed the area to burn and fought the fire from a defensive position. An area of approximately 3 to 4 city blocks was evacuated. Thousands of live and spent fireworks were covering the ground throughout this area. Live and spent rifle rounds were also observed throughout the area. Lumber from buildings, metal scraps, and general debris covered the entire evacuated area.

With first responders now on scene, approximately 5 and a half to 6 minutes after the very large explosion, the third major explosion occurred. This explosion caused the garage to the south of the backhouse to explode. The front house on the property also caught fire at this time.

For the remainder of the day, I photographed the scene and assisted firefighters and OFD bomb squad technicians in documentation and removal of fireworks, explosives, live rifle rounds and other evidence. I photographed the victims located in the backyard of 428 west Francis. I also assisted captain Lambert in covering the body of the victim found along the east border of the lot

Several structure fires occurred on the lot and surrounding parcels as well as several vehicles being destroyed or damaged by fire. Numerous house and businesses in the area suffered large amounts of structural damage and broken windows.

I was informed the Ontario Police Department would be the lead investigating agency for the incident and the Ontario Bomb squad would handle the explosion portion of the investigation. Several agencies responded to the location to assist in the investigation, for a comprehensive list of those agencies see Chief Lewis's report. I was released from the scene at approximately 9:00 on the evening of 3/16/21.

On 3/17/21, I returned to the scene on the following morning and assisted in the documentation and photographing of evidence. A pathway was cleared of hazards and debris for the coroner and OPD detectives to photograph and remove the victim bodies. Over the period of the next 4 days, commercial and professional grade fireworks were collected by bomb technicians as well as homemade and improvised explosive devices. At the end of each day the collected firework debris was disposed of in a safe manner by burning them in dumpsters and burn boxes. This process was monitored by members of the AQMD and EPA who were on scene. 11850 returned to the scene on the following days 3/17/21-3/20/21 to continue my investigation and assist OPD and OFD bomb squad in their investigations.

Dan Kloosterman

Additional Narrative (#16 of 18):

On 3/18/2021 ME 142 Was assigned as onsite medical during bomb disposal efforts. We also were on standby for any fire extinguishment needs. The crew from ME 142 also assisted the humane society with animal care. Captain Van Fossen was relieved by Captain Willemse on scene at 1215 hrs.

Brian Van Fossen Fire Captain ME 142

Additional Narrative (#17 of 18):

T131 responded Code 3 with EOD 131 to the reported address. Upon arrival B1815 assigned to Verkaik and Langevin to EOD 131. Firefighter's Gamboa and Jaquess were assigned under Captain Gilbert on ME 132 (Division A).

E.C Verkaik T131

Additional Narrative (#18 of 18):

ME142 Was assigned to 12 hour operational periods starting 3/16-17/2021.

We assisted with overhaul activities as Bomb Squad members utilized hose lines from the fire engine positioned on the street in the safe area.

We provided fire support during the fireworks firing operation.

This shift ended at 0700 on 3/17/2021

Fire Captain L.P. Guapo



NFIRS-1 Basic

Α								
36170	CA	03	16	2021	Station 2 (132)	OF2104486		1
FDID	State	Month	Day	Year	Station	Number		Exposure
B Location Type							Ĺ	Census tract:
Street Address Intersection In Front Of Rear Of Adjacent To Directions US National Grid	428 Number	W-West Prefix	FRANCI Street o	S r Highway			Street eet Type	Suffix
	Apt./Suite,		City			State	9176 Zip Co	
D Aid Given Or Received 1 Mutual Aid Received 2 Auto. Aid Given 3 Mutual Aid Given 4 Auto. Aid Given 5 Other Aid Given	eived L ved The	ir FDID	California Their State ber	Arrival Controlled	03 16 2021 1 03 16 2021 1 03 17 2021 0	12:29 12:34 07:03	В	od Alarms 3 O-10 larms District Studies Value

Actions Taken 11-Extinguishment by fire services Primary Action Taken	service personnel	G1 Resources Apparatus of Personnel Apparatus Suppression 17 EMS 5 Other 5 C: Resource counts include resources.	Personnel 34 12 10	Losses: Recknon	Values: Optional None
Completed Modules 2 - Fire 3 - Structure Fire 4 - Civilian Fire Cas. 5 - Fire Service Cas. 6 - EMS 7 - HazMat 8 - Wildland Fire 9 - Apparatus 10 - Personnel 11 - Arson	Fire Service Civilian H2 Detector Required for Con 1 - Detector	Deaths Injuries 0 0 0 0	H3 Hazardous Ma 1 - Natural C 2 - Propane 3 - Gasoline 4 - Kerosene 5 - Diesel Fu 6 - Househo 7 - Motor Oi 8 - Paint 0 - Other None	Gas e el / Fuel Oil ld Solvents	Mixed Use Property Not Mixed 10 - Assembly Use 20 - Education Use 33 - Medical Use 40 - Residential Use 51 - Row Of Stores 53 - Enclosed Mall 58 - Business and Residential 59 - Office Use 60 - Industrial Use 63 - Military Use 65 - Farm Use 00 - Other Mixed Use
Property Use Non- Structures 131 Church, Place of 161 Restaurant or Ca 162 Bar/Tavern or Nig 213 Elementary Scho 215 High School, Jun 241 College, Adult Ed 311 Nursing Home 331 Hospital	Worship feteria ghtclub ol, Kindegarten ior High	341 Clinic, Clinic-Type 342 Doctor/Dentist O 361 Prison or Jail, Not 419 1- or 2-Family Dwel 429 MultiFamily Dwel 439 Rooming/Boardin 449 Commerical Hote 459 Residential, Board 464 Dormitory/Barrac 519 Food and Beverag	ffice : Juvenile elling ling g House I or Motel d and Care ks	571 Gas or Ser 579 Motor Vel 599 Business C 615 Electric-Ge 629 Laborator 700 Manufactor 819 Livestock/	nicle/Boat Sales/Repairs Office enerating Plant y/Science Laboratory uring Plant (Poultry Storage (Barn) lential Parking Garage
Outside 124 Playground or Pa 655 Crops or Orchard 669 Forest (Timberla 807 Outdoor Storage 919 Dump or Sanitary 931 Open Land or Fie	l nd) : Area y Landfill	938 Graded/Cared for 946 Lake, River, Strear 951 Railroad Right-of-960 Other Street 961 Highway/Divided 962 Residential Street 981 Construction Site 984 Industrial Plant Ya	n Way Highway t/Driveway		a Property Use code and you have NOT checked a

K1				
Person/Entity Involved	Employee	Enviror	mental Protection Agency	
Local Option	Person/Entity Type	Busines	Name (if applicable)	Phone Number
MR-Mr.	Robert		Wise	
Mr., Ms., Mrs.	First Name	MI	Last Name	Suffix
Number	Prefix	Street or Highway	Street Type	Suffix
		r	City of Si	gnal Hill
Post Office Box	Apt./Su	ite/Room	City	
		V V		
State		Zip Code	2	

2					
Owner				11	
Local Option	Person/Enti	ty Type Business	Name (if applicable)	Phone Number	
Mr., Ms., Mrs.	First Name	MI	Last Name	Suffix	
Number	Prefix	Street or Highway	Street Type	Suffix	
L	J	0			
Post Office Box		Apt./Suite/Room	City		
State		Zip Code			

L Remarks:

B 1815 was dispatched as part of the first alarm assignment to a potential structure fire at the documented address. Prior to going enroute B 1815 acknowledged Ontario Dispatch traffic stating that there were multiple explosions at the location. Due to this I immediately started EOD 131 and HM 133.

B 1815 then went responding. While enroute I observed a large column of smoke in the area of the dispatched address. I broadcast this traffic and continued in code 3.

B 1815 AOS and observed fire to the front yard and rear of house. Structure observed was a single story single family residence with significant exposure concern to the delta side. B 1815 established Francis Command. Immediately upon establishing Francis Command, B 1815 requested that OPD shut down Francis St west of Fern and east of San Antonio. B 1815 also requested a 300' perimeter be established around 428 W. Francis St.

ME 132 AOS and Francis Command assigned him as Division A. Objectives were perimeter control and victim accountability. They were advised to engage in fire attack operations only if they felt safe in doing so.

ME 131 AOS and was assigned as a rescue group. There were report of victims on the "D" side of 428 W. Francis. This information was relayed to ME 131 and they set up for potential rescue operations.

T 1820 arrived onscene and he was assigned as division D with primary objectives of perimeter control and victim accountability. ME 136 was almost immediately assigned to help out division ...

Full primary narrative can be found in NFIRS 1S - Supplemental

Villiams, Ryan	Battalion Chief		03/23/2021
gnature	Position or Rank	Assignment	Date
Gilbert, Ryan	Fire Captain		03/25/2021
gnature	Position or Rank	Assignment	Date
	gnature ilbert, Ryan	nature Position or Rank ilbert, Ryan Fire Captain	nature Position or Rank Assignment ilbert, Ryan Fire Captain

NFIRS-2 Fire

Ľ	6170 PID	CA State	03 Month	16 Day	2021 Year	Station 2 (132)	OF2104486 Number	1 Exposure
B Prop B1 B2	Estimated number origin whether or number of building	of resident of all units his Buildings involved	esidential ial living uni became invo ngs Not Inv	olved olved	rilding of	C On-Site Materials Or Products		-Site Materials Irage Use
D1	Ignition Cause of Ignition			nvestigation rmined After ing to Ignition	1 - Asleep 2 - Possibly impaired by alcohol or drugs 3 - Unattended person 4 - Possibly Mentally Disabled 5 - Physically Disabled 6 - Multiple Persons Involved 7 - Age Was A Factor Estimated Age of Person Involved Male Female			
Equi Bra	pment Involved nd	n Ignition		Equipme F3 Equipme . 1 - Po	ationary	e	ne or two	G Fire Suppression Factors

H1 Mobile Property Involved 1 - Not involved in ignition, but burned 2 - Involved in ignition, but did not burn 3 - Involved in ignition and burned None	H2 Mobile Property Type and Make Mobile Property Type Mobile Property Make	Pre-Fire Plan Available Arson Report Attached Police Report Attached Coroner Report Attached Other Reports Attached		
Mobile Property Model State License Plate Number	Year VIN			

NFIRS-3 Structure Fire

	111 1110 5 501 0000			
Structure Type 1 - Enclosed Building 2 - Portable/Mobile Structure 3 - Open Structure 4 - Air-Supported Structure 5 - Tent 6 - Open Platform 7 - Underground Structure 8 - Connective Structure 0 - Other	Building Status 1 - Under Construction 2 - In Normal Use 3 - Idle, Not Routinely Used 4 - Under Major Renovation 5 - Vacant and Secured 6 - Vacant and Unsecured 7 - Being Demolished 0 - Other U Undetermined	Building H 1 Number of S At/Above Gr 0 Number of S Below Grade	stories ade stories	I4 Main Floor Size 900 Total Square Feet OR BY Length (ft) X Width (ft)
J1 Fire Origin 1 Below Grade Story of Fire Origin J2 Fire Spread Confined to Object of Origin C 2 - Confined to Room of Origin A - Confined to Building of Origin 5 - Beyond Building of Origin	Number of Stories Damaged By Fla Number of Stories w/Minor Dama Number of Stories w/Significant 0 Number of Stories w/Heavy Dama Number of Stories w/Extreme Da *Count the roof as part of the highest stories	nge (1-24%) Damage (25-49%) age (50-74%) mage (75-100%)	K1 Llento File K2 Llento Type	Material Contributing Flame Spread Contributing Most lame Spread of Material Contributing t To Flame Spread
L1 Presence of Detectors N - None Present 1 - Present U - Undetermined L2 Detector Type 1 - Smoke 2 - Heat 3 - Combination of Smoke and Heat 4 - Sprinkler, Water Flow Detection 5 - More Than One Type Present 0 - Other U - Undetermined	Detector Power Supply 1 - Battery Only 2 - Hardwire Only 3 - Plug-In 4 - Hardwire With Battery 5 - Plug-In With Battery 6 - Mechanical 7 - Multiple Detectors	L5 Detector Effect 1 - Alerted Oc 2 - Alerted Oc 3 - There Wer 4 - Failed to A U - Undeterm L6 Detector Failur 1 - Power Fail 2 - Improper I 3 - Defective 4 - Lack of Ma 5 - Battery Mi 6 - Battery Di 1 0 - Other U - Undeterm	e Reason ure, Shutoff nstallation of sing or Dis- scharged or	r, or Disconnect or Placement Dirty connected

M1	M3	M5
Presence of Automatic Extinguishing System	Operation of Automatic Extinguishing System	Reason for Automatic Extinguishing System Failure
M - None Present 1 - Present 2 - Partial System Present U - Undetermined M2 Type of Automatic Extinguishing System 1 - Wet-Pipe Sprinkler 2 - Dry-Pipe Sprinkler	1 - Operated/Effective 2 - Operated/Not Effective 3 - Fire Too Small To Activate 4 - Failed To Operate 0 - Other U - Undetermined Required if fire was within designed range	1 - System Shut Off 2 - Not Enough Agent Discharged 3 - Agent Discharged But Did Not Reach Fire 4 - Wrong Type of System 5 - Fire Not In Area Protected 6 - System Components Damaged 7 - Lack of Maintenance 8 - Manual Intervention 0 - Other U - Undetermined Required if system failed or not effective
3 - Other Sprinkler System 4 - Dry Chemical System 5 - Foam System 6 - Halogen-Type System 7 - Carbon Dioxide System 0 - Other U - Undetermined Required if fire was within designed range of AES	M4 Number of Sprinkler Heads Operating Required if system operated	

NFIRS-9 Apparatus or Resources

36170	CA	03	16	2021		OF2104486	1
FDID	State	Month	Day	Year	Station	Number	Exposure

B Apparatus/Resource	Dates/Times	Sent	Number of People	Apparatus Use	Actions Taken
ID: B1806 Type: 92-Chief officer car	Dispatch: 03/16/2021 12:42 Arrival: 03/16/2021 12:54	Sent	1	Suppression EMS Other	81-Incident command
·	Clear: 03/16/2021 15:23				
ID: B1807	Dispatch: 03/16/2021 13:02	Sent	0	Suppression EMS	Ц
Type: 92-Chief officer car	Arrival:			Other	
ID: B1808		Sent	l _a l	Suppression	
Type: 92-Chief officer car	Dispatch: 03/16/2021 19:12 Arrival:	Selic	Ů	EMS Other	
	Clear: 03/18/2021 02:51				
ID: B1811	Dispatch: 03/16/2021 19:36	Sent Sent	0	Suppression DEMS	
Type: 92-Chief officer car	Arrival:			Other	
In Land	Clear: 03/17/2021 14:19		1 1		11
Type: 92-Chief officer car	Dispatch: 03/16/2021 12:30 Arrival: 03/16/2021 12:36	Sent	_1_	Suppression EMS Other	
	Clear: 03/17/2021 01:41				
ID: 81825	Dispatch: 03/16/2021 12:32	Sent	1	Suppression	П
Type: 92-Chief officer car	Arrival: 03/16/2021 12:40			Other	
	Clear: 03/16/2021 19:13				
ID: C1842	Dispatch: 03/16/2021 14:06	Sent	0	Suppression EMS	
Type: 60-Support apparatus, other	Arrival: 03/16/2021 14:06 Clear: 03/16/2021 17:43			Other	
ID: D1802	Dispatch: 03/16/2021 13:11	Sent	l _o l	Suppression	11
Type: 92-Chief officer car	Arrival: 03/16/2021 13:11	Jene	Ľ	EMS Other	
	Clear: 03/16/2021 14:26				
ID: D1803	Dispatch: 03/16/2021 12:44	Sent	0	Suppression	Ц
Type: 92-Chief officer car	Arrival:			Other	
	Clear: 03/16/2021 14:26		1.1		11
Type: 00-Other apparatus/resource	Dispatch: 03/16/2021 12:31 Arrival: 03/19/2021 23:41	Sent	8	Suppression EMS Other	П
. Jes. Said apparatus/resource	Clear: 03/20/2021 15:31				
ID: HM133	Dispatch: 03/16/2021 13:09	Sent	0	Suppression	
Type: 93-HazMat unit	Arrival:		_	Other	

			03/20/2021	14:52				
ID:	11850	Dispatch:	03/16/2021	12:30	Sent	1	Suppression	
Туре:	60-Support apparatus, other	Arrival:	03/16/2021	12:36			Other	
		Clear:	03/17/2021	17:58				
ID:	ME131	Dispatch:	03/16/2021	12:30	Sent	4	Suppression	Ц
Туре:	11-Engine	Arrival:	03/16/2021	12:36			Other	
		Clear:	03/16/2021	15:09				
ID:	ME132	Dispatch:	03/16/2021	12:30	Sent	4	Suppression	П
Туре:	11-Engine	Arrival:	03/16/2021	12:34			Other	
		Clear:	03/19/2021	15:43				
ID:	ME134	Dispatch:	03/16/2021	12:42	Sent	4	Suppression	
Туре:	11-Engine	Arrival:	03/16/2021	12:47			Other	
		Clear:	03/16/2021	14:43				
ID:	ME135	Dispatch:	03/16/2021	12:42	Sent	4	Suppression EMS	
Туре:	11-Engine	Arrival:	03/16/2021	12:53			Other	
		Clear:	03/16/2021	14:47				
ID:	ME136	Dispatch:	03/16/2021	12:30	Sent	4	Suppression	11-Extinguishment by fire service personnel
Туре:	11-Engine	Arrival:	03/16/2021	12:42			Other	
		Clear:	03/17/2021	21:11				
ID:	ME137	Dispatch:	03/16/2021	13:09	Sent	4	Suppression	Ц
Туре:	11-Engine	Arrival:	03/16/2021	13:20			Other	
		Clear:	03/16/2021	14:15				
ID:	ME138	Dispatch:	03/16/2021	13:08	Sent	4	Suppression	Ц
Туре:	11-Engine	Arrival:	03/16/2021	13:11			EMS Other	
		Clear:	03/16/2021	15:16				
ID:	ME139	Dispatch:	03/16/2021	12:42	Sent	4	Suppression	
Туре:	11-Engine	Arrival:	03/16/2021	12:54			Other	
		Clear:	03/16/2021	22:13				
ID:	ME141	Dispatch:	03/16/2021	22:31	Sent	0	Suppression	Ц
Туре:	11-Engine	Arrival:	ШШ				Other	
		Clear:	03/20/2021	14:28				
ID:	ME67	Dispatch:	03/16/2021	13:28	Sent	0	Suppression	11-Extinguishment by fire service personnel
Туре:	11-Engine	Arrival:	03/16/2021	13:28			Other	

	Clear: 03/16/2021 23:41	
ID: T131 Type: 12-Truck or aerial	Dispatch: 03/16/2021 12:30 Sent 4 Arrival: 03/16/2021 12:38	Suppression Line Supersion Line Suppression Line Suppression Line Suppression Line Suppression Line Supersion Lin
Types 12 weeks deliak	Clear: 03/16/2021 22:02	
ID: T138 Type: 12-Truck or aerial	Dispatch: 03/16/2021 12:42 Sent 4 Arrival: 12:44 Clear: 03/16/2021 12:44	Suppression EMS Other
ID: T139 Type: 12-Truck or aerial	Dispatch: 03/16/2021 12:43 Sent 4 Arrival:	Suppression Line Supersion Line Suppression Line Supersion Line Supe
	Clear: 03/16/2021 20:05	
ID: T1820 Type: 60-Support apparatus, other	Dispatch: 03/16/2021 12:37 Sent 0 Arrival: 03/16/2021 12:37 Clear: 03/18/2021 13:36	Suppression L EMS Other
ID: T1822 Type: 60-Support apparatus, other	Dispatch: 03/16/2021 12:51 Sent 0 Arrival:	Suppression L EMS Other

NFIRS-10 Personnel

Α							
36170	CA	03	16	2021	Station 2 (132)	OF2104486	1
FDID	State	Month	Day	Year	Station	Number	Exposure

B Apparatus/Resource	Dates/Times		Number of People	Apparatus Use	Actions Taken
ID: B1806	Dispatch: 03/16/2021 12:42	Sent	1	Suppression	81-Incident command
Type: 92-Chief officer car	Arrival: 03/16/2021 12:54		_	EMS Other	
	Clear: 03/16/2021 15:23				
Personnel ID	Name	Rank	Role	Attend	Actions Taken
17111	Roeber, Scotland	Battalion Chief			81-Incident command
	1 11 I				11
ID: B1807	Dispatch: 03/16/2021 13:02	Sent	0	Suppression EMS	Ц
Type: 92-Chief officer car	Arrival:			Other	
	Clear: 03/18/2021 02:52				
Personnel ID	Name	Rank	Role	Attend	Actions Taken
ID: B1808	Dispatch: 03/16/2021 19:12	Sent	0	Suppression	Ц
Type: 92-Chief officer car	Arrival:		_	EMS Other	
	Clear: 03/18/2021 02:51				
Personnel ID	Name	Rank	Role	Attend	Actions Taken
ID: B1811	Dispatch: 03/16/2021 19:36	Sent	0	Suppression	
		Sent	Ľ	EMS	_
Type: 92-Chief officer car	Arrival:			- Other	
Personnel ID	Name	Rank	Role	Attend	Actions Taken
retabilitetib	Ranic	Nalik	Note	Accend	
ID: B1815	Dispatch: 03/16/2021 12:30	Sent	1	Suppression EMS	П
Type: 92-Chief officer car	Arrival: 03/16/2021 12:36			Other	
	Clear: 03/17/2021 01:41				
Personnel ID	Name	Rank	Role	Attend	Actions Taken
18726	Williams, Ryan	Battalion Chief			
					1.1
ID: B1825	Dispatch: 03/16/2021 12:32	Sent	1	Suppression EMS	П
Type: 92-Chief officer car	Arrival: 03/16/2021 12:40			Other	
	Clear: 03/16/2021 19:13				
Personnel ID	Name	Rank	Role	Attend	Actions Taken
18006	Stepanian, Nicolas	Battalion Chief			Ш
In. Lease	Bisselet Januaran I I I	(Cb	1.1	Su	
ID: C1842	Dispatch: 03/16/2021 14:06	Sent	0	Suppression EMS Other	
Type: 60-Support apparatus, other	Arrival: 03/16/2021 14:06			Other	
	Clear: 03/16/2021 17:43				
Personnel ID	Name	Rank	Role	Attend	Actions Taken
ID: Locasi	Dispatch and a change and a				

	טו. Type:	92-Chief officer car	Arrival: 03/16/2021 13:11 Clear: 03/16/2021 14:26	Sent	0	Suppression EMS Other	
Ì	Personn	el ID	Name	- Rank	Role	- Attend	Actions Taken
	ID: Type:	92-Chief officer car	Dispatch: 03/16/2021 12:44 Arrival:	Sent	0	Suppression EMS Other	
t	Personn	elID	Name	Rank	Role	Attend	Actions Taken
	ID: Type:	ED131 00-Other apparatus/resource	Dispatch: 03/16/2021 12:31 Arrival: 03/19/2021 23:41 Clear: 03/20/2021 15:31	Sent	8	Suppression EMS Other	
İ	Personn	el ID	Name	Rank	Role	Attend	Actions Taken
	19425		Trapani, Geoffrey	Fire Investigation Supervisor			
	18343		Goyette, Matthew	Fire Captain			
	19273		Lambert, Darrell	Fire Captain			Ц
	19228		Langevin, Steve	Fire Engineer			Ц
	16923		Lewis, Ryan	Battalion Chief			Ц
	19226	315	Ryan, Jacob	Fire Captain		, G	Ц
	18724		Verkaik, Eugene	Fire Captain		Ei	Ц
	18466		Wedell, Michael	Battalion Chief			Ц
	ID: Type:	HM133 93-HazMat unit	Dispatch: 03/16/2021 13:09 Arrival:	Sent Sent	0	Suppression EMS Other	Ц
t	Personn	elID	Name	Rank	Role	Attend	Actions Taken
	ID: Type:	60-Support apparatus, other	Dispatch: 03/16/2021 12:30 Arrival: 03/16/2021 12:36 Clear: 03/17/2021 17:58	Sent	1	Suppression EMS Other	
	Personn	el ID	Name	Rank	Role	Attend	Actions Taken
	18721		Kloosterman, Daniel	Fire Investigation Supervisor		0	
	ID: Type:	ME131	Dispatch: 03/16/2021 12:30 Arrival: 03/16/2021 12:36 Clear: 03/16/2021 15:09	Sent	4 Pole	EMS Other	Artions Taken
7		- · ·				• •	

reisonnecio	Isame	Malik Mote	Accello	ACTIONS TOKEN
20025	Bandaruk, Jason	Firefighter		Ш
20192	Wilson, Duncan	Firefighter	0	Ш
19140	Hafner, Ryan	Fire Captain		Ш
19344	Preston, Bryan	Fire Engineer	[7	Ц
ID: ME132 Type: 11-Engine	Dispatch: 03/16/2021 12:30 Arrival: 03/16/2021 12:34 Clear: 03/19/2021 15:43	Sent 4	Suppression EMS Other	Ц
Personnel ID	Name	Rank Role	Attend	Actions Taken
20183	Clements, Cody	Firefighter	El .	
19687	Thompson, Matthew	Fire Engineer		L =
19223	Gilbert, Ryan	Fire Captain		
20190	Saunders, Kurt	Firefighter		
ID: ME134 Type: 11-Engine	Dispatch: 03/16/2021 12:42 Arrival: 03/16/2021 12:47 Clear: 03/16/2021 14:43	Sent 4	Suppression EMS Other	
Personnel ID	Name	Rank Role	Attend	Actions Taken
20205	Okamura, Thomas	Firefighter		Ц
20201	Steele, Matthew	Firefighter		Ш
19227	Willemse, Scott	Fire Captain		Ц
19422	Cavanaugh, Sean	Fire Engineer	U	Ц
ID: ME135 Type: 11-Engine	Dispatch: 03/16/2021 12:42 Arrival: 03/16/2021 12:53 Clear: 03/16/2021 14:47	Sent 4	Suppression EMS Other	
Personnel ID	Name	Rank Role	Attend	Actions Taken
19881	Ciszek, Brian		ΕĪ.	<u>U</u>
20199	Hoover, Lucas	Firefighter		Ш
17357	Bekins, Kurt	Fire Captain		Ш
19857	Zaragoza, Eric			Ц
ID: ME136 Type: 11-Engine	Dispatch: 03/16/2021 12:30 Arrival: 03/16/2021 12:42 Clear: 03/17/2021 21:11	Sent 4	Suppression EMS Other	11-Extinguishment by fire service pers
Personnel ID	Name	Rank Role	Attend	Actions Taken
19798	Mowad, Trevor		<u> </u>	Ш
20327				
20327	Magrina, Joel	Firefighter		<u> </u>

20185	Medina, Jacob	Firefighter _		. [1]	<u> </u>
16864	Spellman, Ronald	Fire Captain			· []
ID: ME137	Dispatch: 03/16/2021 13:09	Sent	4	Suppression	
Type: 11-Engine	Arrival: 03/16/2021 13:20 Clear: 03/16/2021 14:15			Other	
Personnel ID	Name	Rank F	Role	Attend	Actions Taken
20194	Esquivias, Jovanny	Firefighter			
19680	Garrett, Chad	Fire Engineer			
17233	De Young, Daniel	Fire Captain			
20321	Armstrong, Joshua	Firefighter		Ð	
ID: ME138 Type: 11-Engine	Dispatch: 03/16/2021 13:08 Arrival: 03/16/2021 13:11 Clear: 03/16/2021 15:16	Sent	4	Suppression FEMS Other	
Personnel ID	Name	Rank F	Role	Attend	Actions Taken
19807	Clarke, Christian			[_]	Ц
16895	Nelson, Tye	Fire Captain			
20316	Hernandez, Michael	Firefighter		白	
20202	Powers, Brian	Firefighter			
ID: ME139 Type: 11-Engine	Dispatch: 03/16/2021 12:42 Arrival: 03/16/2021 12:54 Clear: 03/16/2021 22:13	Sent [4	Suppression JEMS Other	
Personnel ID	Name	Rank R	Role	Attend	Actions Taken
20334	Verral, Eric	Firefighter		EI .	
20184	Selk, Chase	Firefighter			
19686	Talley, Steven	Fire Engineer			П
18902	Bethel, Richard	Fire Captain			Ц
ID: ME141 Type: 11-Engine	Dispatch: 03/16/2021 22:31 Arrival:	Sent	0	Suppression EMS Other	Ц
Personnel ID	Name	Rank F	Role	Attend	Actions Taken
ID: ME67 Type: 11-Engine	Dispatch: 03/16/2021 13:28 Arrival: 03/16/2021 13:28 Clear: 03/16/2021 23:41	Sent	0	Suppression EMS Other	11-Extinguishment by fire service pers
Personnel ID	Name	Rank R	Role	Attend	Actions Taken
ID: T131	Dispatch: 03/16/2021 12:30	Sent		Suppression	

Type: 12-Truck or aerial	Arrival: 03/16/2021 12:38		4	EMS Other	
	Clear: 03/16/2021 22:02				
Personnel ID	Name	Rank	Role	Attend	Actions Taken
20326	Jaquess, Tyler	Firefighter			
19228	Langevin, Steve	Fire Engineer		ĬĬ.	
18724	Verkaik, Eugene	Fire Captain		13	
20032	Gamboa, Neil	Firefighter			Ц
ID: T138 Type: 12-Truck or aerial	Dispatch: 03/16/2021 12:42 Arrival:	Sent	4	Suppression EMS Other	Ц
Personnel ID	Name	Rank	Role	Attend	Actions Taken
19885	Morrison, Christopher			8	Ш
20029	Harper, Martin	Firefighter			
18980	Van Fossen, Brian	Fire Captain			
19508	Bates, Logan	Fire Engineer		ŭ,	
ID: T139 Type: 12-Truck or aerial	Dispatch: 03/16/2021 12:43 Arrival:	Sent	4	Suppression EMS Other	Ц
Personnel ID	Name	Rank	Role	Attend	Actions Taken
19880	DeMartino, Noah				
20214	Norbryhn, Scott	Firefighter		6	
19679	Charleston, David	Firefighter			
17102	Guapo, Louis	Fire Captain		U .	Ц
Type: 60-Support apparatus, other	Dispatch: 03/16/2021 12:37 Arrival: 03/16/2021 12:37 Clear: 03/18/2021 13:36	Sent	0	Suppression EMS Other	
Personnel ID	Name	Rank	Role	Attend	Actions Taken
Type: 60-Support apparatus, other	Dispatch: 03/16/2021 12:51 Arrival:	Sent	0	Suppression EMS Other	Ц
Personnel ID	Name	Rank	Role	Attend	Actions Taken

NFIRS-1S Supplemental

Α								
	36170	CA	03	16	2021	Station 2 (132)	OF2104486	1
	FDID	State	Month	Daý	Year	Station	Number	Exposure

Primary Narrative:

B 1815 was dispatched as part of the first alarm assignment to a potential structure fire at the documented address. Prior to going enroute B 1815 acknowledged Ontario Dispatch traffic stating that there were multiple explosions at the location. Due to this I immediately started EOD 131 and HM 133.

B 1815 then went responding. While enroute I observed a large column of smoke in the area of the dispatched address. I broadcast this traffic and continued in code 3.

B 1815 AOS and observed fire to the front yard and rear of house. Structure observed was a single story single family residence with significant exposure concern to the delta side. B 1815 established Francis Command. Immediately upon establishing Francis Command, B 1815 requested that OPD shut down Francis St west of Fern and east of San Antonio. B 1815 also requested a 300' perimeter be established around 428 W. Francis St.

ME 132 AOS and Francis Command assigned him as Division A. Objectives were perimeter control and victim accountability. They were advised to engage in fire attack operations only if they felt safe in doing so.

ME 131 AOS and was assigned as a rescue group. There were report of victims on the "D" side of 428 W. Francis. This information was relayed to ME 131 and they set up for potential rescue operations.

T 1820 arrived onscene and he was assigned as division D with primary objectives of perimeter control and victim accountability. ME 136 was almost immediately assigned to help out division D.

T 131 AOS and due to unit specialty their crew was split. Captain Verkaik and Engineer Langevin were assigned to the EOD group and FF Jaquess and FF Gamboa were assigned underneath division A to assist with their operation.

ME 134 was assigned as my division B. Their objectives were to establish perimeter control and provide victim accountability.

ME 139 AOS and they were assigned as division D. Their objectives were to establish perimeter control and provide victim accountability.

During the course of assigning unit to their divisional assignments a large explosion occurred. This explosion resulted in an operational retreat of all divisions. A PAR was performed and all firefighters were accounted for. No injuries were noted due to the explosion.

Fire suppression activities resumed after the explosion with safety measures applied. Large diameter hoselines were used from a safe distance.

Fire was extinguished at the documented time. Operations then transitioned into a multi day investigation operation led by Ontario FD EOD and I 1850. Please reference their report for additional information in regards to their operations.

Multi families were displaced as a result of this incident. Red Cross was used as the primary for sheltering measures.

Ultimately on Saturday late afternoon the Francis Incident was terminated and all Ontario Fire Department operations were complete.

R. Williams Fire Battalion Chief Battalion 1-B

Person/Entity Involved		Employee	Employee			
Local Option		Person/Entity Type		Business Name (if applicable)	Phone Num	nber
	Kamal			Brenner		
Mr., Ms., Mrs.	First Name		MI	Last Name		Suffix
A						
Number	Prefix	Street or Highway		Street Ty	/pe	Suffix
					1	
Post Office Box		Apt./S	Suite/Room	City		
State		Zip Code				

Additional Narrative (#1 of 1):

Exposure #1

The property to the west of the area of origin is 426 west Francis. This property sustained a great deal of structural damage to the front and back houses. The explosion caused secondary fires to start e north and west ends of the property.

R. Gilbert ME 132-B Captain



NEIDS-1 Bacic

			IN	LIK2-I	Dazic			
A								
36170	CA	03	16	2021	Station 2 (132)	OF2104486	;	2
FDID	State	Month	Day	Year	Station	Number		Exposure
B Location Type								Census tract
Street Address Intersection In Front Of Rear Of Adjacent To Directions US National Grid	428 Number	W-West Prefix	FRANCI Street o	S r Highway			:T-Street reet Type	Suffix
	Apt./Suite/Ro	oom	City)	=	CA		762 Code
>	Cross Street							
Incident Type 1111-Building fire Aid Given Or Receive 1 Mutual Aid Receive 2 Auto. Aid Receive 3 Mutual Aid Given 4 Auto. Aid Given	eived Lived Their I	FDID T	California heir tate	Alarm Arrival Controlled Last Unit		12:29 12:34 07:03 15:31	Shift or Platoon	and Alarms O-10 Alarms District Studies Value
1 Mutual Aid Rec 2 Auto. Aid Recei 3 Mutual Aid Give	eived Lived Their I	FDID T	heir tate		03 20 2021	15:31	Special	

Their Incident Number

Actions Taken 11-Extinguishment by fire service personnel Primary Action Taken		G1 Resources Apparatus or Personnel Apparatus Suppression 17 EMS 5 Other 5 Resource counts include resources.	Personnel 34 12 10	G2 Estimated Dollar Losses and Value Losses: Required for all fires if known. Optional for all non-fires. Property: \$ 0 Contents: \$ 0 Pre-Incident Values: Optional Non-fires of the property: \$ 0 Contents: \$ 0		
Completed Modules 2 - Fire 3 - Structure Fire 4 - Civilian Fire Cas. 5 - Fire Service Cas. 6 - EMS 7 - HazMat 8 - Wildland Fire 9 - Apparatus 10 - Personnel 11 - Arson	Fire Service Civilian H2 Detector Required for Conf	eaths Injuries	H3 Hazardous Mal 1 - Natural G 2 - Propane G 3 - Gasoline 4 - Kerosene 5 - Diesel Fue 6 - Househol 7 - Motor Oil 8 - Paint 0 - Other None	as	: se	
Property Use Non- Structures 131 Church, Place of 161 Restaurant or Ca 162 Bar/Tavern or Ni 213 Elementary Scho 215 High School, Jun 241 College, Adult Ec 311 Nursing Home 331 Hospital	Worship feteria ghtclub ol, Kindegarten ior High	341 Clinic, Clinic-Type 342 Doctor/Dentist Of 361 Prison or Jail, Not 419 1- or 2-Family Dwell 429 MultiFamily Dwell 439 Rooming/Boardin 449 Commerical Hotel 459 Residential, Board 464 Dormitory/Barrac 519 Food and Beverag	fice Juvenile elling ing g House or Motel I and Care ks	539 Household Goods, Sales, Repairs 571 Gas or Service Station 579 Motor Vehicle/Boat Sales/Repairs 599 Business Office 615 Electric-Generating Plant 629 Laboratory/Science Laboratory 700 Manufacturing Plant 819 Livestock/Poultry Storage (Barn) 882 Non-Residential Parking Garage 891 Warehouse		
Outside 124 Playground or Pa 655 Crops or Orchard 669 Forest (Timberla 807 Outdoor Storage 919 Dump or Sanitary 931 Open Land or Fie	f nd) : Area y Landfill	938 Graded/Cared for 946 Lake, River, Strean 951 Railroad Right-of- 960 Other Street 961 Highway/Divided 962 Residential Street 981 Construction Site 984 Industrial Plant Ya	n Way Highway /Driveway	Property Use: Description Look up and enter a Property Use code and description only if you have NOT checked a Property Use box.		

K1				
Person/Entity Involved	Employee		mental Protection Agency	
Local Option	Person/Entity Type	Busines	s Name (if applicable)	Phone Number
MR-Mr.	Robert][Wise	
Mr., Ms., Mrs.	First Name	MI	Last Name	Suffix
	1			
Number	Prefix	Street or Highway	Street Type	Suffix
Post Office Box	Apt./Su	ite/Room	City	
State		Zip Cod	e	

3 2					
Owner					
Local Option	Person/Enti	ty Type Business	Name (if applicable)	Phone Number	
Mr., Ms., Mrs.	First Name	M	Last Name	Suffix	
L					
Number	Prefix	Street or Highway	Street Type	Suffix	
L		Ĺ			
Post Office Box		Apt./Suite/Room	City		
State		Zip Code	9		

L Remarks:

B 1815 was dispatched as part of the first alarm assignment to a potential structure fire at the documented address. Prior to going enroute B 1815 acknowledged Ontario Dispatch traffic stating that there were multiple explosions at the location. Due to this I immediately started EOD 131 and HM 133.

B 1815 then went responding. While enroute I observed a large column of smoke in the area of the dispatched address. I broadcast this traffic and continued in code 3.

B 1815 AOS and observed fire to the front yard and rear of house. Structure observed was a single story single family residence with significant exposure concern to the delta side. B 1815 established Francis Command. Immediately upon establishing Francis Command, B 1815 requested that OPD shut down Francis St west of Fern and east of San Antonio. B 1815 also requested a 300' perimeter be established around 428 W. Francis St.

ME 132 AOS and Francis Command assigned him as Division A. Objectives were perimeter control and victim accountability. They were advised to engage in fire attack operations only if they felt safe in doing so.

ME 131 AOS and was assigned as a rescue group. There were report of victims on the "D" side of 428 W. Francis. This information was relayed to ME 131 and they set up for potential rescue operations.

T 1820 arrived onscene and he was assigned as division D with primary objectives of perimeter control and victim accountability. ME 136 was almost immediately assigned to help out division ...

Full primary narrative can be found in NFIRS 1S - Supplemental

Authorization	97	75	300	77
18726	Williams, Ryan	Battalion Chief		03/23/2021
Officer In Charge ID	Signature	Position or Rank	Assignment	Date
19223	Gilbert, Ryan	Fire Captain		03/25/2021
Member Making Report ID	Signature	Position or Rank	Assignment	Date

NFIRS-2 Fire

Α										
J36	6170	CA State	03 Month	16 Day	2021 Year	Station 2 (132)	OF2104486	2 Exposure		
			1-10-11-11			Jest of the second seco	- Trainber	Едрозого		
B	perty Details					C On-Site Materials	On	-Site Materials		
B1	1	Not Re	sidential			Or Products		orage Use		
	Estimated number or origin whether or no	of residentia ot all units b	al living unit became invo	s in the bu	ilding of					
B2		Buildin	gs Not Inv	olved						
	Number of buildings	s involved								
B3		None	Less th	an 1 acre						
	Acres burned (outside	de fires)								
D				E1			E3			
Ignit	Ignition Cause of Ignition				_		ors Contributing to			
D1	Undetermined		1 - Intentional				Ignition Check all appl	icable boxes		
	Area of Fire Origin \$\frac{1}{3}\$ - Failure of Equ					pment or Heat	None 1 - Asleep			
D2	82-Radiated heat fro	om another		5 - Cause Under Investigation drugs			drugs	sibly impaired by alcohol or		
	Heat Source		-	U - C Investi	lause Undetergation	rmined After		tended person bly Mentally Disabled		
D3	12-Exterior sidewall surface, finish	covering,		E2.			5 - Physica	sically Disabled tiple Persons Involved		
	Item First Ignited				rs Contributi	ing to Ignition	7 - Age Wa	The state of the s		
D4	99-Multiple types of			71-Ex	posure fire		Estimated Ag Person Involv			
	Type of Material Fir	st Ignited		Factor Contributing to Ignition			Male Female			
F1				F2				G		
Equi	pment Involved In	Ignition		Equipme	ent Power So	игсе		Fire Suppression Factors		
	one									
L.J Equip	oment Involved			Equipmer	nt Power Source	e				
Dec -	.		1	F3						
Bran	1 1			Equipmo	ent Portabilit	S.y				
	1 1			11 - Po	rtable					
Serial # 2 - Stationary Portable equipment n persons.						mally can be moved by or	ne or two			

H1 Mobile Property Involved	H2 Mobile Property Type and Make	Local Use
1 - Not involved in ignition, but burned 2 - Involved in ignition, but did not burn 3 - Involved in ignition and burned None	Mobile Property Type Mobile Property Make	Pre-Fire Plan Available Arson Report Attached Police Report Attached Coroner Report Attached Other Reports Attached
L		1
Mobile Property Model	Year	0
State License Plate Number	VIN	3

NFIRS-3 Structure Fire

	MLIK2-3 201 acci	ure i ire		
Structure Type 1 - Enclosed Building 2 - Portable/Mobile Structure 3 - Open Structure 4 - Air-Supported Structure 5 - Tent 6 - Open Platform 7 - Underground Structure 8 - Connective Structure 0 - Other	osed Building able/Mobile Structure n Structure supported Structure n Platform erground Structure n Platform n Platform erground Structure n Platform n Platfor		stories ade stories	Main Floor Size 300 Total Square Feet OR BY Length (ft) X Width (ft)
J1 Fire Origin 1 Below Grade Story of Fire Origin J2 Fire Spread Confined to Object of Origin 2 - Confined to Room of Origin 3 - Confined to Floor of Origin 4 - Confined to Building of Origin 5 - Beyond Building of Origin	Number of Stories Damaged By I Number of Stories w/Minor Da Number of Stories w/Significar Number of Stories w/Heavy Da Number of Stories w/Extreme *Count the roof as part of the highest	mage (1-24%) nt Damage (25-49%) mage (50-74%) Damage (75-100%)	K1 Ll ltem to Fl K2 Ll Type	Material Contributing Flame Spread Contributing Most lame Spread of Material Contributing t To Flame Spread
L1 Presence of Detectors N - None Present 1 - Present U - Undetermined L2 Detector Type 1 - Smoke 2 - Heat 3 - Combination of Smoke and Heat 4 - Sprinkler, Water Flow Detection 5 - More Than One Type Present 0 - Other U - Undetermined	2 - Hardwire Only 3 - Plug-In 4 - Hardwire With Battery 5 - Plug-In With Battery 6 - Mechanical 7 - Multiple Detectors & Power Supplies 0 - Other U - Undetermined L4 ion 2 - Alerted Occup: 3 - There Were No. 4 - Failed to Alert U - Undetermined 1 - Power Failure Re 1 - Power Failure, 2 - Improper Insta 3 - Defective 4 - Lack of Mainto		e Reason ure, Shutoff nstallation of intenance, I ssing or Dis- scharged or	nts , or Disconnect or Placement Dirty connected

M1	M3	M5
Presence of Automatic Extinguishing System	Operation of Automatic Extinguishing System	Reason for Automatic Extinguishing System Failure
N - None Present 1 - Present 2 - Partial System Present U - Undetermined M2 Type of Automatic Extinguishing System 1 - Wet-Pipe Sprinkler 2 - Dry-Pipe Sprinkler	1 - Operated/Effective 2 - Operated/Not Effective 3 - Fire Too Small To Activate 4 - Failed To Operate 0 - Other U - Undetermined Required if fire was within designed range	1 - System Shut Off 2 - Not Enough Agent Discharged 3 - Agent Discharged But Did Not Reach Fire 4 - Wrong Type of System 5 - Fire Not In Area Protected 6 - System Components Damaged 7 - Lack of Maintenance 8 - Manual Intervention 0 - Other U - Undetermined Required if system failed or not effective
3 - Other Sprinkler System 4 - Dry Chemical System 5 - Foam System 6 - Halogen-Type System 7 - Carbon Dioxide System 0 - Other U - Undetermined Required if fire was within designed range of AES	M4 Number of Sprinkler Heads Operating Required if system operated	

NFIRS-9 Apparatus or Resources

A							
36170	CA	03	16	2021		OF2104486	2
FDID	State	Month	Day	Year	Station	Number	Exposure

B Apparat	:us/Resource	Dates/Times			Sent	Number of People	Apparatus Use	Actions Taken
ID:	B1806	Dispatch: 03	3/16/2021	12:42	Sent	1	Suppression EMS	81-Incident command
Туре:	92-Chief officer car	Arrival: 03	3/16/2021	12:54			Other	
		Clear: 03	3/16/2021	15:23				
ID:	B1807	Dispatch: 03	3/16/2021	13:02	Sent	0	SuppressionEMS	Ц
Туре:	92-Chief officer car	Arrival:	Ц				Other	
		Clear: 03	3/18/2021	02:52				
ID:	B1808	Dispatch: 03	3/16/2021	19:12	Sent	0	Suppression	Ц
Туре:	92-Chief officer car	Arrival:	Ц				Other	
		Clear: 03	3/18/2021	02:51				
ID:	B1811	Dispatch: 03	3/16/2021	19:36	Sent	0	Suppression	Ц
Туре:	92-Chief officer car	Arrival:					Other	
		Clear: 03	3/17/2021	14:19				
ID:	B1815	Dispatch: 03	3/16/2021	12:30	Sent	1	Suppression EMS	
Туре:	92-Chief officer car	Arrival: 03	3/16/2021	12:36			Other	
		Clear: 03	3/17/2021	01:41				
ID:	B1825	Dispatch: 03	3/16/2021	12:32	Sent	1	Suppression EMS	Ц
Туре:	92-Chief officer car	Arrival: 03	3/16/2021	12:40			Other	
		Clear: 03	3/16/2021	19:13				
ID:	C1842	Dispatch: 03	3/16/2021	14:06	Sent	0	Suppression	Ц
Туре:	60-Support apparatus, other	Arrival: 03	3/16/2021	14:06			Other	
		Clear: 03	3/16/2021	17:43				
ID:	D1802	Dispatch: 03	3/16/2021	13:11	Sent	0	Suppression	П
Туре:	92-Chief officer car	Arrival: 03	3/16/2021	13:11		_	Other	
		Clear: 03	3/16/2021	14:26				
ID:	D1803	Dispatch: 03	3/16/2021	12:44	Sent	0	Suppression	П
Туре:	92-Chief officer car	Arrival:	Ц	_			CieMS Other	
	***	Clear: 03	3/16/2021	14:26				
ID:	ED131	Dispatch: 03	3/16/2021	12:31	Sent	8	Suppression	Ц
Type:	00-Other apparatus/resource	Arrival: 03	3/19/2021	23:41			EMS Other	
		Clear: 03	3/20/2021	15:31				
ID:	HM133	Dispatch: 03	3/16/2021	13:09	Sent	0	Suppression	Ш
Туре:	93-HazMat unit	Arrival:	Ш				Other	
		Clear:						

			03/20/2021	14:52				
ID: Type:	I1850 60-Support apparatus, other	Dispatch:	03/16/2021	12:30	Sent	1	Suppression EMS Other	
		Clear:	03/17/2021	17:58				
ID:	ME131	Dispatch:	03/16/2021	12:30	Sent	4	Suppression	Ц
Туре:	11-Engine	Arrival:	03/16/2021	12:36			Other	
		Clear:	03/16/2021	15:09				
ID:	ME132	Dispatch:	03/16/2021	12:30	Sent	4	Suppression EMS	Ц
Туре:	11-Engine	Arrival:	03/16/2021	12:34			Other	
		Clear:	03/19/2021	15:43				
ID:	ME134	Dispatch:	03/16/2021	12:42	Sent	4	Suppression	
Туре:	11-Engine	Arrival:	03/16/2021	12:47			Other	
		Clear:	03/16/2021	14:43				
ID:	ME135	Dispatch:	03/16/2021	12:42	Sent	4	Suppression	
Туре:	11-Engine	Arrival:	03/16/2021	12:53			Other	
		Clear:	03/16/2021	14:47				
ID:	ID: ME136	Dispatch:	03/16/2021	12:30	Sent 4	4	Suppression EMS	11-Extinguishment by fire service personnel
Туре:	11-Engine	Arrival:	03/16/2021	12:42			Other	
		Clear:	03/17/2021	21:11				
ID:	ME137	Dispatch:	03/16/2021	13:09	Sent	4	Suppression	
Туре:	11-Engine	Arrival:	03/16/2021	13:20			Other	
		Clear:	03/16/2021	14:15				
ID:	ME138	Dispatch:	03/16/2021	13:08	Sent	4	Suppression	Ц
Туре:	11-Engine	Arrival:	03/16/2021	13:11			EMS Other	
		Clear:	03/16/2021	15:16				
ID:	ME139	Dispatch:	03/16/2021	12:42	Sent	4	Suppression	
Туре:	11-Engine	Arrival:	03/16/2021	12:54			EMS Other	
		Clear:	03/16/2021	22:13				
ID:	ME141	Dispatch:	03/16/2021	22:31	Sent	0	Suppression EMS	Ц
Type:	11-Engine	Arrival:					Other	
		Clear:	03/20/2021	14:28				
ID:	ME67	Dispatch:	03/16/2021	13;28	Sent	0	Suppression EMS	Ц
Туре:	11-Engine	Arrival:	03/16/2021	13:28			Other	
Į.								

	Clear: 03/16/2021 23:41	
ID: T131	Dispatch: 03/16/2021 12:30 Sent 4	Suppression L EMS
Type: 12-Truck or aerial	Arrival: 03/16/2021 12:38	Other
	Clear: 03/16/2021 22:02	
ID: T138	Dispatch: 03/16/2021 12:42 Sent 4	Suppression L
Type: 12-Truck or aerial	Arrival:	Other
	Clear: 03/16/2021 12:44	
ID: T139	Dispatch: 03/16/2021 12:43 Sent 4	Suppression L Lieus
Type: 12-Truck or aerial	Arrival:	Other
	Clear: 03/16/2021 20:05	
ID: T1820	Dispatch: 03/16/2021 12:37 Sent 0	Suppression L
Type: 60-Support apparatus, other	Arrival: 03/16/2021 12:37	Other
	Clear: 03/18/2021 13:36	
ID: T1822	Dispatch: 03/16/2021 12:51 Sent 0	Suppression LI EMS
Type: 60-Support apparatus, other	Arrival:	Other
	Clear: 03/16/2021 23:41	
N		

NFIRS-10 Personnel

А							
36170	CA	03	16	2021	Station 2 (132)	OF2104486	2
FDID	State	Month	Day	Year	Station	Number	Exposure

B Apparatus/Resource	Dates/Times	Sent	Number of People	Apparatus Use	Actions Taken
ID: B1806	Dispatch: 03/16/2021 12:42	Sent	1	Suppression	81-Incident command
Type: 92-Chief officer car	Arrival: 03/16/2021 12:54			□ EMS □ Other	
	Clear: 03/16/2021 15:23				
Personnel ID	Name	Rank	Role	Attend	Actions Taken
17111	Roeber, Scotland	Battalion Chief			81-Incident command
					11
ID: B1807	Dispatch: 03/16/2021 13:02	Sent	0	Suppression EMS	П
Type: 92-Chief officer car	Arrival:			Other	
	Clear: 03/18/2021 02:52				
Personnel ID	Name	Rank	Role	Attend	Actions Taken
ID: B1808	Dispatch: 03/16/2021 19:12	Sent	0	Suppression EMS	Ц
Type: 92-Chief officer car	Arrival:			□ EMS □ Other	
1,500	Clear: 03/18/2021 02:51				
Personnel ID	Name	Rank	Role	Attend	Actions Taken
	en hat.				
ID: B1811	Dispatch: 03/16/2021 19:36	Sent	0	Suppression EMS	
Type: 92-Chief officer car	Arrival:			Other	
	Clear: 03/17/2021 14:19				
Personnel ID	Name	Rank	Role	Attend	Actions Taken
ID: B1815	Dispatch: 03/16/2021 12:30	Sent	11	Suppression	
Type: 92-Chief officer car	Arrival: 03/16/2021 12:36			Suppression EMS Other	
Type: 122 cites officer con	Clear: 03/17/2021 01:41				
2 112		Rank	Role	Attend	Actions Taken
Personnel ID	Name	Battalion	Kole	Accend	Actions taken
18726	Williams, Ryan	Chief			
ID: B1825	Dispatch: 03/16/2021 12:32	Sent	1	Suppression	П
Type: 92-Chief officer car	Arrival: 03/16/2021 12:40	36110		EMS Other	_
Type. 92-chief officer car					
	Clear: 03/16/2021 19:13				
Personnel ID	Name	Rank	Role	Attend	Actions Taken
18006	Stepanian, Nicolas	Battalion Chief			<u> </u>
ID: C1842	Dispatch: 03/16/2021 14:06	Sent	0	Suppression	Ц
		C Julie	ت	EMS	_
Type: 60-Support apparatus, other	Arrival: 03/16/2021 14:06			- Cite	
	Clear: 03/16/2021 17:43				
Personnel ID	Name	Rank	Role	Attend	Actions Taken
ID: Large I	Dispatch: 00/46/0004 40.44				

	Type:	92-Chief officer car	Arrival:	03/16/2021 13:1 03/16/2021 13:1 03/16/2021 14:2	11	0	USuppression □EMS □ Other	Ц
	Personn	el ID	Name		-Rank	Role	- Attend	-Actions Taken
	ID: Type:	D1803	Dispatch: Arrival: Clear:	03/16/2021 12:4		0	Suppression EMS Other	Ц
	Personn	el ID	Name		Rank	Role	Attend	Actions Taken
	ID: Type:	ED131 00-Other apparatus/resource	Dispatch: Arrival: Clear:	03/16/2021 23:4	41	8	Suppression EMS Other	
l	Personn	el ID	Name		Rank	Role	Attend	Actions Taken
	19425		Trapani, G	eoffrey	Fire Investigation Supervisor		(0)	
	18343		Goyette, N	1atthew	Fire Captain			
	19273		Lambert, (Darrell	Fire Captain		0	Ш
	19228		Langevin,	Steve	Fire Engineer			Ц
	16923		Lewis, Rya	n	Battalion Chief		O .	Ц
	19226		Ryan, Jaco	b	Fire Captain			
	18724		Verkaik, E	ugene	Fire Captain			
	18466		Wedell, M	ichael	Battalion Chief		0	Ш
	ID: Type:	93-HazMat unit	Dispatch: Arrival: Clear:	03/16/2021 13:0		0	Suppression EMS Other	Ц
	Personn	el ID	Name		Rank	Role	Attend	Actions Taken
	ID: Type:	60-Support apparatus, other	Dispatch: Arrival: Clear:	03/16/2021 12:: 03/16/2021 12:: 03/17/2021 17::	36	1	Suppression EMS Other	Ц
	Personn	el ID	Name		Rank	Role	Attend	Actions Taken
	18721		Kloosterm	an, Daniel	Fire Investigation Supervisor	l		Ц
	ID: Type:	ME131 11-Engine	Dispatch: Arrival: Clear:	03/16/2021 12:: 03/16/2021 12:: 03/16/2021 15::	36	Pole Pole	Suppression EMS Other	Actions Taken
	Derconn	ern)	Name		Maur	HUID	CALL COLLEGE	OLLIODE LAKMU

reisonnecio	Hallic	Nanv	Kole	VICELIA	Actions taxen
20025	Bandaruk, Jason	Firefighter		0	Ц
20192	Wilson, Duncan	Firefighter		8	
19140	Hafner, Ryan	Fire Captain		8	
19344	Preston, Bryan	Fire Engineer		D	
ID: ME132 Type: 11-Engine	Dispatch: 03/16/2021 12:30 Arrival: 03/16/2021 12:34 Clear: 03/19/2021 15:43	[]Sent	4	Suppression EMS Other	Ц
Personnel ID	Name	Rank	Role	Attend	Actions Taken
20183	Clements, Cody	Firefighter			
19687	Thompson, Matthew	Fire Engineer			
19223	Gilbert, Ryan	Fire Captain		9	U
20190	Saunders, Kurt	Firefighter		0	Ц
ID: ME134 Type: 11-Engine	Dispatch: 03/16/2021 12:42 Arrival: 03/16/2021 12:47 Clear: 03/16/2021 14:43	Sent	4	Suppression EMS Other	
Personnel ID	Name	Rank	Role	Attend	Actions Taken
20205	Okamura, Thomas	Firefighter		.0	Ц
20201	Steele, Matthew	Firefighter		0	
19227	Willemse, Scott	Fire Captain			<u>U</u>
19422	Cavanaugh, Sean	Fire Engineer			Ш
ID: ME135 Type: 11-Engine	Dispatch: 03/16/2021 12:42 Arrival: 03/16/2021 12:53 Clear: 03/16/2021 14:47	Sent	4	Suppression EMS Other	П
Personnel ID	Name	Rank	Role	Attend	Actions Taken
19881	Ciszek, Brian			Ц	Ш
20199	Hoover, Lucas	Firefighter			Ш
17357	Bekins, Kurt	Fire Captain		Ē.	
19857	Zaragoza, Eric				Ц
ID: ME136 Type: 11-Engine	Dispatch: 03/16/2021 12:30 Arrival: 03/16/2021 12:42 Clear: 03/17/2021 21:11	Sent	4	Suppression EMS Other	11-Extinguishment by fire service pers
Personnel ID	Name	Rank	Role	Attend	Actions Taken
19798	Mowad, Trevor				
20327	Magrina, Joel	Firefighter		<u>u</u>	Ц
A.					11

20185	Medina, Jacob	Firefighter -	<u></u>	
16864	Spellman, Ronald	Fire Captain	•	- 🗌
ID: ME137 Type: 11-Engine	Dispatch: 03/16/2021 13:09 Arrival: 03/16/2021 13:20	Sent 4	Suppression EMS Other	
	Clear: 03/16/2021 14:15			
Personnel ID	Name	Rank Role	Attend	Actions Taken
20194	Esquivias, Jovanny	Firefighter		
19680	Garrett, Chad	Fire Engineer		
17233	De Young, Daniel	Fire Captain		
20321	Armstrong, Joshua	Firefighter		
ID: ME138 Type: 11-Engine	Dispatch: 03/16/2021 13:08 Arrival: 03/16/2021 13:11	Sent 4	Suppression EMS Other	Ц
100	Clear: 03/16/2021 15:16			
Personnel ID	Name	Rank Role	Attend	Actions Taken
		Rdik Role	Accend	
19807	Clarke, Christian			<u> </u>
16895	Nelson, Tye	Fire Captain		
20316	Hernandez, Michael	Firefighter		
20202	Powers, Brian	Firefighter		Ш
ID: ME139 Type: 11-Engine	Dispatch: 03/16/2021 12:42 Arrival: 03/16/2021 12:54 Clear: 03/16/2021 22:13	Sent 4	Suppression EMS Other	
Personnel ID	Name	Rank Role	Attend	Actions Taken
20334	Verral, Eric	Firefighter	7,000.10	
			-	
20184	Selk, Chase	Firefighter	<u> </u>	<u> </u>
19686	Talley, Steven	Fire Engineer	1.0	Ш
18902	Bethel, Richard	Fire Captain	Q	
ID: ME141 Type: 11-Engine	Dispatch: 03/16/2021	Sent 0	EMS Other	
Personnel ID	Name	Rank Role	Attend	Actions Taken
ID: ME67 Type: 11-Engine	Dispatch: 03/16/2021 13:28 Arrival: 03/16/2021 13:28 Clear: 03/16/2021 23:41	Sent 0	Suppression [JEMS [:Other	
Personnel ID	Name	Rank Role	Attend	Actions Taken
		Ple .	(Current)	
ID: T131	Dispatch: 03/16/2021 12:30	Sent	Suppression	

Type:	12-Truck or aerial	Arrival: 03/16/2021 12:38		4	Other	Ц
		Clear: 03/16/2021 22:02				
Personn	el ID	Name	Rank	Role	Attend	Actions Taken
20326		Jaquess, Tyler	Firefighter		D.	
19228		Langevin, Steve	Fire Engineer			
18724		Verkaik, Eugene	Fire Captain		0	
20032		Gamboa, Neil	Firefighter		0	
	1 1	1 11 1		1.1	100	II
ID:	T138	Dispatch: 03/16/2021 12:42	Sent	4	Suppression EMS	П
Type:	12-Truck or aerial	Arrival:			Other	
		Clear: 03/16/2021 12:44				
Personn	el ID	Name	Rank	Role	Attend	Actions Taken
19885		Morrison, Christopher				Ц
20029		Harper, Martin	Firefighter		П	Ц
18980		Van Fossen, Brian	Fire Captain			
19508		Bates, Logan	Fire Engineer		ū.	Ц
ID: Type:	T139	Dispatch: 03/16/2021 12:43 Arrival:	Sent	4	Suppression EMS Other	Ц
		Clear: 03/16/2021 20:05				
Personn	el ID	Name	Rank	Role	Attend	Actions Taken
19880		DeMartino, Noah				Ц
20214		Norbryhn, Scott	Firefighter		D	
19679		Charleston, David	Firefighter		B	
17102		Guapo, Louis	Fire Captain		9	
				1 1		11
ID:	T1820	Dispatch: 03/16/2021 12:37	Sent	0	Suppression EMS	Ц
Туре:	60-Support apparatus, other	Arrival: 03/16/2021 12:37			Other	
		Clear: 03/18/2021 13:36				
Personn	el ID	Name	Rank	Role	Attend	Actions Taken
	1 1		277.4	1.1	Title .	11
ID:	T1822	Dispatch: 03/16/2021 12:51	Sent	0	Suppression EMS Other	
Туре:	60-Support apparatus, other	Arrival:			Other	
		Clear: 03/16/2021 23:41				
Personn	el ID	Name	Rank	Role	Attend	Actions Taken

NFIRS-1S Supplemental

Α								
	36170	CA	03	16	2021	Station 2 (132)	OF2104486	2
1	FDID	State	Month	Day	Year	Station	Number	Exposure

Primary Narrative:

B 1815 was dispatched as part of the first alarm assignment to a potential structure fire at the documented address. Prior to going enroute B 1815 acknowledged Ontario Dispatch traffic stating that there were multiple explosions at the location. Due to this I immediately started EOD 131 and HM 133.

B 1815 then went responding. While enroute I observed a large column of smoke in the area of the dispatched address. I broadcast this traffic and continued in code 3.

B 1815 AOS and observed fire to the front yard and rear of house. Structure observed was a single story single family residence with significant exposure concern to the delta side. B 1815 established Francis Command. Immediately upon establishing Francis Command, B 1815 requested that OPD shut down Francis St west of Fern and east of San Antonio. B 1815 also requested a 300' perimeter be established around 428 W. Francis St.

ME 132 AOS and Francis Command assigned him as Division A. Objectives were perimeter control and victim accountability. They were advised to engage in fire attack operations only if they felt safe in doing so.

ME 131 AOS and was assigned as a rescue group. There were report of victims on the "D" side of 428 W. Francis. This information was relayed to ME 131 and they set up for potential rescue operations.

T 1820 arrived onscene and he was assigned as division D with primary objectives of perimeter control and victim accountability. ME 136 was almost immediately assigned to help out division D.

T 131 AOS and due to unit specialty their crew was split. Captain Verkaik and Engineer Langevin were assigned to the EOD group and FF Jaquess and FF Gamboa were assigned underneath division A to assist with their operation.

ME 134 was assigned as my division B. Their objectives were to establish perimeter control and provide victim accountability.

ME 139 AOS and they were assigned as division D. Their objectives were to establish perimeter control and provide victim accountability.

During the course of assigning unit to their divisional assignments a large explosion occurred. This explosion resulted in an operational retreat of all divisions. A PAR was performed and all firefighters were accounted for. No injuries were noted due to the explosion.

Fire suppression activities resumed after the explosion with safety measures applied. Large diameter hoselines were used from a safe distance.

Fire was extinguished at the documented time. Operations then transitioned into a multi day investigation operation led by Ontario FD EOD and I 1850. Please reference their report for additional information in regards to their operations.

Multi families were displaced as a result of this incident. Red Cross was used as the primary for sheltering measures.

Ultimately on Saturday late afternoon the Francis Incident was terminated and all Ontario Fire Department operations were complete.

R. Williams Fire Battalion Chief Battalion 1-B

Person/Entity Involved		Employee		South Coast Air Quality Management District	
Local Option		Person/Entity Type		Business Name (if applicable)	Phone Number
	Kamal		_][Brenner	
Mr., Ms., Mrs.	First Name		MI	Last Name	Suffix
Number	Prefix	Street or Highway		Street Type	Suffix
Post Office Box		Apt./	Suite/Room	City	
State		Zip Code			
7					

Additional Narrative (#1 of 1):

Exposure #2

The property to the east of the area of origin is 424 west Francis. This property sustained a great deal of structural damage to the house from the explosion and blast pressure. A secondary fire to the detached garage started either by radiant heat or firebrands. ME 132 utilized a master stream to protect the residence from radiant heat later in the incident.

R. Gilbert ME 132-B Captain



NFIRS-1 Basic

Α									
36170	CA	03	16	2021	Station 2 (132)	OF2104486] 3	
FDID	State	Month	Day	Year	Station	Number		Exposure	_
B Location Type					9			Census tra	act:
Intersection In Front Of Rear Of Adjacent To Directions US National Grid	428 Number	W-West Prefix	FRANC Street o	S r Highway			-Street eet Type	Suffix	
	Apt./Suite/Roo	om	City	0		CA State		762 Code	
D Aid Given Or Recei 1 Mutual Aid Recei 2 Auto. Aid Given 4 Auto. Aid Given 5 Other Aid Given	eived ved Their F		California Their State	E1 Dates an Alarm Arrival Controlled Last Unit Cleared	03 16 2021	12:29 12:34 07:03	Shift or Platoon	and Alarms 3 O-10 Alarms District Studies Value	

Actions Taken 11-Extinguishment by fire service personnel Primary Action Taken		G1 Resources Apparatus or Personne Apparatus Suppression 17 EMS 5 Other 5 Resource counts including resources.	34 12 10 10	Losses: Recknon nor Property: \$	Values: Optional	Values None None
Completed Modules 2 - Fire 3 - Structure Fire 4 - Civilian Fire Cas. 5 - Fire Service Cas. 6 - EMS 7 - HazMat 8 - Wildland Fire 9 - Apparatus 10 - Personnel 11 - Arson	Fire Service Civilian H2 Detector Required for Coni 1 - Detector	eaths Injuries	H3 Hazardous Ma 1 - Natural (2 - Propane 3 - Gasoline 4 - Kerosene 5 - Diesel Fu 6 - Househo 7 - Motor O 1 8 - Paint 0 - Other None	Gas e let / Fuet Oit ld Solvents	Mixed Use Prop Not Mixed 10 - Assembly 20 - Education 33 - Medical U 40 - Residentia 51 - Row Of St 53 - Enclosed I 58 - Business a Residential 59 - Office Use 60 - Industrial 63 - Military U 65 - Farm Use 600 - Other Mix	Use Use se al Use ores Mall and e Use
Property Use Non Structures 131 Church, Place of 161 Restaurant or Ca 162 Bar/Tavern or Ni 213 Elementary School, Jun 241 College, Adult Ed 311 Nursing Home 331 Hospital	Worship Ifeteria ghtclub Iol, Kindegarten Ior High	341 Clinic, Clinic-Type 342 Doctor/Dentist O 361 Prison or Jail, No 419 1- or 2-Family Dwe 429 MultiFamily Dwel 439 Rooming/Boardir 449 Commerical Hote 459 Residential, Boar 464 Dormitory/Barrac 519 Food and Bevera	office t Juvenile relling lling ng House el or Motel d and Care	571 Gas or Sen 579 Motor Veh 599 Business C 615 Electric-Ge 629 Laborator 700 Manufactu 819 Livestock/	icle/Boat Sales/Rep Office enerating Plant y/Science Laborator Iring Plant Poultry Storage (Ba ential Parking Gara	pairs Ty arn)
Outside 124 Playground or Pa 655 Crops or Orchard 669 Forest (Timberla 807 Outdoor Storage 919 Dump or Sanitar 931 Open Land or Fie 936 Vacant Lot	d nd) e Area y Landfill	938 Graded/Cared for 946 Lake, River, Strea 951 Railroad Right-of 960 Other Street 961 Highway/Divided 962 Residential Stree 981 Construction Site 984 Industrial Plant Y	m -Way Highway t/Driveway		a Property Use code a You have NOT checked	

K1				
Person/Entity Involved	Employee		Environmental Protection Agency	
Local Option	Person/Entity Type		Business Name (if applicable)	Phone Number
MR-Mr.	Robert		Wise	
Mr., Ms., Mrs.	First Name	MI	Last Name	Suffix
Number	Prefix	Street or High	way Street Type	Suffix
Post Office Box	Apt./Suite/Room		City	
State			Zip Code	

K2						
Owner	1					
Local Option	Person/Enti	ty Type Busines	s Name (if applicable)	Phone Number		
Mr., Ms., Mrs.	First Name	MI	Last Name	Suffix		
		J L				
Number	Prefix	Street or Highway	Street Type	Suffix		
1						
Post Office Box		Apt./Suite/Room	City			
1						
State	Zip Code					

L Remarks:

B 1815 was dispatched as part of the first alarm assignment to a potential structure fire at the documented address. Prior to going enroute B 1815 acknowledged Ontario Dispatch traffic stating that there were multiple explosions at the location. Due to this I immediately started EOD 131 and HM 133.

B 1815 then went responding. While enroute I observed a large column of smoke in the area of the dispatched address. I broadcast this traffic and continued in code 3.

B 1815 AOS and observed fire to the front yard and rear of house. Structure observed was a single story single family residence with significant exposure concern to the delta side. B 1815 established Francis Command. Immediately upon establishing Francis Command, B 1815 requested that OPD shut down Francis St west of Fern and east of San Antonio. B 1815 also requested a 300' perimeter be established around 428 W. Francis St.

ME 132 AOS and Francis Command assigned him as Division A. Objectives were perimeter control and victim accountability. They were advised to engage in fire attack operations only if they felt safe in doing so.

ME 131 AOS and was assigned as a rescue group. There were report of victims on the "D" side of 428 W. Francis. This information was relayed to ME 131 and they set up for potential rescue operations.

T 1820 arrived onscene and he was assigned as division D with primary objectives of perimeter control and victim accountability. ME 136 was almost immediately assigned to help out division ...

Full primary narrative can be found in NFIRS 1S - Supplemental

Authorization				
18726	Williams, Ryan	Battalion Chief		03/23/2021
Officer In Charge ID	Signature	Position or Rank	Assignment	Date
19223	Gilbert, Ryan	Fire Captain		03/25/2021
Member Making Report ID	Signature	Position or Rank	Assignment	Date

NFIRS-2 Fire

Α								
36	5170	CA	03	16	2021	Station 2 (132)	OF2104486	3
FDI	ID	State	Month	Day	Year	Station	Number	Exposure
Property Details B1 2 Not Residential Estimated number of residential living units in the building of origin whether or not all units became involved B2 Buildings Not Involved Number of buildings involved Number of buildings involved B3 None Less than 1 acre					iilding of	C On-Site Materials Or Products		-Site Materials orage Use
D Ignit D1 D2 D3 D4	Acres burned (outs	cterior Trom anothe		1 - li 2 - U 3 - F Source U - 4 - A U - C Investi	act of Nature Cause Under Ir Cause Undete gation	pment or Heat nvestigation rmined After ing to Ignition	Ignition Check all appli None 1 - Asleep 2 - Possibl drugs 3 - Unatte 4 - Possibl 5 - Physica 6 - Multipl	y impaired by alcohol or nded person y Mentally Disabled Illy Disabled e Persons Involved as A Factor
I ⊠ N₁	oment involved al #	n Ignition		Equipme F3 Equipme 1 - Po	ationary	e	ne or two	G Fire Suppression Factors

H1 Mobile Property Involved	H2 Mobile Property Type and Make	Local Use
1 - Not involved in ignition, but burned 2 - Involved in ignition, but did not burn 3 - Involved in ignition and burned None	Mobile Property Type Mobile Property Make	Pre-Fire Plan Available Arson Report Attached Police Report Attached Coroner Report Attached Other Reports Attached
Mobile Property Model	Year	
State License Plate Number	VIN	(

NFIRS-3 Structure Fire

	NFIRS-3 Struct	ulerile		
Structure Type 1 - Enclosed Building 2 - Portable/Mobile Structure 3 - Open Structure 4 - Air-Supported Structure 5 - Tent 6 - Open Platform 7 - Underground Structure 8 - Connective Structure 0 - Other	Building Status 1 - Under Construction 2 - In Normal Use 3 - Idle, Not Routinely Used 4 - Under Major Renovation 5 - Vacant and Secured 6 - Vacant and Unsecured 7 - Being Demolished 0 - Other U - Undetermined	Building H 1 Number of S At/Above Gr 0 Number of S Below Grade	itories ade itories	I4 Main Floor Size 1000 Total Square Feet OR BY Length (ft) X Width (ft)
J1 Fire Origin 1 Below Grade Story of Fire Origin J2 Fire Spread Confined to Object of Origin 2 - Confined to Room of Origin 3 - Confined to Floor of Origin 4 - Confined to Building of Origin 5 - Beyond Building of Origin	Number of Stories Damaged By Number of Stories w/Minor Da Number of Stories w/Significa Number of Stories w/Heavy Da Number of Stories w/Extreme *Count the roof as part of the highest	mage (1-24%) nt Damage (25-49%) amage (50-74%) Damage (75-100%)	K1 Ll lten to F	Material Contributing Flame Spread Contributing Most lame Spread of Material Contributing at To Flame Spread
L1 Presence of Detectors N - None Present 1 - Present U - Undetermined L2 Detector Type 1 - Smoke 2 - Heat 3 - Combination of Smoke and Heat 1 + Sprinkler, Water Flow Detection 5 - More Than One Type Present 0 - Other U - Undetermined	L3 Detector Power Supply 1 - Battery Only 2 - Hardwire Only 3 - Plug-In 4 - Hardwire With Battery 5 - Plug-In With Battery 6 - Mechanical 7 - Multiple Detectors & Power Supplies 0 - Other U - Undetermined L4 Detector Operation 1 - Fire Too Small To Activate 2 - Operated	2 - Alerted Od 3 - There Wer 4 - Failed to A U - Undeterm L6 Detector Failur	ecupants, Occupants, Occupants, Occupants occupation of the control of the control occupation of the control occupation occupants occupation occupation occupants occu	f, or Disconnect or Placement Dirty connected

M1	мз	M5
Presence of Automatic Extinguishing System N - None Present 1 - Present 2 - Partial System Present U - Undetermined	Operation of Automatic Extinguishing System 1 - Operated/Effective 2 - Operated/Not Effective 3 - Fire Too Small To Activate 4 - Failed To Operate 0 - Other	Reason for Automatic Extinguishing System Failure 1 - System Shut Off 2 - Not Enough Agent Discharged 3 - Agent Discharged But Did Not Reach Fire 4 - Wrong Type of System 5 - Fire Not In Area Protected 6 - System Components Damaged
M2 Type of Automatic Extinguishing System ☐ 1 - Wet-Pipe Sprinkler ☐ 2 - Dry-Pipe Sprinkler	Required if fire was within designed range	3 - Manual Intervention 0 - Other U - Undetermined Required if system failed or not effective
3 - Other Sprinkler System 4 - Dry Chemical System 5 - Foam System 6 - Halogen-Type System 7 - Carbon Dioxide System 0 - Other 1 U - Undetermined Required if fire was within designed range of AES	M4 Number of Sprinkler Heads Operating Required if system operated	

NFIRS-9 Apparatus or Resources

36170	CA	03	16	2021		OF2104486] 3
FDID	State	Month	Day	Year	Station	Number	Exposure

B Appara l	tus/Resource	Dates/Times		Sent	Number of People	Apparatus Use	Actions Taken
ID:	B1806	Dispatch: 03	3/16/2021 12:4	Sent Sent	1	Suppression	81-Incident command
Type:	92-Chief officer car	Arrival: 03	/16/2021 12:5	4		EMS Other	
,		Clear: 03	15:2	:3			
ID:	B1807	Dispatch: 03	/16/2021 13:0	2 Sent	0	Suppression EMS	
Туре:	92-Chief officer car	Arrival:				Other	
		Clear: 03	/18/2021 02:5	52			
ID:	B1808	Dispatch: 03	/16/2021 19:1	2 Sent	0	Suppression EMS	
Туре:	92-Chief officer car	Arrival:	∐			Other	
		Clear: 03	02:5	1			
ID:	B1811	Dispatch: 03	/16/2021 19:3	6 Sent	0	Suppression	
Type:	92-Chief officer car	Arrival:	Ш			Other	
		Clear: 03	/17/2021 14:1	9			
ID:	B1815	Dispatch: 03	/16/2021 12:3	Sent Sent	1	Suppression EMS	
Туре:	92-Chief officer car	Arrival: 03	/16/2021 12:3	6		Other	
		Clear: 03	01:4	1			
ID:	B1825	Dispatch: 03	/16/2021 12:3	2 Sent	1	Suppression	
Туре:	92-Chief officer car	Arrival: 03	3/16/2021 12:4	10		Other	
		Clear: 03	3/16/2021 19:1	3			
ID:	C1842	Dispatch: 03	3/16/2021 14:0	Sent	0	Suppression	
Туре:	60-Support apparatus, other	Arrival: 03	3/16/2021 14:0	16		Other	
		Clear: 03	3/16/2021 17:4	13			
ID:	D1802	Dispatch: 03	3/16/2021 13:1	1 Sent	0	Suppression	
Туре:	92-Chief officer car	Arrival: 03	3/16/2021 13:1	1		Other	
		Clear: 03	3/16/2021 14:2	26			
ID:	D1803	Dispatch: 03	3/16/2021 12:4	4 Sent	0	Suppression	
Туре:	92-Chief officer car	Arrival:				Other	
	52	Clear: 03	3/16/2021 14:2	26			
ID:	ED131	Dispatch: 03	3/16/2021 12:3	Sent	8	Suppression	
Туре:	00-Other apparatus/resource	Arrival: 03	3/19/2021 23:4	11		Other	
		Clear: 03	3/20/2021 15:3	31			
ID:	HM133	Dispatch: 03	3/16/2021 13:0	9 Sent	0	Suppression	
Туре:	93-HazMat unit	Arrival:				Other	
	: 	Clear:					

		03/20/2021	14:52			
ID: 11850	Dispatch:	03/16/2021	12:30	Sent 1	Suppression	Ш
Type: 60-Support apparatus, other	Arrival:	03/16/2021	12:36		E Other	
	Clear:	03/17/2021	17:58			
ID: ME131	Dispatch:	03/16/2021	12:30	Sent 4	Suppression	Ц
Type: 11-Engine	Arrival:	03/16/2021	12:36	_	EMS Other	
	Clear:	03/16/2021	15:09			
ID: ME132	Dispatch:	03/16/2021	12:30	Sent 4	Suppression	Ц
Type: 11-Engine	Arrival:	03/16/2021	12:34	_	EMS Other	
	Clear:	03/19/2021	15:43			
ID: ME134	Dispatch:	03/16/2021	12:42	Sent 4	Suppression	Ц
Type: 11-Engine	Arrival:	03/16/2021	12:47		EMS Other	
	Clear:	03/16/2021	14:43			
ID: ME135	Dispatch:	03/16/2021	12:42	Sent 4	Suppression EMS	Ц
Type: 11-Engine	Arrival:	03/16/2021	12:53		Other	
	Clear:	03/16/2021	14:47			
		9 19				2
ID: ME136	Dispatch:	03/16/2021	12:30	Sent 4	Suppression	11-Extinguishment by fire service personnel
Type: 11-Engine	Dispatch: Arrival:	03/16/2021	12:30 12:42	Sent 4	Suppression EMS Other	11-Extinguishment by fire service personnel
		-		Sent 4	EMS	11-Extinguishment by fire service personnel
	Arrival:	03/16/2021	12:42	Sent 4	Other Suppression	
Type: 11-Engine	Arrival: Clear:	03/16/2021	12:42		EMS Other	
Type: 11-Engine	Arrival: Clear: Dispatch:	03/16/2021 03/17/2021 03/16/2021	12:42		Other Suppression	
Type: 11-Engine	Arrival: Clear: Dispatch: Arrival:	03/16/2021 03/17/2021 03/16/2021 03/16/2021	12:42 21:11 13:09 13:20		Suppression EMS Other	
Type: 11-Engine ID: ME137 Type: 11-Engine	Arrival: Clear: Dispatch: Arrival: Clear:	03/16/2021 03/17/2021 03/16/2021 03/16/2021 03/16/2021	12:42 21:11 13:09 13:20 14:15	Sent 4	Suppression EMS Other	
Type: 11-Engine ID: ME137 Type: 11-Engine ID: ME138	Arrival: Clear: Dispatch: Arrival: Clear: Dispatch:	03/16/2021 03/17/2021 03/16/2021 03/16/2021 03/16/2021	12:42 21:11 13:09 13:20 14:15	Sent 4	Suppression EMS Other Suppression EMS Other	
Type: 11-Engine ID: ME137 Type: 11-Engine ID: ME138	Arrival: Clear: Dispatch: Arrival: Clear: Dispatch: Arrival:	03/16/2021 03/17/2021 03/16/2021 03/16/2021 03/16/2021 03/16/2021 03/16/2021	12:42 21:11 13:09 13:20 14:15 13:08	Sent 4	Suppression EMS Other Suppression EMS Other Suppression EMS Other	
Type: 11-Engine ID: ME137 Type: 11-Engine ID: ME138 Type: 11-Engine	Arrival: Clear: Dispatch: Arrival: Clear: Dispatch: Arrival: Clear:	03/16/2021 03/17/2021 03/16/2021 03/16/2021 03/16/2021 03/16/2021 03/16/2021 03/16/2021	12:42 21:11 13:09 13:20 14:15 13:08 13:11 15:16	Sent 4	Suppression EMS Other Suppression EMS Other	
Type: 11-Engine ID: ME137 Type: 11-Engine ID: ME138 Type: 11-Engine ID: ME139	Arrival: Clear: Dispatch: Arrival: Clear: Dispatch: Arrival: Clear: Dispatch:	03/16/2021 03/17/2021 03/16/2021 03/16/2021 03/16/2021 03/16/2021 03/16/2021 03/16/2021	12:42 21:11 13:09 13:20 14:15 13:08 13:11 15:16	Sent 4	Suppression EMS Other Suppression EMS Other Suppression EMS Other	
Type: 11-Engine ID: ME137 Type: 11-Engine ID: ME138 Type: 11-Engine	Arrival: Clear: Dispatch: Arrival: Clear: Dispatch: Arrival: Clear: Arrival: Arrival:	03/16/2021 03/17/2021 03/16/2021 03/16/2021 03/16/2021 03/16/2021 03/16/2021 03/16/2021 03/16/2021	12:42 21:11 13:09 13:20 14:15 13:08 13:11 15:16 12:42	Sent 4	Suppression EMS Other Suppression EMS Other Suppression EMS Other	
Type: 11-Engine ID: ME137 Type: 11-Engine ID: ME138 Type: 11-Engine ID: ME139 Type: 11-Engine	Arrival: Clear: Dispatch: Arrival: Clear: Dispatch: Arrival: Clear: Clear: Clear: Clear:	03/16/2021 03/17/2021 03/16/2021 03/16/2021 03/16/2021 03/16/2021 03/16/2021 03/16/2021 03/16/2021 03/16/2021	12:42 21:11 13:09 13:20 14:15 13:08 13:11 15:16 12:42 12:54	Sent 4 Sent 4	Suppression EMS Other Suppression EMS Other Suppression EMS Other Other	
Type: 11-Engine ID: ME137 Type: 11-Engine ID: ME138 Type: 11-Engine ID: ME139 Type: 11-Engine	Arrival: Clear: Dispatch: Arrival: Clear: Dispatch: Arrival: Clear: Dispatch: Arrival: Clear: Dispatch: Arrival:	03/16/2021 03/17/2021 03/16/2021 03/16/2021 03/16/2021 03/16/2021 03/16/2021 03/16/2021 03/16/2021 03/16/2021 03/16/2021	12:42 21:11 13:09 13:20 14:15 13:08 13:11 15:16 12:42 12:54 22:13	Sent 4 Sent 4	Suppression EMS Other Suppression EMS Other Suppression EMS Other Suppression EMS Other	
Type: 11-Engine ID: ME137 Type: 11-Engine ID: ME138 Type: 11-Engine ID: ME139 Type: 11-Engine	Arrival: Clear: Dispatch: Arrival: Clear: Dispatch: Arrival: Clear: Dispatch: Arrival: Arrival: Arrival: Arrival:	03/16/2021 03/16/2021 03/16/2021 03/16/2021 03/16/2021 03/16/2021 03/16/2021 03/16/2021 03/16/2021 03/16/2021 03/16/2021 03/16/2021	12:42 21:11 13:09 13:20 14:15 13:08 13:11 15:16 12:42 12:54 22:13	Sent 4 Sent 4	Suppression EMS Other Suppression EMS Other Suppression EMS Other Suppression EMS Other	

	Clear: 03/16/2021 23:41	
ID: T131	Dispatch: 03/16/2021 12:30 Sent 4	Suppression L
Type: 12-Truck or aerial	Arrival: 03/16/2021 12:38	Other
	Clear: 03/16/2021 22:02	
ID: T138	Dispatch: 03/16/2021 12:42 Sent 4	Suppression L EMS
Type: 12-Truck or aerial	Arrival:	Other
	Clear: 03/16/2021 12:44	
ID: T139	Dispatch: 03/16/2021 12:43 Sent 4	Suppression LI TEMS
Type: 12-Truck or aerial	Arrival:	Other
	Clear: 03/16/2021 20:05	
ID: T1820	Dispatch: 03/16/2021 12:37 Sent 0	Suppression L
Type: 60-Support apparatus, other	Arrival: 03/16/2021 12:37	Other
	Clear: 03/18/2021 13:36	
ID: T1822	Dispatch: 03/16/2021 12:51 Sent 0	Suppression LI EMS
Type: 60-Support apparatus, other	Arrival:	Other
	Clear: 03/16/2021 23:41	

NFIRS-10 Personnel

A							
36170	CA	03	16	2021	Station 2 (132)	OF2104486	3
FDID	State	Month	Day	Year	Station	Number	Exposure

B Apparatus/Resource	Dates/Times	Sent	Number of People	Apparatus Use	Actions Taken
ID: B1806	Dispatch: 03/16/2021 12:42	Sent	1	Suppression EMS	81-Incident command
Type: 92-Chief officer car	Arrival: 03/16/2021 12:54		_	Other	
	Clear: 03/16/2021 15:23				
Personnel ID	Name	Rank	Role	Attend	Actions Taken
17111	Roeber, Scotland	Battalion Chief			81-Incident command
		Cinei			
ID: B1807	Dispatch: 03/16/2021 13:02	Sent	0	Suppression	
Type: 92-Chief officer car	Arrival:			☐ EMS ☐ Other	
	Clear: 03/18/2021 02:52				
Personnel ID	Name	Rank	Role	Attend	Actions Taken
	1 11 1		1 1		11
ID: B1808	Dispatch: 03/16/2021 19:12	Sent	0	Suppression EMS	П
Type: 92-Chief officer car	Arrival:			Other	
	Clear: 03/18/2021 02:51				
Personnel ID	Name	Rank	Role	Attend	Actions Taken
In	B: 11	Sent	l.l	© Cuppersion	
ID: B1811	Dispatch: 03/16/2021 19:36	Sent	0	Suppression EMS	
Type: 92-Chief officer car	Arrival:			Other	
	Clear: 03/17/2021 14:19				
Personnel ID	Name	Rank	Role	Attend	Actions Taken
ID: B1815	Dispatch: 03/16/2021 12:30	Sent	1		Ш
Type: 92-Chief officer car	Arrival: 03/16/2021 12:36			EMS Other	
Type. Deciner officer car					
Personnel ID	Name	Rank	Role	Attend	Actions Taken
18726	Williams, Ryan	Battalion Chief			Ц
					11
ID: B1825	Dispatch: 03/16/2021 12:32	Sent	1	Suppression EMS	Ц
Type: 92-Chief officer car	Arrival: 03/16/2021 12:40			Other	
	Clear: 03/16/2021 19:13				
Personnel ID	Name	Rank	Role	Attend	Actions Taken
18006	Stepanian, Nicolas	Battalion Chief			
		Cillei			
ID: C1842	Dispatch: 03/16/2021 14:06	Sent	0	Suppression	Ц
Type: 60-Support apparatus, other	Arrival: 03/16/2021 14:06		_	EMS Other	
	Clear: 03/16/2021 17:43				
Personnel ID	Name	Rank	Role	Attend	Actions Taken
Leisoillierin	HUMIC	NUIN	Note	r Noward	restoria rensell
ID: Locan I	Dispatch: an /ac/page an ac				

Type:	92-Chief officer car	03/16/2021 Arrival: 03/16/2021 Clear: 03/16/2021	13:11	Sent	0	Suppression EMS Other	Ц
Personr	nel ID	Name			Role	Attend	- Actions Taken
		T T			1 1		11
ID: Type:	D1803 92-Chief officer car	Dispatch: 03/16/2021 Arrival:	12:44	Sent	0	Suppression EMS Other	
		Clear: 03/16/2021	14:26				
Personr	nel ID	Name		Rank	Role	Attend	Actions Taken
		1	111	(Te.:	1.1		11
ID: Type:	ED131 00-Other apparatus/resource	Dispatch: 03/16/2021 Arrival: 03/19/2021	12:31	Sent	8	Suppression EMS Other	
		Clear: 03/20/2021	15:31				
Personr	nel ID	Name		Rank	Role	Attend	Actions Taken
19425		Trapani, Geoffrey		Fire Investigation Supervisor			
18343		Goyette, Matthew		Fire Captain		D	Ц
19273		Lambert, Darrell		Fire Captain			
19228		Langevin, Steve		Fire Engineer			
16923		Lewis, Ryan		Battalion Chief		D	Ш
19226		Ryan, Jacob		Fire Captain		日	Ш
18724		Verkaik, Eugene		Fire Captain			Ш
18466		Wedell, Michael		Battalion Chief			Ц
ID: Type:	HM133 93-HazMat unit	Dispatch: 03/16/2021 Arrival:		Sent	0	Suppression JEMS Li Other	
Personr	nel ID	Name		Rank	Role	Attend	Actions Taken
Terson				T.G.III.			
ID:	11850	Dispatch: 03/16/2021	12:30	Sent	1	Suppression EMS Other	
Туре:	60-Support apparatus, other	Arrival: 03/16/2021 Clear: 03/17/2021	12:36			Other	
Personr	and ID	Name] [Rank	Role	Attend	Actions Taken
18721	ietiD	Kloosterman, Daniel		Fire	Note	Accello	LI
16721		Alousterman, Daniel		Investigation Supervisor			
ID:	ME131	Dispatch: 03/16/2021	12:30	Sent	4	Suppression	Ц
Type:	11-Engine	Arrival: 03/16/2021	12:36			Other	
		Clear: 03/16/2021	15:09				
Derconi	nel ID	Name		Dank	Pole	Attend	Actions Taken

Cisoni	ICCID	Hume	TO THE	NOIC	Accessed	Accions raken
20025		Bandaruk, Jason	Firefighter		Q.	
20192		Wilson, Duncan	Firefighter		ū,	
19140		Hafner, Ryan	Fire Captain		ij.	
19344	844 Preston, Bryan		Fire Engineer		D	Ц
ID: Type:	ME132	Dispatch: 03/16/2021 12:30 Arrival: 03/16/2021 12:34 Clear: 03/19/2021 15:43	Sent	4	Suppression EMS Other	Ц
Personr	nel ID	Name	Rank	Role	Attend	Actions Taken
20183		Clements, Cody	Firefighter		D.	
19687	· · · · · · · · · · · · · · · · · · ·	Thompson, Matthew	Fire Engineer			
19223		Gilbert, Ryan	Fire Captain		0	
20190		Saunders, Kurt	Firefighter		T)	
ID: Type:	ME134	Dispatch: 03/16/2021 12:42 Arrival: 03/16/2021 12:47 Clear: 03/16/2021 14:43	Sent	4	Suppression EMS Other	Ц
Personr	nel ID	Name	Rank	Role	Attend	Actions Taken
20205		Okamura, Thomas	Firefighter		9	
20201		Steele, Matthew	Firefighter			
19227		Willemse, Scott	Fire Captain			<u>L</u>
19422		Cavanaugh, Sean	Fire Engineer		Ω	Ц
ID: Type:	ME135	Dispatch: 03/16/2021 12:42 Arrival: 03/16/2021 12:53 Clear: 03/16/2021 14:47	Sent	4	Suppression EMS Other	
Personr	nel ID	Name	Rank	Role	Attend	Actions Taken
19881		Ciszek, Brian			4	Ц
20199		Hoover, Lucas	Firefighter		Ū.	Ц
17357		Bekins, Kurt	Fire Captain		0	
19857		Zaragoza, Eric				Ц
ID: Type:	ME136	Dispatch: 03/16/2021 12:30 Arrival: 03/16/2021 12:42 Clear: 03/17/2021 21:11	Sent	4	Suppression EMS Other	11-Extinguishment by fire service pers
Person	nel ID	Name	Rank	Role	Attend	Actions Taken
19798		Mowad, Trevor			D .	Ш
20327		Magrina, Joel	Firefighter		Ц	
I						1.1

20185	Medina, Jacob	Firefighter		Ų.	
16864	Spellman, Ronald	Fire Captain	-		•
ID: ME137 Type: 11-Engine	Dispatch: 03/16/2021 13:09 Arrival: 03/16/2021 13:20 Clear: 03/16/2021 14:15	S ent	4	Suppression EMS Other	
Personnel ID	Name	Rank	Role	Attend	Actions Taken
20194	Esquivias, Jovanny	Firefighter			Ц
19680	Garrett, Chad	Fire Engineer		U	
17233	De Young, Daniel	Fire Captain			
20321	Armstrong, Joshua	Firefighter			
ID: ME138 Type: 11-Engine	Dispatch: 03/16/2021 13:08 Arrival: 03/16/2021 13:11 Clear: 03/16/2021 15:16	Sent	4	Suppression EMS Other	
Personnel ID	Name	Rank	Role	Attend	Actions Taken
19807	Clarke, Christian			Q.	
16895	Nelson, Tye	Fire Captain		L.	Ц
20316	Hernandez, Michael	Firefighter		틴	Ш
20202	Powers, Brian	Firefighter			Ц
ID: ME139 Type: 11-Engine	Dispatch: 03/16/2021 12:42 Arrival: 03/16/2021 12:54 Clear: 03/16/2021 22:13	Sent	4	Suppression EMS Other	Ц
Personnel ID	Name	Rank	Role	Attend	Actions Taken
20334	Verral, Eric	Firefighter		E	Ц
20184	Selk, Chase	Firefighter		5	Ц
19686	Talley, Steven	Fire Engineer		Ti .	П
18902	Bethel, Richard	Fire Captain		L	
ID: ME141 Type: 11-Engine	Dispatch: 03/16/2021 22:31 Arrival:	☑ Sent	0	Suppression EMS Other	Ц
Personnel ID	Name	Rank	Role	Attend	Actions Taken
ID: ME67 Type: 11-Engine	Dispatch: 03/16/2021 13:28 Arrival: 03/16/2021 13:28 Clear: 03/16/2021 23:41	Sent	0	Suppression EMS Other	
Personnel ID	Name	Rank	Role	Attend	Actions Taken
ID: T131	Dispatch: 03/16/2021 12:30	Sent		Suppression	

Type: 12-Truck or aerial	Arrival: 03/16/2021 12:38		4	EMS Other	
Type: 12-Truck or aerial					
Personnel ID	Clear: 03/16/2021 22:02	Rank	- Role	Attend	Actions Taken
			Rote	Attend	ACCIONS TAKEN
20326	Jaquess, Tyler	Firefighter			
19228	Langevin, Steve	Fire Engineer			
18724	Verkaik, Eugene	Fire Captain		EŁ	Ц
20032	Gamboa, Neil	Firefighter		Ü	Ц
Type: 12-Truck or aerial	Dispatch: 03/16/2021 12:42 Arrival:	Sent	4	Suppression EMS Other	
Personnel ID	Name	Rank	Role	Attend	Actions Taken
19885	Morrison, Christopher			0	
20029	Harper, Martin	Firefighter			
18980	Van Fossen, Brian	Fire Captain			
19508	Bates, Logan	Fire Engineer		T1	
ID: T139 Type: 12-Truck or aerial	Dispatch: 03/16/2021 12:43 Arrival:	Sent Sent	4	Suppression EMS Other	
Personnel ID	Name	Rank	Role	Attend	Actions Taken
19880	DeMartino, Noah				Ц
20214	Norbryhn, Scott	Firefighter			
19679	Charleston, David	Firefighter		J	
17102	Guapo, Louis	Fire Captain			
ID: T1820 Type: 60-Support apparatus, other	Dispatch: 03/16/2021 12:37 Arrival: 03/16/2021 12:37 Clear: 03/18/2021 13:36	Sent	0	Suppression EMS Other	Ц
Personnel ID	Name	Rank	Role	Attend	Actions Taken
ID: T1822 Type: 60-Support apparatus, other	Dispatch: 03/16/2021 12:51 Arrival:	Sent	0	Suppression EMS Other	Ц
Personnel ID	Name	Rank	Role	Attend	Actions Taken

NFIRS-1S Supplemental

Α								
	36170	CA	03	16	2021	Station 2 (132)	OF2104486	3
	FDID	State	Month	Day	Year	Station	Number	Exposure

Primary Narrative:

B 1815 was dispatched as part of the first alarm assignment to a potential structure fire at the documented address. Prior to going enroute B 1815 acknowledged Ontario Dispatch traffic stating that there were multiple explosions at the location. Due to this I immediately started EOD 131 and HM 133.

B 1815 then went responding. While enroute I observed a large column of smoke in the area of the dispatched address. I broadcast this traffic and continued in code 3.

B 1815 AOS and observed fire to the front yard and rear of house. Structure observed was a single story single family residence with significant exposure concern to the delta side. B 1815 established Francis Command. Immediately upon establishing Francis Command, B 1815 requested that OPD shut down Francis St west of Fern and east of San Antonio. B 1815 also requested a 300' perimeter be established around 428 W. Francis St.

ME 132 AOS and Francis Command assigned him as Division A. Objectives were perimeter control and victim accountability. They were advised to engage in fire attack operations only if they felt safe in doing so.

ME 131 AOS and was assigned as a rescue group. There were report of victims on the "D" side of 428 W. Francis. This information was relayed to ME 131 and they set up for potential rescue operations.

T 1820 arrived onscene and he was assigned as division D with primary objectives of perimeter control and victim accountability. ME 136 was almost immediately assigned to help out division D.

T 131 AOS and due to unit specialty their crew was split. Captain Verkaik and Engineer Langevin were assigned to the EOD group and FF Jaquess and FF Gamboa were assigned underneath division A to assist with their operation.

ME 134 was assigned as my division B. Their objectives were to establish perimeter control and provide victim accountability.

ME 139 AOS and they were assigned as division D. Their objectives were to establish perimeter control and provide victim accountability.

During the course of assigning unit to their divisional assignments a large explosion occurred. This explosion resulted in an operational retreat of all divisions. A PAR was performed and all firefighters were accounted for. No injuries were noted due to the explosion.

Fire suppression activities resumed after the explosion with safety measures applied. Large diameter hoselines were used from a safe distance.

Fire was extinguished at the documented time. Operations then transitioned into a multi day investigation operation led by Ontario FD EOD and I 1850. Please reference their report for additional information in regards to their operations.

Multi families were displaced as a result of this incident. Red Cross was used as the primary for sheltering measures.

Ultimately on Saturday late afternoon the Francis Incident was terminated and all Ontario Fire Department operations were complete.

R. Williams Fire Battalion Chief Battalion 1-B

Person/Entity	Involved	Employee		South Coast Air Quality Management District		
Local Option		Person/Entity Type		Business Name (if applicable)	Phone Number	
1	Kamal			Brenner		
Mr., Ms., Mrs.	First Name		MI	Last Name	Suffix	
10 TO 1						
Number	Prefix	Street or Highway		Street Typ	e Suffix	
					350 U.S.	
Post Office Box		Apt./	/Suite/Room	City		
State		Zîp Code				

Additional Narrative (#1 of 1):

Exposure #3

The property parcel to the east of the area of origin is 416 west Francis. This property sustained a great deal of structural damage to the house from the explosion and blast pressure. The garage fire at 424 west Francis provided enough radiant heat to cause a vehicle fire at this location. A silver van or SUV vehicle was destroyed by fire. The fence between the two properties of 416 and 424 west Francis was also damaged by fire. Division A (ME 132) utilized a master stream to protect the residence located at 416 W. Francis.

R. Gilbert ME 132-B Captain



NFIRS-1 Basic

A								
36170	CA	03	16	2021	Station 2 (132)	OF2104486		4
FDID	State	Month	Day	Үеаг	Station	Number		Exposure
B Location Type							1	Census tract:
Street Address Intersection In Front Of Rear Of Adjacent To Directions US National Grid	428 Number	W-West Prefix	FRANCI Street o	s r Highway			-Street eet Type	Suffix
	Apt./Suite/R	oom	City)		CA	Zip C	
	Cross Street							
D Aid Given Or Recei 1 Mutual Aid Recei 2 Auto. Aid Recei 3 Mutual Aid Given 4 Auto. Aid Given 5 Other Aid Given	eived L ved Their	FDID	California Their State	E1 Dates an Alarm Arrival Controlled Last Unit Cleared	03 16 2021	12:29 12:34 07:03 15:31	В	nd Alarms 3 O-10 Alarms District Studies Value

F Actions Taken 11-Extinguishment by fire service personnel Primary Action Taken		Apparatus or Personnel Module is used. Apparatus Personnel Suppression 17 34 EMS 5 12 Other 5 10 Resource counts include aid received resources.		Contents: \$ 0		
Completed Modules 2 - Fire 3 - Structure Fire 4 - Civilian Fire Cas. 5 - Fire Service Cas. 6 - EMS 7 - HazMat 8 - Wildland Fire 9 - Apparatus 10 - Personnel 11 - Arson	Fire Service Civilian H2 Detector Required for Coni 1 - Detector	leaths Injuries	1 - Natural 2 - Propan 3 - Gasolin 4 - Keroser	Not M 10 - A 20 - E 33 - M 10 - A 10	Use Property Nixed ssembly Use ducation Use ledical Use esidential Use ow Of Stores nclosed Mall usiness and dential office Use ndustrial Use arm Use ether Mixed Use	
Property Use Nor Structures 131 Church, Place of 161 Restaurant or Ci 162 Bar/Tavern or Ni 213 Elementary School, Jur 215 High School, Jur 241 College, Adult E 311 Nursing Home 331 Hospital	Worship afeteria ightclub ool, Kindegarten nior High	341 Clinic, Clini 342 Doctor/Dei 361 Prison or Ja 419 1- or 2-Fam 429 MultiFamily 439 Rooming/B 449 Commerica 459 Residential 464 Dormitory/ 519 Food and B	ntist Office ail, Not Juvenile ily Dwelling y Dwelling Boarding House Il Hotel or Motel I, Board and Care (Barracks	Household Goods, Sa 571 — Gas or Service Statior 579 — Motor Vehicle/Boat S 599 — Business Office 615 — Electric-Generating P 629 — Laboratory/Science L 700 — Manufacturing Plant 819 — Livestock/Poultry Sto 882 — Non-Residential Park 891 — Warehouse	n Sales/Repairs Plant Laboratory orage (Barn)	
Outside 124 Playground or P 655 Crops or Orchar 669 Forest (Timberla 807 Outdoor Storag 919 Dump or Sanitar 931 Open Land or Fi 936 Vacant Lot	d and) e Area ry Landfill	938 Graded/Cai 946 Lake, River, 951 Railroad Ri 960 Other Stree 961 Highway/D 962 Residential 981 Construction	ght-of-Way et ivided Highway l Street/Driveway on Site	Property Use: Description Look up and enter a Property U description only if you have NO Property Use box.		

K 1				
Person/Entity Involved	Employee	En	vironmental Protection Agency	
Local Option	Person/Enti	ty Type Bus	iness Name (if applicable)	Phone Number
MR-Mr.	Robert		Wise	
Mr., Ms., Mrs.	First Name	MI	Last Name	Suffix
TELL				
Number	Prefix	Street or Highway	Street Type	Suffix
		I] [
Post Office Box		Apt./Suite/Room	City	
State		Zip	Code	

2					
Owner					
Local Option	Person/Enti	ity Type Business	Name (if applicable)	Phone Number	
Mr., Ms., Mrs.	First Name	MI	Last Name	Suffix	
Number	Prefix	Street or Highway	Street Type	Suffix	
Post Office Box		Apt./Suite/Room	City		
State		Zip Code			

L Remarks:

B 1815 was dispatched as part of the first alarm assignment to a potential structure fire at the documented address. Prior to going enroute B 1815 acknowledged Ontario Dispatch traffic stating that there were multiple explosions at the location. Due to this I immediately started EOD 131 and HM 133.

B 1815 then went responding. While enroute I observed a large column of smoke in the area of the dispatched address. I broadcast this traffic and continued in code 3.

B 1815 AOS and observed fire to the front yard and rear of house. Structure observed was a single story single family residence with significant exposure concern to the delta side. B 1815 established Francis Command. Immediately upon establishing Francis Command, B 1815 requested that OPD shut down Francis St west of Fern and east of San Antonio. B 1815 also requested a 300' perimeter be established around 428 W. Francis St.

ME 132 AOS and Francis Command assigned him as Division A. Objectives were perimeter control and victim accountability. They were advised to engage in fire attack operations only if they felt safe in doing so.

ME 131 AOS and was assigned as a rescue group. There were report of victims on the "D" side of 428 W. Francis. This information was relayed to ME 131 and they set up for potential rescue operations.

T 1820 arrived onscene and he was assigned as division D with primary objectives of perimeter control and victim accountability. ME 136 was almost immediately assigned to help out division ...

Full primary narrative can be found in NFIRS 1S - Supplemental

Authorization				
18726	Williams, Ryan	Battalion Chief		03/23/2021
Officer In Charge ID	Signature	Position or Rank	Assignment	Date
19223	Gilbert, Ryan	Fire Captain		03/25/2021
Member Making Report II) Signature	Position or Rank	Assignment	Date

NFIRS-2 Fire

Α									
	36170	CA	03	16	2021		OF2104486	4	
F	DID	State	Month	Day	Year	Station	Number	Exposure	
B Pro	Estimated number origin whether or r	of residenti not all units		olved	ilding of	C On-Site Materials Or Products		-Site Materials orage Use	
В	Number of building Acres burned (outs	gs involved None		an 1 acre					
D				E1			E3		
Igr	ition				of Ignition		Human Facto	ors Contributing to	
D D	Area of Fire Origin 80-Heat spread fro fire, other Heat Source	n .		2 - U 3 - Fo Source U 4 - A 5 - C	ct of Nature ause Under I ause Undete	pment or Heat	Check all appli None 1 - Asleep 2 - Possibl drugs 3 - Unatte 4 - Possibl 5 - Physica 6 - Multipl	y impaired by alcohol or nded person y Mentally Disabled Illy Disabled e Persons Involved	
D	Type of Material F	irst Ignited		71-Ex	rs Contributions on the contributing to the contributions of the contribution	y to Ignition 7 - Age Was A Factor Estimated Age of Person Involved Male Female			
Equi	uipment Involved I None uipment Involved rand	n Ignition		Equipmer F3 Equipme 1 - Pool 2 - Sta	tionary	re	ne or two	G Fire Suppression Factors	

H1 Mobile Property Involved 1 - Not involved in ignition, but burned 2 - Involved in ignition, but did not burn 3 - Involved in ignition and burned None	H2 Mobile Property Type and Make Mobile Property Type Mobile Property Make	Pre-Fire Plan Available Arson Report Attached Police Report Attached Coroner Report Attached Other Reports Attached
Mobile Property Model State License Plate Number	Year VIN	

NFIRS-3 Structure Fire

NFIRS-3 SUIUCUIE FIIE								
Structure Type 1 - Enclosed Building 2 - Portable/Mobile Structure 3 - Open Structure 4 - Air-Supported Structure 5 - Tent 6 - Open Platform 7 - Underground Structure 8 - Connective Structure 0 - Other	Building Status 1 - Under Construction 2 - In Normal Use 3 - Idle, Not Routinely Used 4 - Under Major Renovation 5 - Vacant and Secured 6 - Vacant and Unsecured 7 - Being Demolished 0 - Other U - Undetermined	Building Ho 1 Number of S At/Above Gra 0 Number of S Below Grade	tories ade tories	Main Floor Size 1000 Total Square Feet OR BY Length (ft) X Width (ft)				
J1 Fire Origin 1 Below Grade Story of Fire Origin J2 Fire Spread Confined to Object of Origin 2 - Confined to Room of Origin 3 - Confined to Floor of Origin 4 - Confined to Building of Origin 5 - Beyond Building of Origin	Number of Stories Damaged By Flat Number of Stories w/Minor Dama Number of Stories w/Significant Number of Stories w/Heavy Dam Number of Stories w/Extreme Date *Count the roof as part of the highest st	age (1-24%) Damage (25-49%) age (50-74%) nmage (75-100%)	K1 L ltem to Fla	Material Contributing Flame Spread Contributing Most ame Spread of Material Contributing To Flame Spread				
Presence of Detectors N - None Present 1 - Present U - Undetermined	L3 Detector Power Supply 1 - Battery Only 2 - Hardwire Only 3 - Plug-In 4 - Hardwire With Battery 5 - Plug-In With Battery 6 - Mechanical		cupants, Occ cupants, Occ e No Occupa lert Occupar					
L2 Detector Type 1 - Smoke 2 - Heat 3 - Combination of Smoke and Heat 4 - Sprinkler, Water Flow Detection 5 - More Than One Type Present 0 - Other U - Undetermined	7 - Multiple Detectors & Power Supplies 0 - Other U - Undetermined L4 Detector Operation 1 - Fire Too Small To Activate 2 - Operated 3 - Failed To Operate U - Undetermined	L6 Detector Failure Reason 1 1 - Power Failure, Shutoff, or Disconnect 2 - Improper Installation or Placement 3 - Defective 4 - Lack of Maintenance, Dirty 5 - Battery Missing or Disconnected 6 - Battery Discharged or Dead 0 - Other U - Undetermined						

M1	M3	M5
Presence of Automatic Extinguishing System	Operation of Automatic Extinguishing System	Reason for Automatic Extinguishing System Failure
M2 Type of Automatic Extinguishing System 1 - Wet-Pipe Sprinkler 2 - Dry-Pipe Sprinkler	1 - Operated/Effective 2 - Operated/Not Effective 3 - Fire Too Small To Activate 4 - Failed To Operate 0 - Other U - Undetermined Required if fire was within designed range	1 - System Shut Off 2 - Not Enough Agent Discharged 3 - Agent Discharged But Did Not Reach Fire 4 - Wrong Type of System 5 - Fire Not In Area Protected 6 - System Components Damaged 7 - Lack of Maintenance 8 - Manual Intervention 0 - Other U - Undetermined Required if system failed or not effective
3 - Other Sprinkler System 4 - Dry Chemical System 5 - Foam System 6 - Halogen-Type System 7 - Carbon Dioxide System 0 - Other U - Undetermined Required if fire was within designed range of AES	M4 Number of Sprinkler Heads Operating Required if system operated	

NFIRS-9 Apparatus or Resources

1							
36170	CA	03	16	2021	Station 2 (132)	OF2104486	4
FDID	State	Month	Day	Year	Station	Number	Exposure

B Apparatus/Resource	Dates/Times	Sent	Number of People	Apparatus Use	Actions Taken
ID: B1806 Type: 92-Chief officer car	Dispatch: 03/16/2021 12:42 Arrival: 03/16/2021 12:54 Clear: 03/16/2021 15:23	Sent	1	Suppression EMS Other	81-Incident command
ID: B1807 Type: 92-Chief officer car	Dispatch: 03/16/2021 13:02 Arrival:	Sent	0	Suppression EMS Other	
ID: B1808 Type: 92-Chief officer car	Dispatch: 03/16/2021 19:12 Arrival:	- Sent	0	Suppression EMS Other	
ID: B1811 Type: 92-Chief officer car	Dispatch: 03/16/2021 19:36 Arrival:	Sent	0	Suppression EMS Other	
ID: B1815 Type: 92-Chief officer car	Dispatch: 03/16/2021 12:30 Arrival: 03/16/2021 12:36 Clear: 03/17/2021 01:41	Sent	1	Suppression EMS Other	
ID: B1825 Type: 92-Chief officer car	Dispatch: 03/16/2021 12:32 Arrival: 03/16/2021 12:40 Clear: 03/16/2021 19:13	Sent	1	Suppression EMS Other	
ID: C1842 Type: 60-Support apparatus, other	Dispatch: 03/16/2021 14:06 Arrival: 03/16/2021 14:06 Clear: 03/16/2021 17:43	Sent	0	Suppression EMS Other	
ID: D1802 Type: 92-Chief officer car	Dispatch: 03/16/2021 13:11 Arrival: 03/16/2021 13:11 Clear: 03/16/2021 14:26	Sent	0	Suppression JEMS Other	Ц
ID: D1803 Type: 92-Chief officer car	Dispatch: 03/16/2021 12:44 Arrival: 1 Clear: 03/16/2021 14:26	Sent	0	Suppression EMS Other	
ID: ED131 Type: 00-Other apparatus/resource	Dispatch: 03/16/2021 12:31 Arrival: 03/19/2021 23:41 Clear: 03/20/2021 15:31	Sent	8	USuppression UEMS Other	
ID: HM133 Type: 93-HazMat unit	Dispatch: 03/16/2021 13:09 Arrival:	Sent	0	Suppression EMS Other	

		03/20/2021	14:52			
ID: [11850]	Dispatch:		12:30	Sent 1	Suppression	
Type: 60-Support apparatus, other	Arrival:		12:36		Other	
	Clear:	03/17/2021	17:58			
ID: ME131	Dispatch:	03/16/2021	12:30	Sent 4	Suppression	
Type: 11-Engine	Arrival:	03/16/2021	12:36		Other	
	Clear:	03/16/2021	15:09			
ID: ME132	Dispatch:	03/16/2021	12:30	Sent 4	Suppression EMS	
Type: 11-Engine	Arrival:	03/16/2021	12:34		Other	
	Clear:	03/19/2021	15:43			
ID: ME134	Dispatch:	03/16/2021	12:42	Sent 4	USuppression EMS	Ц
Type: 11-Engine	Arrival:	03/16/2021	12:47		Other	
	Clear:	03/16/2021	14:43			
ID: ME135	Dispatch:	03/16/2021	12:42	Sent 4	Suppression EMS	Ш
Type: 11-Engine	Arrival:	03/16/2021	12:53		Other	
	Clear:	03/16/2021	14:47			
ID: ME136	Dispatch:	03/16/2021	12:30	Sent 4	Suppression EMS	11-Extinguishment by fire service personnel
Type: 11-Engine	Arrival:	03/16/2021	12:42		Other	
	Clear:	03/17/2021	21:11			
ID: ME137	Dispatch:	03/16/2021	13:09	Sent 4	Suppression JEMS	
Type: 11-Engine	Arrival:	03/16/2021	13:20		Other	
	Clear:	03/16/2021	14:15			
ID: ME138	Dispatch:	03/16/2021	13:08	Sent 4	Suppression SEMS	
Type: 11-Engine	Arrival:	03/16/2021	13:11		Other	
	Clear:	03/16/2021	15:16			
ID: ME139	Dispatch:	03/16/2021	12:42	Sent 4	Suppression EMS	П
Type: 11-Engine	Arrival:	03/16/2021	12:54		Other	
	Clear:	03/16/2021	22:13			
ID: ME141	Dispatch:	03/16/2021	22:31	Sent 0	Suppression EMS	
Type: 11-Engine	Arrival:	ШШ			Other	
	Clear:	03/20/2021	14:28			
ID: ME67	Dispatch:	03/16/2021	13:28	Sent 0	Suppression EMS	
Type: 11-Engine	Arrival:	03/16/2021	13:28		EMS Other	

	Clear: 03/16/2021 23:41	
ID: T131 Type: 12-Truck or aerial	Dispatch: 03/16/2021 12:30 Sent 4 Arrival: 03/16/2021 12:38	Suppression EMS Other
	Clear: 03/16/2021 22:02	
ID: T138 Type: 12-Truck or aerial	Dispatch: 03/16/2021 12:42 Sent 4 Arrival:	Suppression EMS Other
ID: T139 Type: 12-Truck or aerial	Dispatch: 03/16/2021 12:43 Sent 4 Arrival:	Suppression L JEMS Other
ID: T1820 Type: 60-Support apparatus, other	Dispatch: 03/16/2021 12:37 Sent 0 Arrival: 03/16/2021 12:37 Clear: 03/18/2021 13:36	Suppression L EMS Other
ID: T1822 Type: 60-Support apparatus, other	Dispatch: 03/16/2021 12:51 Sent 0 Arrival:	Suppression EMS Other

NFIRS-10 Personnel

4							
36170	CA	03	16	2021	Station 2 (132)	OF2104486	4
FDID	State	Month	Day	Year	Station	Number	Ехроѕиге

B Apparatus/Resource	Dates/Times	Sent	Number of People	Apparatus Use	Actions Taken
ID: B1806 Type: 92-Chief officer car	Dispatch: 03/16/2021 12:42 Arrival: 03/16/2021 12:54 Clear: 03/16/2021 15:23	Sent Sent	1	Suppression EMS Other	81-Incident command
Personnel ID	Name	Rank	Role	Attend	Actions Taken
17111	Roeber, Scotland	Battalion Chief		Ω	81-Incident command
ID: B1807 Type: 92-Chief officer car	Dispatch: 03/16/2021 13:02 Arrival:	Sent	0	Suppression EMS Other	
Personnel ID	Name	Rank	Role	Attend	Actions Taken
ID: B1808 Type: 92-Chief officer car	Dispatch: 03/16/2021 19:12 Arrival:	Sent	0	Suppression JEMS Other	
Personnel ID	Name	Rank	Role	Attend	Actions Taken
ID: B1811 Type: 92-Chief officer car	Dispatch: 03/16/2021 19:36 Arrivat:	Sent	0	Suppression EMS Other	
Personnel ID	Name	Rank	Role	Attend	Actions Taken
ID: B1815 Type: 92-Chief officer car	Dispatch: 03/16/2021 12:30 Arrival: 03/16/2021 12:36 Clear: 03/17/2021 01:41	Sent	1	Suppression EMS Other	
Personnel ID	Name	Rank	Role	Attend	Actions Taken
18726	Williams, Ryan	Battalion Chief			Ц
ID: B1825 Type: 92-Chief officer car	Dispatch: 03/16/2021 12:32 Arrival: 03/16/2021 12:40 Clear: 03/16/2021 19:13	Sent	1	Suppression EMS Other	
Personnel ID	Name	Rank	Role	Attend	Actions Taken
18006	Stepanian, Nicolas	Battalion Chief		þ	Ц
ID: C1842 Type: 60-Support apparatus, other	Dispatch: 03/16/2021 14:06 Arrival: 03/16/2021 14:06 Clear: 03/16/2021 17:43	Sent	0	Suppression EMS Other	
Personnel ID	Name	Rank	Role	Attend	Actions Taken
In. Larani	Dispatch: Lagraciona Lagraci				

Type:	92-Chief officer car	Arrival:		13:11	Sent	0	Suppression EMS Other	
Personn	and ID	Name	03/10/2021	14.20	- -Rank	Role	- Attend	-Actions Taken
Personn	etib	Name			Rank	Rote	- Accend	- Accions Fanci
ID: Type:	D1803 92-Chief officer car	Dispatch: Arrival: Clear:	 	12:44	Sent	0	Suppression EMS Other	
			03/10/2021	14.20				
Personn	elID	Name			Rank	Role	Attend	Actions Taken
ID: Type:	ED131 00-Other apparatus/resource	Dispatch: Arrival: Clear:	03/16/2021	12:31 23:41 15:31	Sent	8	Suppression SMS Other	
Personn	nel ID	Name	L		Rank	Role	Attend	Actions Taken
19425		Trapani, G	eoffrey		Fire Investigation Supervisor		13	
18343		Goyette, N	1atthew		Fire Captain			
19273		Lambert, í	Darrell		Fire Captain			
19228		Langevin,	Steve		Fire Engineer		П	
16923		Lewis, Rya	n		Battalion Chief		Ħ	Ц
19226		Ryan, Jaco	b		Fire Captain		0	Ш
18724		Verkaik, E	ıgene		Fire Captain		5	
18466		Wedell, M	ichael		Battalion Chief			Ц
ID: Type:	93-HazMat unit	Dispatch: Arrival: Clear:	03/16/2021	13:09	Sent	0	Suppression EMS Other	Ц
Personr	nel ID	Name			Rank	Role	Attend	Actions Taken
ID: Type:	60-Support apparatus, other	Dispatch: Arrival: Clear:	03/16/2021	12:30 12:36 17:58	Sent	1	Suppression UEMS Other	Ц
Personr	nel ID	Name			Rank	Role	Attend	Actions Taken
18721		Kloosterm	an, Daniel		Fire Investigation Supervisor			Ц
ID: Type:	ME131	Dispatch: Arrival: Clear:	03/16/2021	12:36 12:36 15:09	Sent	4	L. Suppression EMS Other	L. Asticos Toloro
Dercont	ALI ILA	Name			Pank	Pole	Attend	Artions Taken

Leranimerin	1401116	Nativ Note	Accina	ACTIONS TORON
20025	Bandaruk, Jason	Firefighter	ā.	
20192	Wilson, Duncan	Firefighter		
19140	Hafner, Ryan	Fire Captain	Į.	
19344	Preston, Bryan	Fire Engineer	D	
ID: ME132 Type: 11-Engine	Dispatch: 03/16/2021 12:30 Arrival: 03/16/2021 12:34 Clear: 03/19/2021 15:43	€Sent 4	Suppression EMS Other	
Personnel ID	Name	Rank Role	Attend	Actions Taken
20183	Clements, Cody	Firefighter		Ц
19687	Thompson, Matthew	Fire Engineer	B	Ц
19223	Gilbert, Ryan	Fire Captain		Ц
20190	Saunders, Kurt	Firefighter	Ü	
ID: ME134 Type: 11-Engine	Dispatch: 03/16/2021 12:42 Arrival: 03/16/2021 12:47 Clear: 03/16/2021 14:43	Sent 4	Suppression EMS Other	
Personnel ID	Name	Rank Role	Attend	Actions Taken
20205	Okamura, Thomas	Firefighter	0.	
20201	Steele, Matthew	Firefighter	O	
19227	Willemse, Scott	Fire Captain		Ц
19422	Cavanaugh, Sean	Fire Engineer		
ID: ME135 Type: 11-Engine	Dispatch: 03/16/2021 12:42 Arrival: 03/16/2021 12:53 Clear: 03/16/2021 14:47	Sent 4	Suppression EMS Other	
Personnel ID	Name	Rank Role	Attend	Actions Taken
19881	Ciszek, Brian			Ш
20199	Hoover, Lucas	Firefighter		Ц
17357	Bekins, Kurt	Fire Captain		
19857	Zaragoza, Eric		g.	
ID: ME136 Type: 11-Engine	Dispatch: 03/16/2021 12:30 Arrival: 03/16/2021 12:42 Clear: 03/17/2021 21:11	Sent 4	Suppression LEMS Other	11-Extinguishment by fire service pers
Personnel ID	Name	Rank Role	Attend	Actions Taken
19798	Mowad, Trevor		<u>d</u>	
20327	Magrina, Joel	Firefighter	tt	Ш

20185	Medina, Jacob	Firefighter	1.1	1.1
16864	Spellman, Ronald	Fire Captain	P	· 📙
ID: ME137 Type: 11-Engine	Dispatch: 03/16/2021 13:09 Arrival: 03/16/2021 13:20 Clear: 03/16/2021 14:15	Sent 4	Suppression EMS Other	
Personnel ID	Name	Rank Role	Attend	Actions Taken
20194	Esquivias, Jovanny	Firefighter	D.	П
19680	Garrett, Chad	Fire Engineer		
17233	De Young, Daniel	Fire Captain		Ш
20321	Armstrong, Joshua	Firefighter	L	L
ID: ME138 Type: 11-Engine	Dispatch: 03/16/2021 13:08 Arrival: 03/16/2021 13:11 Clear: 03/16/2021 15:16	Sent 4	Suppression EMS Other	
Personnel ID	Name	Rank Role	Attend	Actions Taken
19807	Clarke, Christian		팃	Ц
16895	Nelson, Tye	Fire Captain	D	Ц
20316	Hernandez, Michael	Firefighter	딮	
20202	Powers, Brian	Firefighter		Ц
ID: ME139 Type: 11-Engine	Dispatch: 03/16/2021 12:42 Arrival: 03/16/2021 12:54 Clear: 03/16/2021 22:13	Sent 4	Suppression EMS Other	
Personnel ID	Name	Rank Role	Attend	Actions Taken
20334	Verral, Eric	Firefighter	6	Ц
20184	Selk, Chase	Firefighter	- D	
19686	Talley, Steven	Fire Engineer	a	Ц
18902	Bethel, Richard	Fire Captain	GI	
ID: ME141 Type: 11-Engine	Dispatch: 03/16/2021 22:31 Arrival:	Sent 0	Suppression EMS Other	Ц
Personnel ID	Name	Rank Role	Attend	Actions Taken
ID: ME67 Type: 11-Engine	Dispatch: 03/16/2021 13:28 Arrival: 03/16/2021 13:28 Clear: 03/16/2021 23:41	[:Sent o	Suppression EMS Other	Ц
Personnel ID	Name	Rank Role	Attend	Actions Taken
ID: T131	Dispatch: 03/16/2021 12:30	Sent	Suppression	

				4	EMS	Ц
Type:	12-Truck or aerial	Arrival: 03/16/2021 12:38			Other	_
		Clear: 03/16/2021 22:02				
Personn	el ID	Name	Rank	Role	Attend	Actions Taken
20326		Jaquess, Tyler	Firefighter		Ů.	
19228		Langevin, Steve	Fire Engineer		Н	
18724		Verkaik, Eugene	Fire Captain		5	Ц
20032		Gamboa, Neil	Firefighter		U.	Ц
ID: Type:	T138	Dispatch: 03/16/2021 12:42 Arrival:	Ed Sent	4	Suppression EMS Other	Ц
Personn	el ID	Name	Rank	Role	Attend	Actions Taken
19885		Morrison, Christopher			d	Ц
20029		Harper, Martin	Firefighter			
18980		Van Fossen, Brian	Fire Captain		ø	Ш
19508		Bates, Logan	Fire Engineer			Ц
ID: Type:	T139	Dispatch: 03/16/2021 12:43 Arrival:	Sent	4	Suppression EMS Other	
Personn	el ID	Name	Rank	Role	Attend	Actions Taken
19880		DeMartino, Noah			D	Ш
20214		Norbryhn, Scott	Firefighter		Ü.	
19679		Charleston, David	Firefighter			Ц
17102		Guapo, Louis	Fire Captain		0	
ID: Type:	T1820 60-Support apparatus, other	Dispatch: 03/16/2021 12:37 Arrival: 03/16/2021 12:37 Clear: 03/18/2021 13:36	Sent	0	Suppression EMS Other	Ц
Personn	el ID	Name	Rank	Role	Attend	Actions Taken
ID: Type:	T1822 60-Support apparatus, other	Dispatch: 03/16/2021 12:51 Arrival:	Sent	0	Suppression EMS Other	Ц
Degrana	alip		Rank	Role	Attend	Actions Taken
Personn	et ID	Name	r(d) K	KULE	ALLEHU	WOUGHS LOVELL

NFIRS-1S Supplemental

A								
	36170	CA	03	16	2021	Station 2 (132)	OF2104486	4
	FDID	State	Month	Day	Year	Station	Number	Exposure

Primary Narrative:

B 1815 was dispatched as part of the first alarm assignment to a potential structure fire at the documented address. Prior to going enroute B 1815 acknowledged Ontario Dispatch traffic stating that there were multiple explosions at the location. Due to this I immediately started EOD 131 and HM 133.

B 1815 then went responding. While enroute I observed a large column of smoke in the area of the dispatched address. I broadcast this traffic and continued in code 3.

B 1815 AOS and observed fire to the front yard and rear of house. Structure observed was a single story single family residence with significant exposure concern to the delta side. B 1815 established Francis Command. Immediately upon establishing Francis Command, B 1815 requested that OPD shut down Francis St west of Fern and east of San Antonio. B 1815 also requested a 300' perimeter be established around 428 W. Francis St.

ME 132 AOS and Francis Command assigned him as Division A. Objectives were perimeter control and victim accountability. They were advised to engage in fire attack operations only if they felt safe in doing so.

ME 131 AOS and was assigned as a rescue group. There were report of victims on the "D" side of 428 W. Francis. This information was relayed to ME 131 and they set up for potential rescue operations.

T 1820 arrived onscene and he was assigned as division D with primary objectives of perimeter control and victim accountability. ME 136 was almost immediately assigned to help out division D.

T 131 AOS and due to unit specialty their crew was split. Captain Verkaik and Engineer Langevin were assigned to the EOD group and FF Jaquess and FF Gamboa were assigned underneath division A to assist with their operation.

ME 134 was assigned as my division B. Their objectives were to establish perimeter control and provide victim accountability.

ME 139 AOS and they were assigned as division D. Their objectives were to establish perimeter control and provide victim accountability.

During the course of assigning unit to their divisional assignments a large explosion occurred. This explosion resulted in an operational retreat of all divisions. A PAR was performed and all firefighters were accounted for. No injuries were noted due to the explosion.

Fire suppression activities resumed after the explosion with safety measures applied. Large diameter hoselines were used from a safe distance.

Fire was extinguished at the documented time. Operations then transitioned into a multi day investigation operation led by Ontario FD EOD and I 1850. Please reference their report for additional information in regards to their operations.

Multi families were displaced as a result of this incident. Red Cross was used as the primary for sheltering measures.

Ultimately on Saturday late afternoon the Francis Incident was terminated and all Ontario Fire Department operations were complete.

R. Williams Fire Battalion Chief Battalion 1-B

Person/Entity Involved		Employee		South Coast Air Quality Management District		
Local Option		Person/Entity Type		Business Name (if applicable)	Phone Number	
Mr., Ms., Mrs.	First Name		MI	Last Name		Suffix
		Copley]
Number	Prefix	Street or Highway		Street Type		Suffix
][
Post Office Box		Apt./	Suite/Room	City		
State		Zip Code				

Additional Narrative (#1 of 1):

Exposure #4

The property of 1736 Fern is referred to as exposure 4 and is located in Division D during the incident. This property sustained a great deal of structural damage to the house from the explosion and blast pressure. The thermal effect from the explosion caused secondary fires to start either by radiant heat or firebrands on the west end of the property. The structure involved was approximately 15 x 30 feet and appeared to be a shed or patio cover.

R. Gilbert ME 132-B Captain



NFIRS-1 Basic

Α									
36170	CA	03	16	2021	Station 2 (132)	OF2104486		5	
FDID	State	Month	Day	Year	Station	Number		Ехроѕиге	======
B Location Type Street Address Intersection In Front Of Rear Of Adjacent To Directions US National Grid	428 Number Apt./Suite/Ro	W-West Prefix	Street o ONTARIO City	r Highway			-Street eet Type 9176 Zip Co		ract:
C Incident Type 1111-Building fire D Aid Given Or Recei 1 Mutual Aid Rece 2 Auto. Aid Rece 3 Mutual Aid Give 4 Auto. Aid Giver 5 Other Aid Giver None	eived Loved Their F	FDID Incident Num	California Their State	Alarm Arrival Controlled Last Unit Cleared	03 16 2021	12:29 12:34 07:03 15:31			

F Actions Taken 11-Extinguishment by fire services Primary Action Taken	service personnel	G1 Resources Apparatus or Personnel Apparatus Suppression 17 EMS 5 Other 5 Resource counts include resources.	Personnel 34 12 10	Losses: Required for all fires if known. Optional for all non-fires. Property: \$ 0 Contents: \$ 0 Pre-Incident Values: Optional Property: \$ 0 Contents: \$ 0		Values None None
Completed Modules 2 - Fire 3 - Structure Fire 4 - Civilian Fire Cas. 5 - Fire Service Cas. 6 - EMS 7 - HazMat 8 - Wildland Fire 9 - Apparatus 10 - Personnel 11 - Arson	Fire Service Civilian H2 Detector Required for Conf	eaths Injuries	H3 Hazardous Mat 1 - Natural Ga 2 - Propane C 3 - Gasoline 4 - Kerosene 5 - Diesel Fue 6 - Household 7 - Motor Oil 8 - Paint 0 - Other None	as ias al/Fuel Oil d Solvents	Mixed Use Prop Not Mixed 10 - Assembly 20 - Education 33 - Medical Us 40 - Residential 51 - Row Of Sta 53 - Enclosed M 58 - Business a Residential 59 - Office Use 60 - Industrial 63 - Military Us 65 - Farm Use 00 - Other Mixe	Use Use ie I Use ores Aall nd
Property Use Non Structures 131 Church, Place of 161 Restaurant or Ca 162 Bar/Tavern or Ni 213 Elementary School, Jun 241 College, Adult Ed 311 Nursing Home 331 Hospital	Worship Ifeteria ghtclub ool, Kindegarten ior High	341 Clinic, Clinic-Type I 342 Doctor/Dentist Of 361 Prison or Jail, Not 419 1- or 2-Family Dwell 439 Rooming/Boarding 449 Commerical Hotel 459 Residential, Board 464 Dormitory/Barracl 519 Food and Beverag	fice Juvenile Illing ing g House or Motel and Care	571 Gas or Ser 579 Motor Veh 599 Business C 615 Electric-Ge 629 Laborator 700 Manufactu 819 Livestock/	nicle/Boat Sales/Rep Office enerating Plant y/Science Laborator uring Plant (Poultry Storage (Ba lential Parking Garag	airs y rn)
Outside 124 Playground or Pa 655 Crops or Orchard 669 Forest (Timberla 807 Outdoor Storage 919 Dump or Sanitar 931 Open Land or Fid 936 Vacant Lot	d nd) e Area y Landfill	938 Graded/Cared for 946 Lake, River, Strean 951 Railroad Right-of-N 960 Other Street 961 Highway/Divided I 962 Residential Street 981 Construction Site 984 Industrial Plant Ya	n Nay Highway /Driveway		a Property Use code ar you have NOT checked	

K1				
Person/Entity Involved	Employee	Envi	ronmental Protection Agency	
Local Option	Person/Ent	ity Type Busin	ness Name (if applicable)	Phone Number
MR-Mr.	Robert		Wise	
Mr., Ms., Mrs.	First Name MI		Last Name	Suffix
Number	Prefix	Street or Highway	Street Type	Suffix
Post Office Box		Apt./Suite/Room	City	
State		Zip C	ode	

K2					
Owner					
Local Option	Person/Ent	ity Type Busines	s Name (if applicable)	Phone Number	
		JL	1[
Mr., Ms., Mrs.	First Name	MI	Last Name	Suffix	
Number	Prefix	Street or Highway	Street Type	Suffix	
Post Office Box		Apt./Suite/Room	City		
State		Zip Cod	e		

L Remarks:

B 1815 was dispatched as part of the first alarm assignment to a potential structure fire at the documented address. Prior to going enroute B 1815 acknowledged Ontario Dispatch traffic stating that there were multiple explosions at the location. Due to this I immediately started EOD 131 and HM 133.

B 1815 then went responding. While enroute I observed a large column of smoke in the area of the dispatched address. I broadcast this traffic and continued in code 3.

B 1815 AOS and observed fire to the front yard and rear of house. Structure observed was a single story single family residence with significant exposure concern to the delta side. B 1815 established Francis Command. Immediately upon establishing Francis Command, B 1815 requested that OPD shut down Francis St west of Fern and east of San Antonio. B 1815 also requested a 300' perimeter be established around 428 W. Francis St.

ME 132 AOS and Francis Command assigned him as Division A. Objectives were perimeter control and victim accountability. They were advised to engage in fire attack operations only if they felt safe in doing so.

ME 131 AOS and was assigned as a rescue group. There were report of victims on the "D" side of 428 W. Francis. This information was relayed to ME 131 and they set up for potential rescue operations.

T 1820 arrived onscene and he was assigned as division D with primary objectives of perimeter control and victim accountability. ME 136 was almost immediately assigned to help out division ...

Full primary narrative can be found in NFIRS 1S - Supplemental

M Authorization				
18726	Williams, Ryan	Battalion Chief		03/23/2021
Officer In Charge ID	Signature	Position or Rank	Assignment	Date
19223	Gilbert, Ryan	Fire Captain		03/25/2021
Member Making Report ID	Signature	Position or Rank	Assignment	Date

NFIRS-2 Fire

A 36	5170 C	Ά	03	16	2021		OF2104486	5		
FD	ID Sta	ate	Month	L Day	Year	Station	Number	Exposure		
B Prop	erty Details					C On-Site Materials	On-	Site Materials		
B1	2	Not Re	sidential			Or Products		rage Use		
	Estimated number of rorigin whether or not a	esidentia all units b	l living unit ecame invo	s in the bu	ilding of					
B2		Buildin	gs No t Inv	olved		2				
	Number of buildings in			_						
В3	Acres burned (outside	None fires)	Less the	an 1 acre						
		•								
D	tion			E1	of Ignition		E3 Human Facto	ors Contributing to		
_	Ignition Cause of Ignition 1 1 - Intentional 2 - Unintentiona 3 - Failure of Equ				ntentional		Ignition			
01						pment or Heat	Check all applic			
	80-Heat spread from another			Source 4 - Act of Nature			1 - Asleep 2 - Possibly impaired by alcohol or			
D2	fire, other Heat Source			U-0		nvestigation rmined After		ugs 3 - Unattended person 4 - Possibly Mentally Disabled		
D3	86-Fence, pole			Investi	gation		5 - Physica	lly Disabled e Persons Involved		
	Item First Ignited			E2			7 - Age Was A Factor			
D4			J _e	1	040	ing to Ignition	Estimated Ag Person Involv	e of		
	Type of Material First	Ignited		-	posure fire Contributing t	o Ignition	Male	Female		
F1	la an and Jave Ive all 1	!L!		F2	anh Danuar Ca	NI SEA		G Fire Suppression Factors		
Equi	i pment Involved in I g one	Inicion		Equipme	ent Power So	ource		riie suppression ractors		
				Equipme	nt Power Sourc	ce .				
Equip	oment Involved			F3						
Brai	nd L				ent Portabili	ty				
Мос	del			1. 1 - Po	rtable					
	al#			2 - Sta	ationary	rmally can be moved by on	e or two			
Vana				persons.						

H1 Mobile Property Involved	H2 Mobile Property Type and Make	Local Use
1 - Not involved in ignition, but burned 2 - Involved in ignition, but did not burn 3 - Involved in ignition and burned None	Mobile Property Type Mobile Property Make	Pre-Fire Plan Available Arson Report Attached Police Report Attached Coroner Report Attached Other Reports Attached
Mobile Property Model	Year	——
State License Plate Number	VIN	

NFIRS-3 Structure Fire

	14F1K3-3 3C1 UCCC	are ine		
Structure Type 1 - Enclosed Building 2 - Portable/Mobile Structure 3 - Open Structure 4 - Air-Supported Structure 5 - Tent 6 - Open Platform 7 - Underground Structure 8 - Connective Structure 0 - Other	Building Status 1 - Under Construction 2 - In Normal Use 3 - Idle, Not Routinely Used 4 - Under Major Renovation 5 - Vacant and Secured 6 - Vacant and Unsecured 7 - Being Demolished 0 - Other U - Undetermined	Building Ho 1 Number of S At/Above Gr 0 Number of S Below Grade	tories ade tories	Main Floor Size 1200 Total Square Feet OR BY Length (ft) X Width (ft)
J1 Fire Origin 1 Below Grade Story of Fire Origin J2 Fire Spread Confined to Object of Origin 2 - Confined to Room of Origin 3 - Confined to Floor of Origin 4 - Confined to Building of Origin 5 - Beyond Building of Origin	Number of Stories Damaged By F Number of Stories w/Minor Dar Number of Stories w/Significan Number of Stories w/Heavy Dal Number of Stories w/Extreme (*Count the roof as part of the highest	mage (1-24%) It Damage (25-49%) mage (50-74%) Damage (75-100%)	K1 LILEM to F	Material Contributing Flame Spread The Contributing Most lame Spread The of Material Contributing Strom Flame Spread
Presence of Detectors N - None Present 1 - Present U - Undetermined	L3 Detector Power Supply 1 - Battery Only 2 - Hardwire Only 3 - Plug-In 4 - Hardwire With Battery 5 - Plug-In With Battery 6 - Mechanical 7 - Multiple Detectors	1 - Alerted Oc 2 - Alerted Oc 3 - There Wer 4 - Failed to A	cupants, Oc cupants, Oc e No Occup lert Occupa	
L2 Detector Type 1 - Smoke 1 - 2 - Heat 2 - Heat 4 - Sprinkler, Water Flow Detection 5 - More Than One Type Present 0 - Other U - Undetermined	& Power Supplies 0 - Other U - Undetermined L4 Detector Failure Reason 1 - Power Failure, Shutoff, or L2 - Improper Installation or P 3 - Defective Detector Operation			or Placement Dirty sconnected

M1	M3	M5
Presence of Automatic Extinguishing System	Operation of Automatic Extinguishing System	Reason for Automatic Extinguishing System Failure
N - None Present 1 - Present 2 - Partial System Present U - Undetermined M2 Type of Automatic Extinguishing System 1 - Wet-Pipe Sprinkler 2 - Dry-Pipe Sprinkler	1 - Operated/Effective 2 - Operated/Not Effective 3 - Fire Too Small To Activate 4 - Failed To Operate 0 - Other U - Undetermined Required if fire was within designed range	1 - System Shut Off 2 - Not Enough Agent Discharged 3 - Agent Discharged But Did Not Reach Fire 4 - Wrong Type of System 5 - Fire Not In Area Protected 6 - System Components Damaged 7 - Lack of Maintenance 8 - Manual Intervention 0 - Other U - Undetermined Required if system failed or not effective
3 - Other Sprinkler System 4 - Dry Chemical System 5 - Foam System 6 - Halogen-Type System 7 - Carbon Dioxide System 0 - Other U - Undetermined Required if fire was within designed range of AES	M4 Number of Sprinkler Heads Operating Required if system operated	

NFIRS-9 Apparatus or Resources

A							
36170	CA	03	16	2021	Station 2 (132)	OF2104486	5
FDID	State	Month	Day	Year	Station	Number	Exposure

B Apparal	tus/Resource	Dates/Times	Sent	Number of People	Apparatus Use	Actions Taken
ID: Type:	B1806 92-Chief officer car	Dispatch: 03/16/2021 12:42 Arrival: 03/16/2021 12:54		1	Suppression EMS Other	81-Incident command
	1 1	Clear: 03/16/2021 15:23		1 1	The state of	11
ID:	B1807	Dispatch: 03/16/2021 13:02	Sent	0	Suppression EMS Other	
Туре:	92-Chief officer car	Arrival:	.1		Cotner	
		Clear: 03/18/2021 02:52				1.1
ID:	B1808	Dispatch: 03/16/2021 19:12	Sent	0	Suppression EMS	Ц
Туре:	92-Chief officer car	Arrival:	1		Other	
		Clear: 03/18/2021 02:51				
ID:	B1811	Dispatch: 03/16/2021 19:36	Sent	0	Suppression EMS	
Туре:	92-Chief officer car	Arrival:			Other	
		Clear: 03/17/2021 14:19				
ID:	B1815	Dispatch: 03/16/2021 12:30	Sent	1	Suppression EMS	
Type:	92-Chief officer car	Arrival: 03/16/2021 12:36	5		Other	
		Clear: 03/17/2021 01:41				
ID:	B1825	Dispatch: 03/16/2021 12:32	Sent	1	Suppression	
Type:	92-Chief officer car	Arrival: 03/16/2021 12:40	- >		EMS Other	
		Clear: 03/16/2021 19:13	в			
ID:	C1842	Dispatch: 03/16/2021 14:06	Sent	: 0	Suppression	Ц
Туре:	60-Support apparatus, other	Arrival: 03/16/2021 14:00	_ 5	_	EMS Other	
		Clear: 03/16/2021 17:43	3			
ID:	D1802	Dispatch: 03/16/2021 13:11	Sent	: 0	Suppression	
Type:	92-Chief officer car	Arrival: 03/16/2021 13:1	_		Other	
		Clear: 03/16/2021 14:20	5			
ID:	D1803	Dispatch: 03/16/2021 12:44	Sent	: 0	Suppression	Ш
Type:	92-Chief officer car	Arrival:			Other	
		Clear: 03/16/2021 14:20	5			
ID:	ED131	Dispatch: 03/16/2021 12:3	Sent	8	Suppression	
Type:	00-Other apparatus/resource	Arrival: 03/19/2021 23:4	1		Other	
		Clear: 03/20/2021 15:3	1			
ID:	HM133	Dispatch: 03/16/2021 13:00	Sent	t [0]	Suppression	Ц
Туре:	93-HazMat unit	Arrival:			Other	
		Clear:				

	03/20/20	021 14:52		
ID: I1850 Type: 60-Support apparatus, other	Dispatch: 03/16/20 Arrival: 03/16/20 Clear: 03/17/20	021 12:36	Suppression L EMS Other	
ID: ME131 Type: 11-Engine	Dispatch: 03/16/20 Arrival: 03/16/20 Clear: 03/16/20	021 12:36	Suppression L EMS Other	
ID: ME132 Type: 11-Engine	Dispatch: 03/16/20 Arrival: 03/16/20 Clear: 03/19/20	021 12:34	Suppression EMS Other	
ID: ME134 Type: 11-Engine	Dispatch: 03/16/20 Arrival: 03/16/20 Clear: 03/16/20	021 12:42 Sent 4 021 12:47	Suppression L EMS Other	
ID: ME135 Type: 11-Engine	Dispatch: 03/16/20 Arrival: 03/16/20 Clear: 03/16/20	021 12:42 Sent 4 021 12:53	Suppression L EMS Other]
ID: ME136 Type: 11-Engine	Dispatch: 03/16/20 Arrival: 03/16/20 Clear: 03/17/20	021 12:42	Suppression EMS Other	11-Extinguishment by fire service personnel
ID: ME137 Type: 11-Engine	Dispatch: 03/16/2 Arrival: 03/16/2 Clear: 03/16/2	021 13:20	Suppression L EMS Other	
ID: ME138 Type: 11-Engine	Dispatch: 03/16/2 Arrival: 03/16/2 Clear: 03/16/2	021 13:11	Suppression L EMS Other	
ID: ME139 Type: 11-Engine	Dispatch: 03/16/2 Arrival: 03/16/2 Clear: 03/16/2	1021 12:54	Suppression iEMS iOther	
ID: ME141 Type: 11-Engine	Dispatch: 03/16/2 Arrival:		Suppression EMS Other	
ID: ME67 Type: 11-Engine	Dispatch: 03/16/2 Arrival: 03/16/2		Suppression EMS Other	

	Clear: 03/16/2021 23:41	
ID: T131 Type: 12-Truck or aerial	Dispatch: 03/16/2021 12:30 Sent 4 Arrival: 03/16/2021 12:38	Suppression EMS Other
	Clear: 03/16/2021 22:02	
ID: T138 Type: 12-Truck or aerial	Dispatch: 03/16/2021 12:42 Sent 4 Arrival:	Suppression L EMS Other
	Clear: 03/16/2021 12:44	
ID: T139 Type: 12-Truck or aerial	Dispatch: 03/16/2021 12:43 Sent 4 Arrival:	Suppression L EMS Other
	Clear: 03/16/2021 20:05	
ID: T1820 Type: 60-Support apparatus, other	Dispatch: 03/16/2021 12:37 Sent 0 Arrival: 03/16/2021 12:37	Suppression L EMS Other
	Clear: 03/18/2021 13:36	
ID: T1822 Type: 60-Support apparatus, other	Dispatch: 03/16/2021 12:51 Sent 0 Arrival:	Suppression L EMS Other
	Clear: 03/16/2021 23:41	

NFIRS-10 Personnel

A							
36170	CA	03	16	2021	Station 2 (132)	OF2104486	5
FDID	State	Month	Day	Year	Station	Number	Exposure

B Apparat	:us/Resource	Dates/Times		Sent	Number of People	Apparatus Use	Actions Taken
ID:	B1806	Dispatch: 03/16/2021	12:42	Sent	11	Suppression	81-Incident command
Туре:	92-Chief officer car	Arrival: 03/16/2021	12:54			EMS Other	
		Clear: 03/16/2021	15:23				
Personn	el ID	Name		Rank	Role	Attend	Actions Taken
17111		Roeber, Scotland		Battalion Chief			81-Incident command
ID:	B1807	Dispatch: 03/16/2021	13:02	Sent	0	Suppression DEMS	
Туре:	92-Chief officer car	Arrival:				Other	
		Clear: 03/18/2021	02:52				
Personn	el ID	Name		Rank	Role	Attend	Actions Taken
ID:	B1808	Dispatch: 03/16/2021	19:12	Sent	0	Suppression	Ц
Type:	92-Chief officer car	Arrival:				EMS Other	
.,,,,,,,,	72 dilet officer dai	Clear: 03/18/2021	02:51				
Personn	el ID	Name		Rank	Role	Attend	Actions Taken
T CISOIII		1101110		TO THE	11010	7100110	
ID:	B1811	Dispatch: 03/16/2021	19:36	Sent	0	Suppression	
Type:	92-Chief officer car	Arrival:				Other	
		Clear: 03/17/2021	14:19				
Personn	el ID	Name		Rank	Role	Attend	Actions Taken
ID:	B1815	Dispatch: 03/16/2021	12:30	Sent	1	Suppression	Ц
Туре:	92-Chief officer car	Arrival: 03/16/2021	12:36			EMS Other	
lypc.	22-Cilier officer car						
			01:41				
Personn	el ID	Name		Rank	Role	Attend	Actions Taken
18726		Williams, Ryan		Battalion Chief		-	
[<u>.</u> _	11		1 1	Ele i	1.1	F.c	
ID:	B1825	Dispatch: 03/16/2021	12:32	Sent	1	Suppression EMS	
Туре:	92-Chief officer car	Arrival: 03/16/2021	12:40			Other	
		Clear: 03/16/2021	19:13				
Personn	el ID	Name		Rank	Role	Attend	Actions Taken
18006		Stepanian, Nicolas		Battalion Chief			Ш
							1.1
ID:	C1842	Dispatch: 03/16/2021	14:06	Sent	0	Suppression EMS	
Туре:	60-Support apparatus, other	Arrival: 03/16/2021	14:06			Other	
		Clear: 03/16/2021	17:43				
Personn	el ID	Name		Rank	Role	Attend	Actions Taken
ID.	1,,,,,, 1	Dispatch: Lagragasa	Laal				

Type:	92-Chief officer car	Arrival:	03/16/2021 13:11 03/16/2021 13:11 03/16/2021 14:26	Sent	0	Suppression EMS Other	Ц
Personn	nel ID	Name		Rank	Role	- Attend	Actions Taken
ID: Type:	D1803 92-Chief officer car	Dispatch: Arrival: Clear:	03/16/2021 12:44	Sent	0	Suppression EMS Other	
Personn	nel ID	Name		Rank	Role	Attend	Actions Taken
ID: Type:	ED131 00-Other apparatus/resource	Dispatch: Arrival: Clear:	03/16/2021	Sent	8	USuppression EMS Other	
Personn	nel ID	Name		Rank	Role	Attend	Actions Taken
19425		Trapani, G	eoffrey	Fire Investigation Supervisor			Ц
18343		Goyette, N	1atthew	Fire Captain		0,	Ц
19273		Lambert, l	Darrell	Fire Captain		9	
19228		Langevin,	Steve	Fire Engineer		F	Ц
16923		Lewis, Rya	n	Battalion Chief		E	
19226		Ryan, Jaco	b	Fire Captain			
18724		Verkaik, E	ugene	Fire Captain		ē.	Ц
18466		Wedell, M	ichael	Battalion Chief		E .	<u> </u>
ID: Type:	93-HazMat unit	Dispatch: Arrival: Clear:	03/16/2021 13:09	Sent Sent	0	Suppression EMS Other	
Personr	nel ID	Name		Rank	Role	Attend	Actions Taken
ID: Type:	60-Support apparatus, other	Dispatch: Arrival: Clear:	03/16/2021 12:30 03/16/2021 12:36 03/17/2021 17:58	Sent Sent	1	Suppression EMS Other	Ц
Personr	nel ID	Name		Rank	Role	Attend	Actions Taken
18721		Kloosterm	nan, Daniel	Fire Investigation Supervisor	_	1	П
ID: Type:	ME131	Dispatch: Arrival: Clear:	03/16/2021 12:30 03/16/2021 12:36 03/16/2021 15:09	Sent	4 Pole	Suppression EMS Other	Artions Taken
Derenni	ner II)	Name		~ ~ ~ ~ ~ ~			

retacimento	HOITIC	Nonk Not	se vrceud	ACTIONS TOKEN
20025	Bandaruk, Jason	Firefighter	П	
20192	Wilson, Duncan	Firefighter		
19140	Hafner, Ryan	Fire Captain	(ii	
19344	Preston, Bryan	Fire Engineer	В	
ID: ME132 Type: 11-Engine	Dispatch: 03/16/2021 12:30 Arrival: 03/16/2021 12:34 Clear: 03/19/2021 15:43	Sent 4	Suppression EMS Other	
Personnel ID	Name	Rank Rol	le Attend	Actions Taken
20183	Clements, Cody	Firefighter		<u>U</u>
19687	Thompson, Matthew	Fire Engineer	Ω	<u> </u>
19223	Gilbert, Ryan	Fire Captain		Ц
20190	Saunders, Kurt	Firefighter	Di .	
ID: ME134 Type: 11-Engine	Dispatch: 03/16/2021 12:42 Arrival: 03/16/2021 12:47 Clear: 03/16/2021 14:43	Sent 4	Suppression EMS Other	
Personnel ID	Name	Rank Rol	le Attend	Actions Taken
20205	Okamura, Thomas	Firefighter		
20201	Steele, Matthew	Firefighter	0	Ц
19227	Willemse, Scott	Fire Captain		Ш
19422	Cavanaugh, Sean	Fire Engineer		Ц
ID: ME135 Type: 11-Engine	Dispatch: 03/16/2021 12:42 Arrival: 03/16/2021 12:53 Clear: 03/16/2021 14:47	Sent 4	Suppression EMS Other	
Personnel ID	Name	Rank Rol	le Attend	Actions Taken
19881	Ciszek, Brian			Ц
20199	Hoover, Lucas	Firefighter		
17357	Bekins, Kurt	Fire Captain	B	
19857	Zaragoza, Eric		С	Ц
ID: ME136 Type: 11-Engine	Dispatch: 03/16/2021 12:30 Arrival: 03/16/2021 12:42 Clear: 03/17/2021 21:11	Sent 4	Suppression EMS Other	11-Extinguishment by fire service pers
Personnel ID	Name	Rank Ro	le Attend	Actions Taken
19798	Mowad, Trevor			Ц
20327	Magrina, Joel	Firefighter	P	<u> </u>
0				• •

20185	Medina, Jacob	Firefighter	=-	<u> </u>
16864	Spellman, Ronald	Fire Captain		
ID: ME137 Type: 11-Engine	Dispatch: 03/16/2021 13:09 Arrival: 03/16/2021 13:20 Clear: 03/16/2021 14:15	Sent 4	Suppression EMS Other	
Personnel ID	Name	Rank Role	Attend	Actions Taken
20194	Esquivias, Jovanny	Firefighter	in in	
19680	Garrett, Chad	Fire Engineer	6	Ц
17233	De Young, Daniel	Fire Captain	Ü,	
20321	Armstrong, Joshua	Firefighter	П	
ID: ME138 Type: 11-Engine	Dispatch: 03/16/2021 13:08 Arrival: 03/16/2021 13:11 Clear: 03/16/2021 15:16	Sent 4	Suppression EMS Other	
Personnel ID	Name	Rank Role	Attend	Actions Taken
19807	Clarke, Christian			
16895	Nelson, Tye	Fire Captain		
20316	Hernandez, Michael	Firefighter		
20202	Powers, Brian	Firefighter	þ	
ID: ME139 Type: 11-Engine	Dispatch: 03/16/2021 12:42 Arrival: 03/16/2021 12:54 Clear: 03/16/2021 22:13	Sent 4	Suppression EMS Other	Ц
Personnel ID	Name	Rank Role	Attend	Actions Taken
20334	Verral, Eric	Firefighter	П	
20184	Selk, Chase	Firefighter		
19686	Talley, Steven	Fire Engineer	D	
18902	Bethel, Richard	Fire Captain	10	Ц
ID: ME141 Type: 11-Engine	Dispatch: 03/16/2021 22:31 Arrival:	Sent 0	Suppression EMS Other	Ц
Personnel ID	Name	Rank Role	Attend	Actions Taken
ID: ME67 Type: 11-Engine	Dispatch: 03/16/2021 13:28 Arrival: 03/16/2021 13:28 Clear: 03/16/2021 23:41	Sent 0	Suppression JEMS Other	Ц
Personnel ID	Name	Rank Role	Attend	Actions Taken
ID: T131	Dispatch: 03/16/2021 12:30	Sent	Suppression	

Turnet	L. I	r A meis sa la	[12/47/2024] [42/20]		4	EMS Other	
Туре:	12-Truck or aerial	Arrival: Clear:	03/16/2021 12:38				
			03/16/2021 22:02				
Personn	el ID	Name		Rank	Role	Attend	Actions Taken
20326		Jaquess, 1	yler	Firefighter		ğ	Ш
19228		Langevin,	Steve	Fire Engineer			Ш
18724		Verkaik, E	ugene	Fire Captain			Ц
20032		Gamboa, I	Neil	Firefighter		В	Ц
ID: Type:	T138	Dispatch: Arrival: Clear:	03/16/2021 12:42	Sent	4	Suppression EMS Other	Ц
Personn	el ID	Name		Rank	Role	Attend	Actions Taken
19885		Morrison,	Christopher			g	
20029		Нагрег, М	artin	Firefighter			Ш
18980		Van Fosse	n, Brian	Fire Captain			Ш
19508		Bates, Log	gan	Fire Engineer			П
ID: Type:	T139	Dispatch: Arrival: Clear:	03/16/2021 12:43	Sent	4	Suppression EMS Other	П
Personn	el ID	Name		Rank	Role	Attend	Actions Taken
19880		DeMartin	o, Noah				Ш
20214		Norbryhn		Firefighter		日	Ш
19679		Charlesto	n, David	Firefighter		Ü	Ц
17102		Guapo, Lo	uis	Fire Captain		ū	
ID: Type:	T1820 60-Support apparatus, other	Dispatch: Arrival: Clear:	03/16/2021 12:37 03/16/2021 12:37 03/18/2021 13:36	Sent	0	Suppression EMS Other	Ц
Personn	iel ID	Name		Rank	Role	Attend	Actions Taken
ID: Type:	T1822 60-Support apparatus, other	Dispatch: Arrival: Clear:	03/16/2021 12:51	Sent	0	Suppression EMS Other	Ц
Personn	el ID	Name		Rank	Role	Attend	Actions Taken

NFIRS-1S Supplemental

Α								
	36170	CA	03	16	2021	Station 2 (132)	OF2104486	5
	FDID	State	Month	Day	Year	Station	Number	Exposure

Primary Narrative:

B 1815 was dispatched as part of the first alarm assignment to a potential structure fire at the documented address. Prior to going enroute B 1815 acknowledged Ontario Dispatch traffic stating that there were multiple explosions at the location. Due to this I immediately started EOD 131 and HM 133.

B 1815 then went responding. While enroute I observed a large column of smoke in the area of the dispatched address. I broadcast this traffic and continued in code 3.

B 1815 AOS and observed fire to the front yard and rear of house. Structure observed was a single story single family residence with significant exposure concern to the delta side. B 1815 established Francis Command. Immediately upon establishing Francis Command, B 1815 requested that OPD shut down Francis St west of Fern and east of San Antonio. B 1815 also requested a 300' perimeter be established around 428 W. Francis St.

ME 132 AOS and Francis Command assigned him as Division A. Objectives were perimeter control and victim accountability. They were advised to engage in fire attack operations only if they felt safe in doing so.

ME 131 AOS and was assigned as a rescue group. There were report of victims on the "D" side of 428 W. Francis. This information was relayed to ME 131 and they set up for potential rescue operations.

T 1820 arrived onscene and he was assigned as division D with primary objectives of perimeter control and victim accountability. ME 136 was almost immediately assigned to help out division D.

T 131 AOS and due to unit specialty their crew was split. Captain Verkaik and Engineer Langevin were assigned to the EOD group and FF Jaquess and FF Gamboa were assigned underneath division A to assist with their operation.

ME 134 was assigned as my division B. Their objectives were to establish perimeter control and provide victim accountability.

ME 139 AOS and they were assigned as division D. Their objectives were to establish perimeter control and provide victim accountability.

During the course of assigning unit to their divisional assignments a large explosion occurred. This explosion resulted in an operational retreat of all divisions. A PAR was performed and all firefighters were accounted for. No injuries were noted due to the explosion.

Fire suppression activities resumed after the explosion with safety measures applied. Large diameter hoselines were used from a safe distance.

Fire was extinguished at the documented time. Operations then transitioned into a multi day investigation operation led by Ontario FD EOD and I 1850. Please reference their report for additional information in regards to their operations.

Multi families were displaced as a result of this incident. Red Cross was used as the primary for sheltering measures.

Ultimately on Saturday late afternoon the Francis Incident was terminated and all Ontario Fire Department operations were complete.

R. Williams Fire Battalion Chief Battalion 1-B

Person/Entity	Involved	Employee		South Coast Air Quality Management District	
Local Option		Person/Entity Type		Business Name (if applicable)	Phone Number
	Kamal			Brenner	
Mr., Ms., Mrs.	First Name		MI	Last Name	Suffix
Number	Prefix	Street or Highway		Street Type	Suffix
Post Office Box		Apt./s	Suite/Room	City	
State		Zip Code			

Additional Narrative (#1 of 1):

Exposure #5

The property of 1742 Fern was located in Division D. This property sustained a great deal of structural damage to the house from the explosion and blast pressure. The thermal effect from the explosion caused a secondary fire. This fire occurred to a 10 x15 foot shed or out-building along the north edge of the property in the backyard.

R. Gilbert ME 132-B



NFIRS-1 Basic

A							
36170	CA	03	16	2021	Station 2 (132)	OF2104486	6
FDID	State	Month	Day	Year	Station	Number	Exposure
^B Location Type							Census tract:
Street Address Intersection In Front Of Rear Of Adjacent To Directions US National Grid	428 Number	W-West Prefix	FRANCI Street o	S r Highway			r-Street Suffix
			ONTARIO)		CA	91762
	Apt./Suite/F	Room	City			State	Zip Code
	Cross Street	:					
С				E1 Dates and	d T i		E2 Shifts and Alarms
Incident Type 111-Building fire D				Alarm Arrival Controlled	03 16 2021 03 16 2021 03 17 2021	12:29 12:34 07:03	Shift or Alarms District Platoon
Aid Given Or Recei 1 Mutual Aid Recei 2 Auto. Aid Recei 3 Mutual Aid Give	eived L ved Their	FDID	California Their State	Last Unit Cleared		15:31	E3 Special Studies L L L L L L L L L L L L L L L L L L L
4 Auto. Aid Giver 5 Other Aid Giver None	ո 🗀	Incident Num					

Their Incident Number

Actions Taken 11-Extinguishment by fire Primary Action Taken	service personnel	G1 Resources Apparatus or Personnel Apparatus Suppression 17 EMS 5 Other 5 Resource counts include resources.	Personnel 35 12 10	Losses: Recknon nor Property: \$ Contents: \$	Values: Optional	Values None None
Completed Modules 2 - Fire 3 - Structure Fire 4 - Civilian Fire Cas. 5 - Fire Service Cas. 6 - EMS 7 - HazMat 8 - Wildland Fire 9 - Apparatus 10 - Personnel 11 - Arson	Fire Service Civilian H2 Detector Required for Contact 1 - Detector	o o o	H3 Hazardous Mal 1 - Natural G 2 - Propane 3 - Gasoline 4 - Kerosene 5 - Diesel Fu 6 - Househol 7 - Motor Oil 8 - Paint 0 - Other None	Gas el / Fuel Oil d Solvents	Mixed Use Prop Not Mixed 10 - Assembly 20 - Education 33 - Medical U 40 - Residentia 51 - Row Of St 53 - Enclosed I 58 - Business a Residential 59 - Office Use 60 - Industrial 63 - Military Use 65 - Farm Use 00 - Other Mix	Use Use se ol Use ores Mall and b Use
Property Use Non Structures 131 Church, Place of 161 Restaurant or Ca 162 Bar/Tavern or Ni 213 Elementary Scho 215 High School, Jun 241 College, Adult Ed 311 Nursing Home 331 Hospital	Worship afeteria ghtclub ool, Kindegarten aior High	341 Clinic, Clinic-Type 342 Doctor/Dentist Of 361 Prison or Jail, Not 419 1- or 2-Family Dwell 429 MultiFamily Dwell 439 Commerical Hote 459 Residential, Board 464 Dormitory/Barrac 519 Food and Beverag	ffice : Juvenile elling ling g House I or Motel d and Care ks	571 Gas or Sen 579 Motor Veh 599 Business C 615 Electric-Ge 629 Laborator 700 Manufactu 819 Livestock/	icle/Boat Sales/Rep Office enerating Plant y/Science Laborator uring Plant Poultry Storage (Ba ential Parking Gara	pairs Ty Irn)
Outside 124 Playground or P. 655 Crops or Orchan 669 Forest (Timberla 807 Outdoor Storage 919 Dump or Sanitar 931 Open Land or Fig 936 Vacant Lot	d ind) e Area y Landfill	938 Graded/Cared for 946 Lake, River, Stream 951 Railroad Right-of-960 Other Street 961 Highway/Divided 962 Residential Street 981 Construction Site 984 Industrial Plant Ya	m Way Highway t/Driveway		a Property Use code a rou have NOT checked	

K1					
Person/Entity Involved			nvironmental Protection Agency		
Local Option	Person/Entity Type	Bus	siness Name (if applicable)	Phone Number	
MR-Mr.	Robert		Wise		
Mr., Ms., Mrs.	First Name	ME	Last Name	Suffix	
Number	Prefix	Street or Highway	Street Type	Suffix	
Post Office Box	Apt./Su	ite/Room	City		
i		C			
State		Zip	Code		

Owner	1	TF		If	
Local Option	Person/Enti	ty Type Rusiness	Name (if applicable)	Phone Number	
Local Option	P CT3OTY LITER	cos Dusiness	anii	VW:	
Mr., Ms., Mrs.	First Name	MI	Last Name	Suffix	
İ					
Number	Prefix	Street or Highway	Street Type	Suffix	
Ĭ					
Post Office Box		Apt./Suite/Room	City		
		11			
State		Zip Code			

L Remarks:

B 1815 was dispatched as part of the first alarm assignment to a potential structure fire at the documented address. Prior to going enroute B 1815 acknowledged Ontario Dispatch traffic stating that there were multiple explosions at the location. Due to this I immediately started EOD 131 and HM 133.

B 1815 then went responding. While enroute I observed a large column of smoke in the area of the dispatched address. I broadcast this traffic and continued in code 3.

B 1815 AOS and observed fire to the front yard and rear of house. Structure observed was a single story single family residence with significant exposure concern to the delta side. B 1815 established Francis Command. Immediately upon establishing Francis Command, B 1815 requested that OPD shut down Francis St west of Fern and east of San Antonio. B 1815 also requested a 300' perimeter be established around 428 W. Francis St.

ME 132 AOS and Francis Command assigned him as Division A. Objectives were perimeter control and victim accountability. They were advised to engage in fire attack operations only if they felt safe in doing so.

ME 131 AOS and was assigned as a rescue group. There were report of victims on the "D" side of 428 W. Francis. This information was relayed to ME 131 and they set up for potential rescue operations.

T 1820 arrived onscene and he was assigned as division D with primary objectives of perimeter control and victim accountability. ME 136 was almost immediately assigned to help out division ...

Full primary narrative can be found in NFIRS 1S - Supplemental

Williams, Ryan	Battalion Chief		03/23/2021
Signature	Position or Rank	Assignment	Date
Gîlbert, Ryan	Fire Captain		03/26/2021
Signature	Position or Rank	Assignment	Date
	Signature Gilbert, Ryan	Signature Position or Rank Gilbert, Ryan	Signature Position or Rank Assignment Gilbert, Ryan Fire Captain

NFIRS-2 Fire

A	470	Ha	Han	Ü	2021	Station 2	OF2104486] 6
3	6170	CA	03	16		(132)	OF2104486	<u> </u>
FD	ID	State	Month	Day	Year	Station	Number	Exposure
B Prop B1 B2 B3	perty Details 1 Estimated number origin whether or or one of building the content of building the co	of resident of resident of all units of the second of the	s became invo	olved	ilding of	C On-Site Materials Or Products		-Site Materials orage Use
D Ignition D1 70-Structural area, other Area of Fire Origin 80-Heat spread from another fire, other Heat Source 11-Exterior roof covering, surface, finish Item First Ignited D4 Undetermined Type of Material First Ignited				1 - II 2 - U 3 - F Source 4 - A 5 - C Investi E2 Facto	act of Nature ause Under I ause Undete gation	ipment or Heat nvestigation ermined After ing to Ignition	Ignition Check all appli None 1 - Asleep 2 - Possible drugs 1 3 - Unatte 4 - Possible 5 - Physica 6 - Multipl	y impaired by alcohol or nded person y Mentally Disabled illy Disabled e Persons Involved as A Factor
Equip Bra	pment Involved nd	n Ignition	•	Equipment F3 Equipment 1 - Po	ationary	ce	ne or two	G Fire Suppression Factors

H1 Mobile Property Involved 1 - Not involved in ignition, but burned 2 - Involved in ignition, but did not burn 3 - Involved in ignition and burned None	H2 Mobile Property Type and Make Mobile Property Type Mobile Property Make	Local Use Pre-Fire Plan Available Arson Report Attached Police Report Attached Coroner Report Attached Other Reports Attached
Mobile Property Model State License Plate Number	Year VIN	

NFIRS-3 Structure Fire

	MEIKS-S SCIUCCU	e i ii e			
I1 Structure Type 1 - Enclosed Building 2 - Portable/Mobile Structure 3 - Open Structure 4 - Air-Supported Structure J 5 - Tent 6 - Open Platform 7 - Underground Structure 8 - Connective Structure	I2 Building Status 1 - Under Construction 2 - In Normal Use 3 - Idle, Not Routinely Used 4 - Under Major Renovation 5 - Vacant and Secured 6 - Vacant and Unsecured 7 - Being Demolished 0 - Other	Building He 1 Number of S At/Above Gra 0 Number of S Below Grade	tories ade tories	Main Floor Size 1200 Total Square Feet OR BY Length (ft) X Width (ft)	
0 - Other	J3 Number of Stories Damaged By Fla Number of Stories w/Minor Dama Number of Stories w/Significant of Stories w/Heavy Dama Number of Stories w/Extreme Dama *Count the roof as part of the highest st	age (1-24%) Damage (25-49%) age (50-74%) mage (75-100%)	K1 LItem to F	Material Contributing Flame Spread n Contributing Most Flame Spread e of Material Contributing st To Flame Spread	
Presence of Detectors N - None Present 1 - Present U - Undetermined	L3 Detector Power Supply 1 - Battery Only 2 - Hardwire Only 3 - Plug-In 4 - Hardwire With Battery 5 - Plug-In With Battery 6 - Mechanical 7 - Multiple Detectors	2 - Alerted Oc 3 - There Were 4 - Failed to Al U - Undetermi	cupants, Occupants, Occupants, Occupants		
Detector Type 1 - Smoke 2 - Heat 3 - Combination of Smoke and Heat 4 - Sprinkler, Water Flow Detection 5 - More Than One Type Present 0 - Other U - Undetermined	& Power Supplies 0 - Other U - Undetermined L4 Detector Operation 1 - Fire Too Small To Activate 1 2 - Operated 3 - Failed To Operate U - Undetermined	L6 Detector Failure Reason 1 - Power Failure, Shutoff, or Disconnect 2 - Improper Installation or Placement 3 - Defective 4 - Lack of Maintenance, Dirty 5 - Battery Missing or Disconnected 6 - Battery Discharged or Dead 0 - Other U - Undetermined			

M1	мз	M5
Presence of Automatic Extinguishing System N - None Present 1 - Present 2 - Partial System Present U - Undetermined M2 Type of Automatic Extinguishing System 1 - Wet-Pipe Sprinkler 2 - Dry-Pipe Sprinkler	Operation of Automatic Extinguishing System 1 - Operated/Effective 2 - Operated/Not Effective 3 - Fire Too Small To Activate 4 - Failed To Operate 0 - Other U - Undetermined Required if fire was within designed range	Reason for Automatic Extinguishing System Failure 1 - System Shut Off 2 - Not Enough Agent Discharged 3 - Agent Discharged But Did Not Reach Fire 4 - Wrong Type of System 5 - Fire Not In Area Protected 6 - System Components Damaged 7 - Lack of Maintenance 8 - Manual Intervention 0 - Other U - Undetermined Required if system failed or not effective
3 - Other Sprinkler System 4 - Dry Chemical System 5 - Foam System 6 - Halogen-Type System 7 - Carbon Dioxide System 0 - Other U - Undetermined Required if fire was within designed range of AES	M4 Number of Sprinkler Heads Operating Required if system operated	=

NFIRS-9 Apparatus or Resources

A							
36170	CA	03	16	2021	Station 2 (132)	OF2104486	6
FDID	State	Month	Day	Year	Station	Number	Exposure

B Apparat u	ıs/Resource	Dates/Times	Sent	Number of People	Apparatus Use	Actions Taken
	B1806 92-Chief officer car	Dispatch: 03/16/2021 12:42 Arrival: 03/16/2021 12:54	_	1	Suppression EMS Other	81-Incident command
		Clear: 03/16/2021 15:23				
1 0	B1807 92-Chief officer car	Dispatch: 03/16/2021 13:02 Arrival:	Sent	1	Suppression EMS Other	Ц
		Clear: 03/18/2021 02:52				
'	B1808	Dispatch: 03/16/2021 19:12	Sent	0	Suppression EMS Other	
[Clear: 03/18/2021 02:51				
	B1811 92-Chief officer car	Dispatch: 03/16/2021 19:36 Arrival:		0	Suppression EMS Other	Ц
		Clear: 03/17/2021 14:19				
1 7	92-Chief officer car	Dispatch: 03/16/2021 12:30 Arrival: 03/16/2021 12:36		1	Suppression EMS Other	
	-	Clear: 03/17/2021 01:41				
1 5	B1825	Dispatch: 03/16/2021 12:32 Arrival: 03/16/2021 12:40	_	1	Suppression EMS Other	
туре.	92-Chief Officer Car	Clear: 03/16/2021 19:13	ا ا			
1 1	C1842 60-Support apparatus, other	Dispatch: 03/16/2021 14:06 Arrival: 03/16/2021 14:06 Clear: 03/16/2021 17:43		0	Suppression EMS Other	
, a	D1802 92-Chief officer car	Dispatch: 03/16/2021 13:11 Arrival: 03/16/2021 13:11 Clear: 03/16/2021 14:26	_	0	Suppression EMS Other	Ц
1 7	D1803 92-Chief officer car	Dispatch: 03/16/2021 12:44 Arrival:	_	0	Suppression EMS Other	
-	ED131 00-Other apparatus/resource	Dispatch: 03/16/2021 12:31 Arrival: 03/19/2021 23:41 Clear: 03/20/2021 15:31	Sent	8	Suppression EMS Other	
	HM133 93-HazMat unit	Dispatch: 03/16/2021 13:09 Arrival:	Sent	0	Suppression EMS Other	

			03/20/2021	14:52				
ID:	11850	Dispatch:	03/16/2021	12:30	Sent	1	Suppression	86-Investigate
Туре:	60-Support apparatus, other	Arrival:	03/16/2021	12:36		_	EMS Other	
		Clear:	03/17/2021	17:58				
ID:	ME131	Dispatch:	03/16/2021	12:30	Sent	4	Suppression	Ц
Type:	11-Engine	Arrival:	03/16/2021	12:36			EMS Other	
		Clear:	03/16/2021	15:09				
ID:	ME132	Dispatch:	03/16/2021	12:30	Sent	4	Suppression	
Type:	11-Engine	Arrival:	03/16/2021	12:34			EMS Other	
		Clear:	03/19/2021	15:43				
ID:	ME134	Dispatch:	03/16/2021	12:42	Sent	4	Suppression EMS	Ц
Type:	11-Engine	Arrival:	03/16/2021	12:47			Other	
		Clear:	03/16/2021	14:43				
ID:	ME135	Dispatch:	03/16/2021	12:42	Sent	4	Suppression EMS	
Туре:	11-Engine	Arrival:	03/16/2021	12:53			Other	
		Clear:	03/16/2021	14:47				
ID:	ME136	Dispatch:	03/16/2021	12:30	Sent	4	Suppression	11-Extinguishment by fire service personnel
Type:	11-Engine	Arrival:	03/16/2021	12:42			Other	
		Clear:	03/17/2021	21:11				
ID:	ME137	Dispatch:	03/16/2021	13:09	Sent	4	Suppression	
Туре:	11-Engine	Arrival:	03/16/2021	13:20			Other	
		Clear:	03/16/2021	14:15				
ID:	ME138	Dispatch:	03/16/2021	13:08	Sent	4	Suppression 3EMS	
Type:	11-Engine	Arrival:	03/16/2021	13:11			Other	
		Clear:	03/16/2021	15:16				
ID:	ME139	Dispatch:	03/16/2021	12:42	Sent	4	Suppression EMS	
Туре:	11-Engine	Arrival:	03/16/2021	12:54			Other	
		Clear:	03/16/2021	22:13				
ID:	ME141	Dispatch:	03/16/2021	22:31	Sent	0	Suppression	П
Type:	11-Engine	Arrival:	ШШ				Other	
		Clear:	03/20/2021	14:28				
ID:	ME67	Dispatch:	03/16/2021	13:28	Sent	0	Suppression EMS	
Type:	11-Engine	Arrival:	03/16/2021	13:28			Other	

	Clear: 03/16/2021 23:41	
ID: T131 Type: 12-Truck or aerial	Dispatch: 03/16/2021 12:30 Sent 4 Arrival: 03/16/2021 12:38 Clear: 03/16/2021 22:02	Suppression
ID: T138 Type: 12-Truck or aerial	Dispatch: 03/16/2021 12:42 Sent 4 Arrival: 03/16/2021 12:44	Suppression E EMS Other
ID: T139 Type: 12-Truck or aerial	Dispatch: 03/16/2021 12:43 Sent 4 Arrival: 03/16/2021 20:05	Suppression L EMS Other
ID: T1820 Type: 60-Support apparatus, other	Dispatch: 03/16/2021 12:37 Sent 0 Arrival: 03/16/2021 12:37 Clear: 03/18/2021 13:36	Suppression L EMS Other
ID: T1822 Type: 60-Support apparatus, other	Dispatch: 03/16/2021 12:51 Sent 0 Arrival:	Suppression L EMS Other

NFIRS-10 Personnel

A							
36170	CA	03	16	2021	Station 2 (132)	OF2104486	6
FDID	State	Month	Day	Year	Station	Number	Exposure

B Apparatus/Resource	Dates/Times		Number of People	Apparatus Use	Actions Taken
ID: B1806 Type: 92-Chief officer car	Dispatch: 03/16/2021 12:42 Arrival: 03/16/2021 12:54	Sent	1	Suppression EMS Other	81-Incident command
	Clear: 03/16/2021 15:23				
Personnel ID	Name	Rank	Role	Attend	Actions Taken
17111	Roeber, Scotland	Battalion Chief		fi	81-Incident command
ID: B1807 Type: 92-Chief officer car	Dispatch: 03/16/2021 13:02	C`Sent	1	Suppression EMS Other	Ц
	Clear: 03/18/2021 02:52				
Personnel ID	Name	Rank	Role	Attend	Actions Taken
16923	Lewis, Ryan	Battalion Chief			Ц
ID: B1808 Type: 92-Chief officer car	Dispatch: 03/16/2021 19:12 Arrival:	Sent Sent	0	Suppression EMS Other	
Personnel ID	Name	Rank	Role	Attend	Actions Taken
ID: B1811 Type: 92-Chief officer car	Dispatch: 03/16/2021 19:36 Arrival:	Sent Sent	0	Suppression EMS Other	
Personnel ID	Name	Rank	Role	Attend	Actions Taken
ID: B1815 Type: 92-Chief officer car	Dispatch: 03/16/2021 12:30 Arrival: 03/16/2021 12:36 Clear: 03/17/2021 01:41	Sent	1	Suppression CEMS Other	
Personnel ID	Name	Rank	Role	Attend	Actions Taken
18726	Williams, Ryan	Battalion Chief		i i	Ц
ID: B1825 Type: 92-Chief officer car	Dispatch: 03/16/2021 12:32 Arrival: 03/16/2021 12:40 Clear: 03/16/2021 19:13	Sent	1	Suppression EMS Other	
Personnel ID	Name	Rank	Role	Attend	Actions Taken
18006	Stepanian, Nicolas	Battalion Chief		E	
ID: C1842 Type: 60-Support apparatus, other	Dispatch: 03/16/2021 14:06 Arrival: 03/16/2021 14:06 Clear: 03/16/2021 17:43	Sent	0	Suppression EMS Other	Ц
Personalin	Nama	Pank	Pole	Attand	Actions Taken

reisonnetiu	Indition	-	Ronk	RULE	Accenio	ACCIONS FORCH
ID: D1802 Type: 92-Chief o	10	atch: 03/16/2021 13:11 val: 03/16/2021 13:11	Sent	0	Suppression EMS Other	
Type: 22 chief c	Clean					
Personnel ID	Name	e	Rank	Role	Attend	Actions Taken
ID: D1803 Type: 92-Chief c		atch: 03/16/2021 12:44	Sent	0	Suppression EMS Other	
	Clear	r: 03/16/2021 14:26				
Personnel ID	Name	e	Rank	Role	Attend	Actions Taken
ID: ED131 Type: 00-Other	Dispa apparatus/resource Arriv		Sent	8	Suppression EMS Other	
Personnel ID	Name		Rank	Role	Attend	Actions Taken
19425		ani, Geoffrey	Fire Investigation Supervisor			Ц
18343	Goye	ette, Matthew	Fire Captain			
19273	Lamb	bert, Darrell	Fire Captain		19	Ц
19228	Lang	evin, Steve	Fire Engineer			Ц
16923	Lewi	s, Ryan	Battalion Chief		ñ	Ц
19226	Ryan	, Jacob	Fire Captain			
18724	Verk	aik, Eugene	Fire Captain			
18466	Wed	ell, Michael	Battalion Chief			Ц
ID: HM133 Type: 93-HazMa	1	1 11 1	S ent	0	Suppression EMS Other	Ц
Personnel ID	Name	e	Rank	Role	Attend	Actions Taken
ID: [11850] Type: 60-Suppo	Disp rt apparatus, other		Sent	1	Suppression EMS Other	86-Investigate
Personnel ID	Name		Rank	Role	Attend	Actions Taken
18721		sterman, Daniel	Fire Investigation Supervisor	Note	recend	L Tuneff
ID: ME131 Type: 11-Engine	î .	val: 03/16/2021 12:30	Sent	4	Suppression EMS Other	

	Clear: 03/16/2021 15:09				
Personnel ID	Name	Rank	Role	Attend	Actions Taken
20025	Bandaruk, Jason	Firefighter		Ĺ.	
20192	Wilson, Duncan	Firefighter		ū	
19140	Hafner, Ryan	Fire Captain		U	
19344	Preston, Bryan	Fire Engineer		D'	Ц
ID: ME132 Type: 11-Engine	Dispatch: 03/16/2021 12:30 Arrival: 03/16/2021 12:34 Clear: 03/19/2021 15:43	Sent	4	Suppression EMS Other	
Personnel ID	Name	Rank	Role	Attend	Actions Taken
20183	Clements, Cody	Firefighter		G.	Ш
19687	Thompson, Matthew	Fire Engineer			Ц
19223	Gilbert, Ryan	Fire Captain		121	
20190	Saunders, Kurt	Firefighter		Ð	
ID: ME134 Type: 11-Engine	Dispatch: 03/16/2021 12:42 Arrival: 03/16/2021 12:47 Clear: 03/16/2021 14:43	Sent	4	Suppression EMS Other	
Personnel ID	Name	Rank	Role	Attend	Actions Taken
20205	Okamura, Thomas	Firefighter	-16		- 🗆
20201	Steele, Matthew	Firefighter		- Li	
19227	Willemse, Scott	Fire Captain		Q.	
19422	Cavanaugh, Sean	Fire Engineer		П	П
ID: ME135 Type: 11-Engine	Dispatch: 03/16/2021 12:42 Arrival: 03/16/2021 12:53 Clear: 03/16/2021 14:47	Sent	4	Suppression LEMS Other	Ц
Personnel ID	Name	Rank	Role	Attend	Actions Taken
19881	Ciszek, Brian			E	
20199	Hoover, Lucas	Firefighter		b	
17357	Bekins, Kurt	Fire Captain		0	Ц
19857	Zaragoza, Eric			5	Ц
ID: ME136 Type: 11-Engine	Dispatch: 03/16/2021 12:30 Arrival: 03/16/2021 12:42 Clear: 03/17/2021 21:11	☑ Sent	4	Suppression E EMS Other	11-Extinguishment by fire service per
Personnel ID	Name	Rank	Role	Attend	Actions Taken
					1.1

19798	Mowad, Trevor			Ш.,	Ц
20327	Magrina, Joel	- Firefighter		G	Ш
20185	Medina, Jacob	Firefighter			
16864	Spellman, Ronald	Fire Captain			
ID: ME137 Type: 11-Engine	Dispatch: 03/16/2021 13:09 Arrival: 03/16/2021 13:20 Clear: 03/16/2021 14:15	Sent	4	Suppression EMS Other	
Personnel ID	Name	Rank	Role	Attend	Actions Taken
20194	Esquivias, Jovanny	Firefighter		Ū	
19680	Garrett, Chad	Fire Engineer		II.	
17233	De Young, Daniel	Fire Captain		0	
20321	Armstrong, Joshua	Firefighter		Ū.	Ц
ID: ME138 Type: 11-Engine	Dispatch: 03/16/2021 13:08 Arrival: 03/16/2021 13:11 Clear: 03/16/2021 15:16	☑ Sent	4	Suppression EMS Other	
Personnel ID	Name	Rank	Role	Attend	Actions Taken
19807	Clarke, Christian			0	
16895	Nelson, Tye	Fire Captain		ă l	
20316	Hernandez, Michael	Firefighter		5	
20202	Powers, Brian	Firefighter		Ū.	
ID: ME139 Type: 11-Engine	Dispatch: 03/16/2021 12:42 Arrival: 03/16/2021 12:54 Clear: 03/16/2021 22:13	Sent	4	Suppression EMS	
Personnel ID	Name	Rank	Role	Attend	Actions Taken
20334	Verral, Eric	Firefighter		B	Ц
20184	Selk, Chase	Firefighter		E	
19686	Talley, Steven	Fire Engineer		b	
18902	Bethel, Richard	Fire Captain			
ID: ME141 Type: 11-Engine	Dispatch: 03/16/2021 22:31 Arrival:	Sent	0	Suppression EMS Other	Ц
Personnel ID	Name	Rank	Role	Attend	Actions Taken
ID: ME67 Type: 11-Engine	Dispatch: 03/16/2021 13:28 Arrival: 03/16/2021 13:28	Sent	0	Suppression EMS Other	Ц

	Clear. 03/10/2021 23.41				
Personnel ID	Name	Rank	Role	Attend	Actions Taken
ID: T131 Type: 12-Truck or aerial	Dispatch: 03/16/2021 12:30 Arrival: 03/16/2021 12:38 Clear: 03/16/2021 22:02	Ø Sent	4	Suppression EMS Other	
Personnel ID	Name	 Rank	Role	Attend	Actions Taken
20326	Jaquess, Tyler	Firefighter	Rote	Accesso	L
19228	Langevin, Steve	Fire Engineer		a	Ц
18724	Verkaik, Eugene	Fire Captain		Ð	Ц
20032	Gamboa, Neil	Firefighter		Ü.	Ц
ID: T138 Type: 12-Truck or aerial	Dispatch: 03/16/2021 12:42 Arrival:	Sent	4	Suppression EMS Other	Ц
Personnel ID	Name	Rank	Role	Attend	Actions Taken
19885	Morrison, Christopher				
20029	Harper, Martin	Firefighter			Ш
18980	Van Fossen, Brian	Fire Captain		þ	
19508	Bates, Logan	Fire Engineer			Ц
ID: T139 Type: 12-Truck or aerial	Dispatch: 03/16/2021 12:43 Arrival:	Sent Sent	4	Suppression EMS Other	Ц
Personnel ID	Name	Rank	Role	Attend	Actions Taken
19880	DeMartino, Noah				
20214	Norbryhn, Scott	Firefighter		B	Ш
19679	Charleston, David	Firefighter			
17102	Guapo, Louis	Fire Captain		Di .	Ш
ID: T1820 Type: 60-Support apparatus, other	Dispatch: 03/16/2021 12:37 Arrival: 03/16/2021 12:37 Clear: 03/18/2021 13:36	Sent	0	Suppression EMS Other	Ц
Personnel ID	Name	Rank	Role	Attend	Actions Taken
ID: T1822 Type: 60-Support apparatus, other	Dispatch: 03/16/2021 12:51 Arrival:	Ø Sent	0	Suppression EMS Other	
Personnel ID	Name	Rank	Role	Attend	Actions Taken

NFIRS-1S Supplemental

Α								
	36170	CA	03	16	2021	Station 2 (132)	OF2104486	6
	FDID	State	Month	Day	Year	Station	Number	Exposure

Primary Narrative:

B 1815 was dispatched as part of the first alarm assignment to a potential structure fire at the documented address. Prior to going enroute B 1815 acknowledged Ontario Dispatch traffic stating that there were multiple explosions at the location. Due to this I immediately started EOD 131 and HM 133.

B 1815 then went responding. While enroute I observed a large column of smoke in the area of the dispatched address. I broadcast this traffic and continued in code 3.

B 1815 AOS and observed fire to the front yard and rear of house. Structure observed was a single story single family residence with significant exposure concern to the delta side. B 1815 established Francis Command. Immediately upon establishing Francis Command, B 1815 requested that OPD shut down Francis St west of Fern and east of San Antonio. B 1815 also requested a 300' perimeter be established around 428 W. Francis St.

ME 132 AOS and Francis Command assigned him as Division A. Objectives were perimeter control and victim accountability. They were advised to engage in fire attack operations only if they felt safe in doing so.

ME 131 AOS and was assigned as a rescue group. There were report of victims on the "D" side of 428 W. Francis. This information was relayed to ME 131 and they set up for potential rescue operations.

T 1820 arrived onscene and he was assigned as division D with primary objectives of perimeter control and victim accountability. ME 136 was almost immediately assigned to help out division D.

T 131 AOS and due to unit specialty their crew was split. Captain Verkaik and Engineer Langevin were assigned to the EOD group and FF Jaquess and FF Gamboa were assigned underneath division A to assist with their operation.

ME 134 was assigned as my division B. Their objectives were to establish perimeter control and provide victim accountability.

ME 139 AOS and they were assigned as division D. Their objectives were to establish perimeter control and provide victim accountability.

During the course of assigning unit to their divisional assignments a large explosion occurred. This explosion resulted in an operational retreat of all divisions. A PAR was performed and all firefighters were accounted for. No injuries were noted due to the explosion.

Fire suppression activities resumed after the explosion with safety measures applied. Large diameter hoselines were used from a safe distance.

Fire was extinguished at the documented time. Operations then transitioned into a multi day investigation operation led by Ontario FD EOD and I 1850. Please reference their report for additional information in regards to their operations.

Multi families were displaced as a result of this incident. Red Cross was used as the primary for sheltering measures.

Ultimately on Saturday late afternoon the Francis Incident was terminated and all Ontario Fire Department operations were complete.

R. Williams Fire Battalion Chief Battalion 1-B

Person/Entity	Involved	Employee		South Coast Air Quality Management District	
Local Option		Person/Entity Type		Business Name (if applicable)	Phone Number
	Kamal			Brenner	
Mr., Ms., Mrs.	First Name		MI	Last Name	Suffix
Number	Prefix	Street or Highway		Street Type	Suffix
Post Office Box		Apt./	'Suite/Room	City	
State		Zip Code			

Additional Narrative (#1 of 1):

Exposure #6

The property of 415 west Maple St. was located in Division C. This property sustained a great deal of structural damage to the house from the explosion and blast pressure. The thermal effect from the explosion caused a secondary fire to start most likely by firebrands or fireworks along the south end of the property. The fence and structures were located in a horse corral that is adjacent to the northeast corner of the 428 west Francis property.

R. Gilbert ME 132-B